


PROBLEM SUMMARY


Laurel Steel 126-2B-M-FLYSHEAR

Hydraulic System

AW HYDRAULIC OIL ISO 46 (--- GAL)



COMPONENT CONDITION SUMMARY



RECOMMENDATION

Little or no information is provided as to the component and lubricant being tested. Recommendations are therefore generic in nature and may not apply to the current application. Please forward information as to equipment type, reservoir capacity, lubricant type and any pertinent information to allow for a more accurate assessment. Check seals and/or filters for points of contaminant entry. We advise that you check for visible metal particles in the oil. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. We recommend you service the filters on this component. Resample in 30-45 days to monitor this situation. NOTE: Please provide information regarding reservoir capacity, filter type and micron rating with next sample. Please specify the brand, type, and viscosity of the oil on your next sample.

Customer Id: FORHAM Sample No.: WC0835329 Lab Number: 02603467 Test Package: IND 2



To manage this report scan the QR code

To discuss the diagnosis or test data: Kevin Marson +1 (289)291-4644 x4644 Kevin.Marson@wearcheck.com

To change component or sample information: Gloria Gonzalez +1 (289)291-4643 x4643 gloria.gonzalez@wearcheck.com

PROBLEMATIC TEST RESULTS							
Sample Status				SEVERE			
Particles >4µm		ASTM D7647	>5000	133849			
Particles >6µm		ASTM D7647	>1300	38987			
Oil Cleanliness		ISO 4406 (c)	>19/17/14	2 4/22/13			
White Metal	scalar	Visual*	NONE	▲ VLITE			
PrtFilter					no image	no image	

RECOMMENDED ACTIONS						
Action	Status	Date	Done By	Description		
Change Filter			?	We recommend you service the filters on this component.		
Resample			?	Resample in 30-45 days to monitor this situation.		
Alert			?	Little or no information is provided as to the component and lubricant being tested. Recommendations are therefore generic in nature and may not apply to the current application. Please forward information as to equipment type, reservoir capacity, lubricant type and any pertinent information to allow for a more accurate assessment.		
Information Required			?	Please specify the brand, type, and viscosity of the oil on your next sample. NOTE: Please provide information regarding reservoir capacity, filter type and micron rating with next sample.		
Check Breathers			?	The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather.		
Check For Visual Metal			?	We advise that you check for visible metal particles in the oil.		
Check Seals			?	Check seals and/or filters for points of contaminant entry.		

HISTORICAL DIAGNOSIS




OIL ANALYSIS REPORT

Laurel Steel 126-2B-M-FLYSHEAR

Hydraulic System

AW HYDRAULIC OIL ISO 46 (--- GAL)





DIAGNOSIS

Recommendation

Little or no information is provided as to the component and lubricant being tested. Recommendations are therefore generic in nature and may not apply to the current application. Please forward information as to equipment type, reservoir capacity, lubricant type and any pertinent information to allow for a more accurate assessment. Check seals and/or filters for points of contaminant entry. We advise that you check for visible metal particles in the oil. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. We recommend you service the filters on this component. Resample in 30-45 days to monitor this situation. NOTE: Please provide information regarding reservoir capacity, filter type and micron rating with next sample. Please specify the brand, type, and viscosity of the oil on your next sample.

Light concentration of visible metal present.

Contamination

There is a high amount of silt (particulates < 14 microns in size) present in the oil.


Fluid Condition

The AN level is acceptable for this fluid. The oil is no longer serviceable as a result of the abnormal and/or severe wear.

SAMPLE INFORM	MATION	method	limit/base	current	history1
Sample Number		Client Info		WC0835329	
Sample Date		Client Info		07 Nov 2023	
Machine Age	hrs	Client Info		0	
Oil Age	hrs	Client Info		0	
Oil Changed		Client Info	N/A		
Sample Status				SEVERE	
CONTAMINATION	٧	method	limit/base	current	history1
Water		WC Method	>0.05	NEG	
WEAR METALS		method	limit/base	current	history1
Iron	ppm	ASTM D5185(m)	>20	8	
Chromium	ppm	ASTM D5185(m)	>20	<1	
Nickel	ppm	ASTM D5185(m)	>20	0	
Titanium	ppm	ASTM D5185(m)		0	
Silver	ppm	ASTM D5185(m)		<1	
Aluminum	ppm	ASTM D5185(m)	>20	0	
Lead	ppm	ASTM D5185(m)	>20	<1	
Copper	ppm	ASTM D5185(m)	>20	9	
Tin	ppm	ASTM D5185(m)	>20	0	
Antimony	ppm	ASTM D5185(m)		0	
Vanadium	ppm	ASTM D5185(m)		0	
Beryllium	ppm	ASTM D5185(m)		0	
Cadmium	ppm	ASTM D5185(m)		0	
4 D D I T I V I T O					


ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185(m)	5	<1		
Barium	ppm	ASTM D5185(m)	5	<1		
Molybdenum	ppm	ASTM D5185(m)	5	0		
Manganese	ppm	ASTM D5185(m)		0		
Magnesium	ppm	ASTM D5185(m)	25	0		
Calcium	ppm	ASTM D5185(m)	200	45		
Phosphorus	ppm	ASTM D5185(m)	300	347		
Zinc	ppm	ASTM D5185(m)	370	427		
Sulfur	ppm	ASTM D5185(m)	2500	808		
Lithium	ppm	ASTM D5185(m)		<1		
CONTAMINANTS	;	method	limit/base	current	history1	history2

Silicon Sodium Potassium	ppm ppm	ASTM D5185(m) ASTM D5185(m) ASTM D5185(m)	>15	<1 0 0		
FLUID CLEANLIN	IESS	method	limit/base	current	history1	history2
Particles >4µm		ASTM D7647	>5000	133849		
Particles >6µm		ASTM D7647	>1300	38987		
Particles >14µm		ASTM D7647	>160	73		
Particles >21µm		ASTM D7647	>40	4		
Particles >38µm		ASTM D7647	>10	1		
Particles >71μm		ASTM D7647	>3	0		
Oil Cleanliness		ISO 4406 (c)	>19/17/14	24/22/13		





OIL ANALYSIS REPORT





CALA ISO 17025:2017 Accredited Laboratory

Laboratory Sample No.

Lab Number

Unique Number

: WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9 : 02603467

: WC0835329 : 5696552

Recieved

: 15 Dec 2023 Diagnosed : 18 Dec 2023 Diagnostician : Kevin Marson FORSYTHE LUBRICATION

120 CHATHAM ST. HAMILTON, ON CA L8P 2B5

Test Package : IND 2 (Additional Tests: Bottom, BottomAnalysis, FilterPatch, PrtFilt@gntact: HEIDI LEINGARTNER

To discuss this sample report, contact Customer Service at 1-800-268-2131. Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab.

Validity of results and interpretation are based on the sample and information as supplied.

T: (905)525-7192 F: (905)525-7024