




PROBLEM SUMMARY


Sample Rating Trend



Machine Id
MX3903
 Component
Transmission (Auto)
 Fluid
DEXRON III (--- LTR)

COMPONENT CONDITION SUMMARY

Ferrous Alloys



RECOMMENDATION

We recommend that you drain the fluid from the component if this has not already been done. We recommend an early resample to monitor this condition. The fluid was not specified, however, a fluid match indicates that this fluid is (GENERIC) DEXRON III. Please confirm.

PROBLEMATIC TEST RESULTS

Sample Status			SEVERE	ABNORMAL	ABNORMAL
Iron	ppm	ASTM D5185(m)	>230	▲ 343	▲ 342
Chromium	ppm	ASTM D5185(m)	>2	▲ 4	▲ 3

Customer Id: HORBUR
 Sample No.: WC0811938
 Lab Number: 02606254
 Test Package: IND 2



To manage this report scan the QR code

To discuss the diagnosis or test data:
 Kevin Marson +1 (289)291-4644 x4644
Kevin.Marson@wearcheck.com

To change component or sample information:
 Gloria Gonzalez +1 (289)291-4643 x4643
gloria.gonzalez@wearcheck.com

RECOMMENDED ACTIONS

Action	Status	Date	Done By	Description
Change Fluid	---	---	?	We recommend that you drain the fluid from the component if this has not already been done.
Resample	---	---	?	We recommend an early resample to monitor this condition.
Alert	---	---	?	The fluid was not specified, however, a fluid match indicates that this fluid is (GENERIC) DEXRON III. Please confirm.
Information Required	---	---	?	The fluid was not specified, however, a fluid match indicates that this fluid is (GENERIC) DEXRON III. Please confirm.

HISTORICAL DIAGNOSIS

21 Oct 2022 Diag: Kevin Marson

WEAR



We recommend that you drain the fluid from the component if this has not already been done. We recommend an early resample to monitor this condition. Please specify the brand, type, and viscosity of the oil on your next sample. Chromium and iron ppm levels are abnormal. The low ferrous density (PQ) index indicates the wear metal levels are due to corrosion. There is no indication of any contamination in the fluid. The AN level is acceptable for this fluid. The fluid is no longer serviceable as a result of the abnormal and/or severe wear.

view report



23 Aug 2022 Diag: Kevin Marson

WEAR



We recommend that you drain the fluid from the component if this has not already been done. We recommend an early resample to monitor this condition. The fluid was not specified, however, a fluid match indicates that this fluid is (GENERIC) TES SYN 295. Please confirm. Chromium and iron ppm levels are abnormal. The low ferrous density (PQ) index indicates the wear metal levels are due to corrosion. There is no indication of any contamination in the fluid. The AN level is acceptable for this fluid. The fluid is no longer serviceable as a result of the abnormal and/or severe wear.

view report



05 Apr 2022 Diag: Kevin Marson

WEAR



We recommend that you drain the fluid from the component if this has not already been done. We recommend an early resample to monitor this condition. The fluid was not specified, however, a fluid match indicates that this fluid is (GENERIC) ATF (PAO). Please confirm. NOTE: Please provide information regarding reservoir capacity, filter type and micron rating with next sample. Iron ppm levels are severe. Chromium ppm levels are abnormal. The low ferrous density (PQ) index indicates the wear metal levels are due to corrosion. There is no indication of any contamination in the fluid. The AN level is acceptable for this fluid. The fluid is no longer serviceable as a result of the abnormal and/or severe wear.


view report





OIL ANALYSIS REPORT

Sample Rating Trend



WEAR



Machine Id
MX3903
 Component
Transmission (Auto)
 Fluid
DEXRON III (--- LTR)

DIAGNOSIS

Recommendation

We recommend that you drain the fluid from the component if this has not already been done. We recommend an early resample to monitor this condition. The fluid was not specified, however, a fluid match indicates that this fluid is (GENERIC) DEXRON III. Please confirm.

Wear

Iron ppm levels are severe. Chromium ppm levels are abnormal. The low ferrous density (PQ) index indicates the wear metal levels are due to corrosion.

Contamination

There is no indication of any contamination in the fluid.

Fluid Condition

The AN level is acceptable for this fluid. The fluid is no longer serviceable as a result of the abnormal and/or severe wear.

SAMPLE INFORMATION

	method	limit/base	current	history1	history2
Sample Number	Client Info		WC0811938	WC0413042	WC0689706
Sample Date	Client Info		18 Oct 2023	21 Oct 2022	23 Aug 2022
Machine Age	hrs	Client Info	0	0	0
Oil Age	hrs	Client Info	0	0	0
Oil Changed	Client Info		N/A	N/A	N/A
Sample Status			SEVERE	ABNORMAL	ABNORMAL

CONTAMINATION

	method	limit/base	current	history1	history2
Water	WC Method	>0.1	NEG	NEG	NEG

WEAR METALS

	method	limit/base	current	history1	history2
PQ	ASTM D8184*	>105	0	0	0
Iron	ppm	ASTM D5185(m) >230	398	343	342
Chromium	ppm	ASTM D5185(m) >2	4	3	3
Nickel	ppm	ASTM D5185(m) >5	<1	<1	<1
Titanium	ppm	ASTM D5185(m) >2	0	0	0
Silver	ppm	ASTM D5185(m) >5	0	0	0
Aluminum	ppm	ASTM D5185(m) >65	2	2	1
Lead	ppm	ASTM D5185(m) >55	3	3	3
Copper	ppm	ASTM D5185(m) >85	60	50	47
Tin	ppm	ASTM D5185(m) >5	<1	<1	<1
Antimony	ppm	ASTM D5185(m)	0	<1	<1
Vanadium	ppm	ASTM D5185(m)	0	0	0
Beryllium	ppm	ASTM D5185(m)	0	0	0
Cadmium	ppm	ASTM D5185(m)	0	0	0

ADDITIVES

	method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185(m)	71	69	71
Barium	ppm	ASTM D5185(m)	0	0	0
Molybdenum	ppm	ASTM D5185(m)	<1	<1	<1
Manganese	ppm	ASTM D5185(m)	4	4	4
Magnesium	ppm	ASTM D5185(m)	2	3	2
Calcium	ppm	ASTM D5185(m)	58	59	57
Phosphorus	ppm	ASTM D5185(m)	181	195	175
Zinc	ppm	ASTM D5185(m)	14	14	12
Sulfur	ppm	ASTM D5185(m)	752	720	734
Lithium	ppm	ASTM D5185(m)	<1	<1	<1


CONTAMINANTS

	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185(m) >20	3	3	3
Sodium	ppm	ASTM D5185(m)	5	6	5
Potassium	ppm	ASTM D5185(m) >20	<1	<1	0




OIL ANALYSIS REPORT


Ferrous Alloys




Acid Number



Viscosity @ 40°C



PQ




FLUID CLEANLINESS	method	limit/base	current	history1	history2
Particles >4µm	ASTM D7647	>10000	76449	136779	---
Particles >6µm	ASTM D7647	>2500	5422	8079	---
Particles >14µm	ASTM D7647	>320	53	154	---
Particles >21µm	ASTM D7647	>80	11	29	---
Particles >38µm	ASTM D7647	>20	2	0	---
Particles >71µm	ASTM D7647	>4	1	0	---
Oil Cleanliness	ISO 4406 (c)	>20/18/15	23/20/13	24/20/14	---

FLUID DEGRADATION	method	limit/base	current	history1	history2
Acid Number (AN)	mg KOH/g	ASTM D974*	0.62	0.50	0.46

VISUAL	method	limit/base	current	history1	history2
White Metal	scalar	Visual*	NONE	NONE	VLITE
Yellow Metal	scalar	Visual*	NONE	NONE	NONE
Precipitate	scalar	Visual*	NONE	NONE	NONE
Silt	scalar	Visual*	NONE	NONE	NONE
Debris	scalar	Visual*	NONE	NONE	VLITE
Sand/Dirt	scalar	Visual*	NONE	NONE	NONE
Appearance	scalar	Visual*	NORML	NORML	NORML
Odor	scalar	Visual*	NORML	NORML	NORML
Emulsified Water	scalar	Visual*	>0.1	NEG	NEG
Free Water	scalar	Visual*		NEG	NEG

FLUID PROPERTIES	method	limit/base	current	history1	history2	
Visc @ 40°C	cSt	ASTM D7279(m)	26.0	27.6	28.3	28.4

SAMPLE IMAGES



Laboratory : WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9
Sample No. : WC0811938 **Recieved** : 03 Jan 2024
Lab Number : **02606254** **Diagnosed** : 05 Jan 2024
Unique Number : 5707340 **Diagnostician** : Kevin Marson
Test Package : IND 2 (Additional Tests: PQ, PrtCount, TAN Man)

To discuss this sample report, contact Customer Service at 1-800-268-2131.
 Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab.
 Validity of results and interpretation are based on the sample and information as supplied.

Dawn Foods
 4370 Harvester Road
 Burlington, ON
 CA L7L 4X2
 Contact: Bosko Cenic
 bosko.cenic@dawnfoods.com
 T: (905)681-5104
 F: (905)681-2755