

# **OIL ANALYSIS REPORT**







# **DIAGNOSIS**

#### Recommendation

We advise that you check for the source of water entry. The oil change at the time of sampling has been noted. We recommend an early resample to monitor this condition.

#### Wear

All component wear rates are normal.

### Contamination

There is a moderate concentration of water present in the oil.

### **Fluid Condition**


The oil is no longer serviceable due to the presence of contaminants.

(ON 80W90 (	GAL)			Dec2023		
SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		WC0888484		
Sample Date		Client Info		21 Dec 2023		
Machine Age	hrs	Client Info		0		
Oil Age	hrs	Client Info		0		
Oil Changed		Client Info		Changed		
Sample Status				ABNORMAL		
WEAR METALS		method	limit/base	current	history1	history2
ron	ppm	ASTM D5185(m)	>1200	116		
Chromium	ppm	ASTM D5185(m)	>10	1		
Nickel	ppm	ASTM D5185(m)	>10	<1		
Titanium	ppm	ASTM D5185(m)		<1		
Silver	ppm	ASTM D5185(m)		0		
Aluminum	ppm	ASTM D5185(m)	>25	2		
_ead	ppm	ASTM D5185(m)	>50	1		
Copper	ppm	ASTM D5185(m)	>50	7		
Γin	ppm	ASTM D5185(m)	>10	0		
Antimony	ppm	ASTM D5185(m)	>5	0		
/anadium	ppm	ASTM D5185(m)		0		
Beryllium	ppm	ASTM D5185(m)		0		
Cadmium	ppm	ASTM D5185(m)		0		
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185(m)	243	180		
Barium	ppm	ASTM D5185(m)	1	0		
Molybdenum	ppm	ASTM D5185(m)		0		
Manganese	ppm	ASTM D5185(m)		<1		
Magnesium	ppm	ASTM D5185(m)	2	9		
Calcium	ppm	ASTM D5185(m)	6	223		
Phosphorus	ppm	ASTM D5185(m)	987	969		
Zinc	ppm	ASTM D5185(m)	1	94		
Sulfur	ppm	ASTM D5185(m)	21530	18422		
_ithium	ppm	ASTM D5185(m)		<1		
CONTAMINANTS	}	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185(m)	>100	12		
Sodium	ppm	ASTM D5185(m)		3		
Potassium	ppm	ASTM D5185(m)	>20	2		
Water	%	ASTM D6304*	>0.25	<b>△</b> 0.573		
opm Water	ppm	ASTM D6304*	>2500	<u>▲</u> 5734		

Sample Rating Trend



## OIL ANALYSIS REPORT







**Unique Number** 

Laboratory Sample No. Lab Number

: WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9 RONI/IRON SHORE EXCAVATING LTD. : 02607206

: WC0888484

Recieved Diagnosed : 5708292

: 10 Jan 2024 Diagnostician : Kevin Marson Test Package : MOBCE ( Additional Tests: KF, Visual )

: 08 Jan 2024

CA L4K 4P3 Contact: Service Team service.team@roni.ca T:

100 MACINTOSH BLVD

VAUGHAN, ON

To discuss this sample report, contact Customer Service at 1-800-268-2131. Test denoted (\*) outside scope of accreditation, (m) method modified, (e) tested at external lab.

F: Validity of results and interpretation are based on the sample and information as supplied.