




PROBLEM SUMMARY

Area
ENGINE ROOM FLOOR
 Machine Id
21-A-6462 STARBOARD MAIN ENGINE LUBE OIL (S/N Maint Plan 22467)
 Component
Starboard Main Engine
 Fluid
MOBIL MOBILGARD 412 (22300 LTR)

Sample Rating Trend




WEAR PARTICLES



COMPONENT CONDITION SUMMARY

▲ Fuel Dilution



RECOMMENDATION

We recommend that you change the oil at the next available stoppage or outage. Re-sampling is suggested to confirm test results prior to significant maintenance activities being performed. Please indicate that this is a resample on your Sample Information Form (SIF). We recommend an early resample to monitor this condition.

PROBLEMATIC TEST RESULTS

Sample Status	Scale 0-10	ASTM D7684*	SEVERE	ABNORMAL	ABNORMAL
Ferrous Cutting			1	1	
Fuel	%	ASTM D7593* >4.0	5.1	6	6.3

Customer Id: SPESTJ
 Sample No.: PP
 Lab Number: 02607418
 Test Package: MAR 3



To manage this report scan the QR code

To discuss the diagnosis or test data:
 Kevin Marson +1 (289)291-4644 x4644
Kevin.Marson@wearcheck.com

To change component or sample information:
 Gloria Gonzalez +1 (289)291-4643 x4643
gloria.gonzalez@wearcheck.com

RECOMMENDED ACTIONS

Action	Status	Date	Done By	Description
Change Fluid	---	---	?	We recommend that you change the oil at the next available stoppage or outage.
Resample	---	---	?	We recommend an early resample to monitor this condition. Re-sampling is suggested to confirm test results prior to significant maintenance activities being performed. Please indicate that this is a resample on your Sample Information Form (SIF).

HISTORICAL DIAGNOSIS

17 Oct 2023 Diag: Kevin Marson

WEAR PARTICLES



Due to this condition we recommend the following action... We advise an early resample to confirm this situation. Wear particle analysis indicates that the ferrous cutting particles are abnormal. Cutting wear particles are caused by either hard protuberances (mis-aligned components, etc.), or abrasives entering the system and embedding themselves in softer materials (sand, etc.), and gouging out mating surfaces. There is a moderate amount of fuel present in the oil. Tests confirm the presence of fuel in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. Viscosity of sample indicates oil is within SAE 30 range, advise investigate. The oil is no longer serviceable as a result of the abnormal and/or severe wear.

view report



26 Aug 2023 Diag: Bill Quesnel

FUEL



We recommend that you change the oil at the next available stoppage or outage. We recommend an early resample to monitor this condition. All component wear rates are normal. The direct-reading & analytical ferrographic results are normal indicating no abnormal wear in the system. There is a moderate amount of fuel present in the oil. Tests confirm the presence of fuel in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. Viscosity of sample indicates oil is within SAE 30 range, advise investigate. The oil is no longer serviceable due to the presence of contaminants.

view report



22 Jun 2023 Diag: Kevin Marson

FUEL



We recommend that you change the oil at the next available stoppage or outage. We recommend an early resample to monitor this condition. All component wear rates are normal. The direct-reading & analytical ferrographic results are normal indicating no abnormal wear in the system. There is a moderate amount of fuel present in the oil. Tests confirm the presence of fuel in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. Fuel is present in the oil and is lowering the viscosity. The oil is no longer serviceable due to the presence of contaminants.


view report





OIL ANALYSIS REPORT

Sample Rating Trend



WEAR PARTICLES



Area
ENGINE ROOM FLOOR
 Machine Id
21-A-6462 STARBOARD MAIN ENGINE LUBE OIL (S/N Maint Plan 22467)
 Component
Starboard Main Engine
 Fluid
MOBIL MOBILGARD 412 (22300 LTR)

DIAGNOSIS

Recommendation

We recommend that you change the oil at the next available stoppage or outage. Re-sampling is suggested to confirm test results prior to significant maintenance activities being performed. Please indicate that this is a resample on your Sample Information Form (SIF). We recommend an early resample to monitor this condition.

Wear

Wear particle analysis indicates that the ferrous cutting particles are severe. Cutting wear particles are caused by either hard protuberances (mis-aligned components, etc.), or abrasives entering the system and embedding themselves in softer materials (sand, etc.), and gouging out mating surfaces.

Contaminants

There is a moderate amount of fuel present in the oil. Tests confirm the presence of fuel in the oil.

Oil Condition

The BN result indicates that there is suitable alkalinity remaining in the oil. The oil is no longer serviceable as a result of the abnormal and/or severe wear.

SAMPLE INFORMATION

method	limit/base	current	history1	history2
Sample Number	Client Info	PP	PP	PP
Sample Date	Client Info	27 Nov 2023	17 Oct 2023	26 Aug 2023
Machine Age	hrs	Client Info	0	0
Oil Age	hrs	Client Info	0	0
Oil Changed	Client Info	N/A	N/A	N/A
Sample Status		SEVERE	ABNORMAL	ABNORMAL

CONTAMINATION

method	limit/base	current	history1	history2
Water	WC Method >0.1	NEG	NEG	NEG
Glycol	WC Method	NEG	NEG	NEG

WEAR METALS

method	limit/base	current	history1	history2
PQ	ASTM D8184*	0	0	0
Iron	ppm ASTM D5185(m) >25	4	4	4
Chromium	ppm ASTM D5185(m) >5	0	0	<1
Nickel	ppm ASTM D5185(m) >5	<1	<1	0
Titanium	ppm ASTM D5185(m) >3	0	0	0
Silver	ppm ASTM D5185(m) >2	0	<1	0
Aluminum	ppm ASTM D5185(m) >10	1	<1	1
Lead	ppm ASTM D5185(m) >5	<1	0	<1
Copper	ppm ASTM D5185(m) >5	2	2	2
Tin	ppm ASTM D5185(m) >5	<1	<1	<1
Antimony	ppm ASTM D5185(m)	0	0	0
Vanadium	ppm ASTM D5185(m)	0	0	0
Beryllium	ppm ASTM D5185(m)	0	0	0
Cadmium	ppm ASTM D5185(m)	0	0	0

ADDITIVES

method	limit/base	current	history1	history2
Boron	ppm ASTM D5185(m) 0	4	3	3
Barium	ppm ASTM D5185(m) 0	0	<1	0
Molybdenum	ppm ASTM D5185(m) 0	0	0	<1
Manganese	ppm ASTM D5185(m) 0	0	0	<1
Magnesium	ppm ASTM D5185(m) 18	16	14	15
Calcium	ppm ASTM D5185(m) 6350	4818	4814	4575
Phosphorus	ppm ASTM D5185(m) 200	201	193	211
Zinc	ppm ASTM D5185(m) 380	328	325	331
Sulfur	ppm ASTM D5185(m) 6950	5013	4661	4799
Lithium	ppm ASTM D5185(m)	<1	<1	<1

CONTAMINANTS





method	limit/base	current	history1	history2
Silicon	ppm ASTM D5185(m) >20	11	8	11
Sodium	ppm ASTM D5185(m) >75	14	11	13
Potassium	ppm ASTM D5185(m) >20	<1	0	1
Fuel	% ASTM D7593* >4.0	5.1	6	6.3

INFRA-RED

method	limit/base	current	history1	history2
Soot %	% ASTM D7844* >2	0.1	0	0
Nitration	Abs/cm ASTM D7624* >20	7.8	8.0	8.1
Sulfation	Abs./1mm ASTM D7415* >30	17.4	16.9	16.6



OIL ANALYSIS REPORT








FLUID DEGRADATION		method	limit/base	current	history1	history2
Oxidation	Abs.:1mm	ASTM D7414*	>25	6.3	6.4	6.5
Base Number (BN)	mg KOH/g	ASTM D2896*	15	11.80	10.54	10.41

VISUAL		method	limit/base	current	history1	history2
Emulsified Water	scalar	Visual*	>0.1	NEG	NEG	NEG
Free Water	scalar	Visual*		NEG	NEG	NEG

FLUID PROPERTIES		method	limit/base	current	history1	history2
Visc @ 100°C	cSt	ASTM D7279(m)	14.5	12.4	▲ 12.0	▲ 11.8

GRAPHS




Laboratory : WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9 **HUSKY SEA ROSE /AKER SOLUTIONS**
Sample No. : PP **Received** : 09 Jan 2024 PO BOX 20
Lab Number : **02607418** **Diagnosed** : 16 Jan 2024 ST. JOHN'S, NL
Unique Number : 5708504 **Diagnostician** : Kevin Marson CA A1C 6C9
Test Package : MAR 3 (Additional Tests: PercentFuel) Contact: Maintenance Supervisor
maintsuper.searose@huskyenergy.ca
 To discuss this sample report, contact Customer Service at 1-800-268-2131. T: x:
 Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab. F: x:
 Validity of results and interpretation are based on the sample and information as supplied.



FERROGRAPHY REPORT

Area
ENGINE ROOM FLOOR
 Machine Id
21-A-6462 STARBOARD MAIN ENGINE LUBE OIL (S/N Maint Plan 22467)
 Component
Starboard Main Engine
 Fluid
MOBIL MOBILGARD 412 (22300 LTR)


Magn: 200x Illum: BC



Magn: 50x Illum: RW



Magn: 100x Illum: RW




DR-FERROGRAPHY		method	limit/base	current	history1	history2
Large Particles		DR-Ferr*		34.9	18.7	14.1
Small Particles		DR-Ferr*		12.2	10.7	7.9
Total Particles		DR-Ferr*	>---	47.1	29.4	22
Large Particles Percentage	%	DR-Ferr*		48.2	27.2	28.2
Severity Index		DR-Ferr*		792	150	87

FERROGRAPHY		method	limit/base	current	history1	history2
Ferrous Rubbing	Scale 0-10	ASTM D7684*		4	3	2
Ferrous Sliding	Scale 0-10	ASTM D7684*				
Ferrous Cutting	Scale 0-10	ASTM D7684*		1	1	
Ferrous Rolling	Scale 0-10	ASTM D7684*		2	1	1
Ferrous Break-in	Scale 0-10	ASTM D7684*				
Ferrous Spheres	Scale 0-10	ASTM D7684*				
Ferrous Black Oxides	Scale 0-10	ASTM D7684*			1	1
Ferrous Red Oxides	Scale 0-10	ASTM D7684*				
Ferrous Corrosive	Scale 0-10	ASTM D7684*				
Ferrous Other	Scale 0-10	ASTM D7684*				
Nonferrous Rubbing	Scale 0-10	ASTM D7684*				
Nonferrous Sliding	Scale 0-10	ASTM D7684*				
Nonferrous Cutting	Scale 0-10	ASTM D7684*				
Nonferrous Rolling	Scale 0-10	ASTM D7684*				
Nonferrous Other	Scale 0-10	ASTM D7684*				
Carbonaceous Material	Scale 0-10	ASTM D7684*				2
Lubricant Degradation	Scale 0-10	ASTM D7684*				
Sand/Dirt	Scale 0-10	ASTM D7684*		1	1	1
Fibres	Scale 0-10	ASTM D7684*				
Spheres	Scale 0-10	ASTM D7684*				
Other	Scale 0-10	ASTM D7684*		1	1	

WEAR

Wear particle analysis indicates that the ferrous cutting particles are severe. Cutting wear particles are caused by either hard protuberances (mis-aligned components, etc.), or abrasives entering the system and embedding themselves in softer materials (sand, etc.), and gouging out mating surfaces.

DR Ferrography



This page left intentionally blank