

PROBLEM SUMMARY

Sample Rating Trend




RBK G2 UGBR/THBR

Component Bearing

MOBIL DTE OIL HVY MEDIUM (55 GAL)

COMPONENT CONDITION SUMMARY



RECOMMENDATION

We advise that you check all areas where contaminants can enter the system. We advise that you check for visible metal particles in the oil. We advise that you perform a filter service, and use offline filtration to improve the cleanliness of the system fluid. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. Resample in 30-45 days to monitor this situation.

PROBLEMATIC T	EST RE	SULTS				
Sample Status				SEVERE	ABNORMAL	SEVERE
Particles >4µm		ASTM D7647	>10000	107703	<u>▲</u> 61955	107510
Particles >6µm		ASTM D7647	>2500	25498	△ 13089	25326
Particles >14µm		ASTM D7647	>160	<u> </u>	<u>▲</u> 521	△ 937
Particles >21µm		ASTM D7647	>40	267	<u> </u>	<u>^</u> 201
Oil Cleanliness		ISO 4406 (c)	>20/18/14	24/22/17	<u>\$\Delta\$ 23/21/16</u>	2 4/22/17
White Metal	scalar	Visual*	NONE	▲ LIGHT	NONE	NONE
PrtFilter					no image	no image

Customer Id: NEWSTJ Sample No.: WC0706214 Lab Number: 02607537 Test Package: IND 2



To manage this report scan the QR code

To discuss the diagnosis or test data: Kevin Marson +1 (289)291-4644 x4644 Kevin.Marson@wearcheck.com

To change component or sample information: Gloria Gonzalez +1 (289)291-4643 x4643 gloria.gonzalez@wearcheck.com

RECOMMENDED ACTIONS							
Action	Status	Date	Done By	Description			
Change Filter			?	We advise that you perform a filter service, and use off-line filtration to improve the cleanliness of the system fluid.			
Resample			?	Resample in 30-45 days to monitor this situation.			
Check Breathers			?	The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather.			
Check Dirt Access			?	We advise that you check all areas where contaminants can enter the system.			
Check For Visual Metal			?	We advise that you check for visible metal particles in the oil.			
Filter Fluid			?	We advise that you perform a filter service, and use off-line filtration to improve the cleanliness of the system fluid.			

HISTORICAL DIAGNOSIS

26 Apr 2023 Diag: Bill Quesnel

 \wedge

We advise that you perform a filter service, and use off-line filtration to improve the cleanliness of the system fluid. We recommend an early resample to monitor this condition. All component wear rates are normal. There is a moderate amount of particulates (2 to 100 microns in size) present in the oil. The AN level is acceptable for this fluid. The oil is still serviceable provided that the contaminant(s) can be reduced to acceptable levels.



03 Mar 2022 Diag: Kevin Marson





We advise that you check all areas where contaminants can enter the system. We advise that you perform a filter service, and use off-line filtration to improve the cleanliness of the system fluid. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. Resample in 30-45 days to monitor this situation. An increase in the iron level is noted. All other component wear rates are normal. Particles $>6\mu m$ are severely high. Particles $>4\mu m$ are severely high. Particles $>14\mu m$ are abnormally high. Particles $>21\mu m$ are abnormally high. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.



15 Feb 2021 Diag: Kevin Marson

ISO



We recommend you service the filters on this component. We recommend an early resample to monitor this condition. All component wear rates are normal. Particles $>4\mu m$ are abnormally high. Particles $>6\mu m$ are notably high. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.






OIL ANALYSIS REPORT

CONTAMINATION

Sample Rating Trend





RBK G2 UGBR/THBR

Component

Bearing

MOBIL DTE OIL HVY MEDIUM (55 GAL)

DIAGNOSIS

Recommendation

We advise that you check all areas where contaminants can enter the system. We advise that you check for visible metal particles in the oil. We advise that you perform a filter service, and use offline filtration to improve the cleanliness of the system fluid. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. Resample in 30-45 days to monitor this situation.

Wear

Light concentration of visible metal present.

Contamination

There is a high amount of particulates (2 to 100 microns in size) present in the oil.

Fluid Condition

The AN level is acceptable for this fluid. The oil is still serviceable provided that the contaminant(s) can be reduced to acceptable levels.


SAMPLE INFORM	IATION	method	limit/base	current	history1	history2
Sample Number		Client Info		WC0706214	WC0455644	WC0445229
Sample Date		Client Info		05 Jan 2024	26 Apr 2023	03 Mar 2022
Machine Age	mths	Client Info		24	24	0
Oil Age	mths	Client Info		24	24	0
Oil Changed		Client Info		N/A	N/A	N/A
Sample Status				SEVERE	ABNORMAL	SEVERE

Water		WC Method	>2	NEG	NEG	NEG
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185(m)	>63	12	10	11
Chromium	ppm	ASTM D5185(m)	>20	0	0	0
Nickel	ppm	ASTM D5185(m)	>20	0	0	<1
Titanium	ppm	ASTM D5185(m)		0	0	0
Silver	ppm	ASTM D5185(m)		0	0	0
Aluminum	ppm	ASTM D5185(m)	>2	<1	<1	<1
Lead	ppm	ASTM D5185(m)	>161	5	4	2
Copper	ppm	ASTM D5185(m)	>13	1	<1	<1
Tin	ppm	ASTM D5185(m)	>27	0	0	0
Antimony	ppm	ASTM D5185(m)		0	<1	<1
Vanadium	ppm	ASTM D5185(m)		0	0	0
Beryllium	ppm	ASTM D5185(m)		0	0	0
Cadmium	ppm	ASTM D5185(m)		0	0	0
ADDITIVEC						

ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185(m)		0	<1	<1
Barium	ppm	ASTM D5185(m)		0	0	0
Molybdenum	ppm	ASTM D5185(m)		0	0	0
Manganese	ppm	ASTM D5185(m)		0	<1	0
Magnesium	ppm	ASTM D5185(m)		<1	<1	0
Calcium	ppm	ASTM D5185(m)		<1	0	1
Phosphorus	ppm	ASTM D5185(m)		126	137	134
Zinc	ppm	ASTM D5185(m)		69	70	76
Sulfur	ppm	ASTM D5185(m)		855	843	791
Lithium	ppm	ASTM D5185(m)		<1	<1	<1
CONTANINANIT	_		12 24 //		11.1	1::

CONTAMINANT	S	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185(m)	>12	<1	<1	<1
Sodium	ppm	ASTM D5185(m)		0	0	<1
Potassium	ppm	ASTM D5185(m)	>20	<1	0	<1
FLUID CLEANLI	NESS	method	limit/base	current	history1	history2

Potassium	ppm	ASTIVI DOTOO(III)	>20	<1	U	<1
FLUID CLEANLIN	IESS	method	limit/base	current	history1	history2
Particles >4µm		ASTM D7647	>10000	107703	<u></u> 61955	107510
Particles >6µm		ASTM D7647	>2500	25498	△ 13089	25326
Particles >14µm		ASTM D7647	>160	1243	<u></u> ▲ 521	4 937
Particles >21µm		ASTM D7647	>40	<u>^</u> 267	4 99	<u>^</u> 201
Particles >38µm		ASTM D7647	>10	12	3	7
Particles >71µm		ASTM D7647	>3	0	1	0
Oil Cleanliness		ISO 4406 (c)	>20/18/14	24/22/17	23/21/16	2 4/22/17




Report Id: NEWSTJ [WCAMIS] 02607537 (Generated: 01/12/2024 15:45:06) Rev: 1

Submitted By: Melissa Snow



OIL ANALYSIS REPORT





CALA ISO 17025:2017 Accredited

Laboratory

Laboratory Sample No. Lab Number Unique Number

: WC0706214 : 02607537 : 5708623

: WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9 Recieved

: 09 Jan 2024 Diagnosed : 12 Jan 2024 Diagnostician : Kevin Marson

NEWFOUNDLAND POWER INC. 50 DUFFY PLACE, PO BOX 8910 ST. JOHNS, NL

CA A1B 3P6

Test Package : IND 2 (Additional Tests: BottomAnalysis, FILTERPATCH, PrtFilter, TAN Man) To discuss this sample report, contact Customer Service at 1-800-268-2131.

Contact: Paul Martin pmartin@newfoundlandpower.com

F: (709)737-2926

Submitted By: Melissa Snow

Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab. Validity of results and interpretation are based on the sample and information as supplied.

T: