

PROBLEM SUMMARY

PUMPHOUSE/CASTER SPRAY WATER PUMPS C - Caster Spray Water Electric Pump OB


Lube System

PETRO CANADA HYDREX AW 100 (1 GAL)





COMPONENT CONDITION SUMMARY



RECOMMENDATION

We advise that you check all areas where contaminants can enter the system. We advise that you check for visible metal particles in the oil. We advise that you perform a filter service, and use offline filtration to improve the cleanliness of the system fluid. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. Resample in 30-45 days to monitor this situation.

PROBLEMATIC TEST RESULTS								
Sample Status				SEVERE	ABNORMAL	SEVERE		
Particles >4µm		ASTM D7647	>5000	122281	<u>▲</u> 16442	226848		
Particles >6µm		ASTM D7647	>1300	56171	<u>^</u> 2661	1 07771		
Particles >14µm		ASTM D7647	>160	2896	174	4779		
Particles >21µm		ASTM D7647	>40	464	48	697		
Oil Cleanliness		ISO 4406 (c)	>19/17/14	2 4/23/19	<u>^</u> 21/19/15	25/24/19		
White Metal	scalar	Visual*	NONE	▲ VLITE	NONE	NONE		
PrtFilter					no image	no image		

Customer Id: LEWBOSC **Sample No.:** WC0898665 Lab Number: 02608066 Test Package: IND 2



To manage this report scan the QR code

To discuss the diagnosis or test data: Kevin Marson +1 (289)291-4644 x4644 Kevin.Marson@wearcheck.com

To change component or sample information: Gloria Gonzalez +1 (289)291-4643 x4643 gloria.gonzalez@wearcheck.com

RECOMMENDED ACTIONS								
Action	Status	Date	Done By	Description				
Change Filter			?	We advise that you perform a filter service, and use off-line filtration to improve the cleanliness of the system fluid.				
Resample			?	Resample in 30-45 days to monitor this situation.				
Check Breathers			?	The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather.				
Check Dirt Access			?	We advise that you check all areas where contaminants can enter the system.				
Check For Visual Metal			?	We advise that you check for visible metal particles in the oil.				
Filter Fluid			?	We advise that you perform a filter service, and use off-line filtration to improve the cleanliness of the system fluid.				

HISTORICAL DIAGNOSIS

16 Aug 2023 Diag: Kevin Marson

WEAR



We recommend that you drain the oil from the component if this has not already been done. We recommend you service the filters on this component. We recommend an early resample to monitor this condition. Iron ppm levels are abnormal. A sharp increase in the iron level is noted. The low ferrous density (PQ) index indicates the wear metal levels are due to corrosion. There is a moderate amount of silt (particulates < 14 microns in size) present in the oil. The system cleanliness is above the acceptable limit for the target ISO 4406 cleanliness code. The AN level is acceptable for this fluid. The oil is no longer serviceable as a result of the abnormal and/or severe wear.



ISO



31 May 2023 Diag: Bill Quesnel

We advise that you check all areas where contaminants can enter the system. We advise that you perform a filter service, and use off-line filtration to improve the cleanliness of the system fluid. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. Resample in 30-45 days to monitor this situation. All component wear rates are normal. There is a high amount of particulates (2 to 100 microns in size) present in the oil. There is a moderate concentration of dirt present in the oil. The system cleanliness code is much higher than the acceptable limit for the target ISO 4406 cleanliness code. The AN level is acceptable for this fluid. The oil is still serviceable provided that the contaminant(s) can be reduced to acceptable levels.





27 Jan 2023 Diag: Kevin Marson

We advise that you check all areas where contaminants can enter the system. We advise that you perform a filter service, and use off-line filtration to improve the cleanliness of the system fluid. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. Resample in 30-45 days to monitor this situation.All component wear rates are normal. Particles >14µm are severely high. Particles >21µm are severely high. Particles >6µm are severely high. Oil Cleanliness are severely high. Particles >4µm are severely high. Particles >38µm are notably high. The system cleanliness code is much higher than the acceptable limit for the target ISO 4406 cleanliness code. The AN level is acceptable for this fluid. The oil is still serviceable provided that the contaminant(s) can be reduced to acceptable levels.






OIL ANALYSIS REPORT

Sample Rating Trend

PUMPHOUSE/CASTER SPRAY WATER PUMPS C - Caster Spray Water Electric Pump OB

Lube System

PETRO CANADA HYDREX AW 100 (1 GAL)





DIAGNOSIS

Recommendation

We advise that you check all areas where contaminants can enter the system. We advise that you check for visible metal particles in the oil. We advise that you perform a filter service, and use offline filtration to improve the cleanliness of the system fluid. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. Resample in 30-45 days to monitor this situation.

Wear

Light concentration of visible metal present.

Contamination

There is a high amount of particulates (2 to 100 microns in size) present in the oil. The system cleanliness code is much higher than the acceptable limit for the target ISO 4406 cleanliness code.

Fluid Condition


The AN level is acceptable for this fluid. The oil is no longer serviceable as a result of the abnormal and/or severe wear.

SAMPLE INFORMAT	TION method	limit/base	current	history1	history2	
Sample Number	Client Info		WC0898665	WC0850119	WC0824402	
Sample Date	Client Info		10 Jan 2024	16 Aug 2023	31 May 2023	
Machine Age hi	rs Client Info		0	0	0	
Oil Age h	rs Client Info		0	0	0	
Oil Changed	Client Info		N/A	N/A	N/A	
Sample Status			SEVERE	ABNORMAL	SEVERE	
CONTAMINATION	method	limit/base	current	historv1	history2	

Water		WC Method	>1	NEG	NEG	NEG
WEAR METALS		method	limit/base	current	history1	history2
PQ		ASTM D8184*	>DFLT	0	0	4
Iron	ppm	ASTM D5185(m)	>20	6	△ 35	21
Chromium	ppm	ASTM D5185(m)	>20	0	<1	0
Nickel	ppm	ASTM D5185(m)	>20	0	<1	0
Titanium	ppm	ASTM D5185(m)		0	0	0
Silver	ppm	ASTM D5185(m)		0	<1	0
Aluminum	ppm	ASTM D5185(m)	>20	1	<1	<1
Lead	ppm	ASTM D5185(m)	>20	<1	<1	1
Copper	ppm	ASTM D5185(m)	>20	6	4	2
Tin	ppm	ASTM D5185(m)	>20	0	0	0
Antimony	ppm	ASTM D5185(m)		0	0	0
Vanadium	ppm	ASTM D5185(m)		0	0	0
Beryllium	ppm	ASTM D5185(m)		0	0	0
Cadmium	ppm	ASTM D5185(m)		0	0	<1


ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185(m)	0	0	0	<1
Barium	ppm	ASTM D5185(m)	0	0	<1	22
Molybdenum	ppm	ASTM D5185(m)	0	0	0	<1
Manganese	ppm	ASTM D5185(m)	0	0	<1	<1
Magnesium	ppm	ASTM D5185(m)	0	<1	<1	4
Calcium	ppm	ASTM D5185(m)	50	48	47	60
Phosphorus	ppm	ASTM D5185(m)	330	336	347	352
Zinc	ppm	ASTM D5185(m)	430	426	404	402
Sulfur	ppm	ASTM D5185(m)	760	2625	2509	2593
Lithium	ppm	ASTM D5185(m)		<1	<1	<1

CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185(m)	>15	6	3	<u> </u>
Sodium	ppm	ASTM D5185(m)		<1	<1	1
Potassium	ppm	ASTM D5185(m)	>20	<1	0	0





OIL ANALYSIS REPORT





CALA ISO 17025:2017 Accredited

Laboratory

Laboratory Sample No. Lab Number **Unique Number**

: WC0898665

: 5709152

Recieved : 02608066

: 10 Jan 2024 Diagnosed : 15 Jan 2024 Diagnostician : Kevin Marson 2330 Regional Road #3, Door: BOSC8

NANTICOKE, ON CA NOA 1L0

Test Package : IND 2 (Additional Tests: Bottom, BottomAnalysis, FilterPatch, PQ, PrtFilter) To discuss this sample report, contact Customer Service at 1-800-268-2131.

Contact: Tom Walden Thomas.Walden@stelco.com T: (519)587-4541

Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab. Validity of results and interpretation are based on the sample and information as supplied.

Submitted By: Bob Melanson