

PROBLEM SUMMARY

Sample Rating Trend

ISO

Lime Kilns Route #1


PREVODOVASKRIN 102389 Kiln #3 Main Drive Reducer

Component

Gear Reducer

MOBIL MOBILGEAR 600 XP 320 (50 GAL)

COMPONENT CONDITION SUMMARY



RECOMMENDATION

Check seals and/or filters for points of contaminant entry. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. We recommend you service the filters on this component. Resample in 30-45 days to monitor this situation.

PROBLEMATIC TEST RESULTS							
Sample Status			SEVERE	SEVERE	SEVERE		
Particles >4μm	ASTM D7647	>20000	185379	<u>▲</u> 132204	165662		
Particles >6μm	ASTM D7647	>5000	32817	42240	58629		
Oil Cleanliness	ISO 4406 (c)	>21/19/16	25/22/16	2 4/23/17	25/23/18		

Customer Id: BEAING Sample No.: WC0877632 Lab Number: 02609139 Test Package: IND 2



To manage this report scan the QR code

To discuss the diagnosis or test data: Wes Davis +1 905-569-8600 x223 wesd@wearcheck.ca

To change component or sample information: Gloria Gonzalez +1 (289)291-4643 x4643 gloria.gonzalez@wearcheck.com

RECOMMENDED ACTIONS							
Action	Status	Date	Done By	Description			
Change Filter			?	We recommend you service the filters on this component.			
Resample			?	Resample in 30-45 days to monitor this situation.			
Check Breathers			?	The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather.			
Check Seals			?	Check seals and/or filters for points of contaminant entry.			

HISTORICAL DIAGNOSIS

16 Nov 2023 Diag: Wes Davis



Check seals and/or filters for points of contaminant entry. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. We recommend you service the filters on this component. Resample in 30-45 days to monitor this situation. All component wear rates are normal. There is a high amount of silt (particulates < 14 microns in size) present in the oil. The AN level is acceptable for this fluid. The oil is still serviceable provided that the contaminant(s) can be reduced to acceptable levels.



20 Apr 2023 Diag: Kevin Marson



We advise that you check all areas where contaminants can enter the system. We advise that you perform a filter service, and use off-line filtration to improve the cleanliness of the system fluid. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. Resample in 30-45 days to monitor this situation.All component wear rates are normal. There is a high amount of particulates (2 to 100 microns in size) present in the oil. Viscosity of sample indicates oil is within ISO 320 range, advise investigate. The AN level is acceptable for this fluid. The oil is still serviceable provided that the contaminant(s) can be reduced to acceptable levels.



05 Oct 2022 Diag: Kevin Marson



Check seals and/or filters for points of contaminant entry. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. We recommend you service the filters on this component. Resample in 30-45 days to monitor this situation. All component wear rates are normal. Particles >6µm are severely high. Particles >4µm are severely high. Oil Cleanliness are severely high. Particles >14µm are abnormally high. Particles >21µm are notably high. The AN level is acceptable for this fluid. The oil is still serviceable provided that the contaminant(s) can be reduced to acceptable levels.





OIL ANALYSIS REPORT

Machine Age

Oil Changed

Oil Age

yrs

Client Info

Client Info

Client Info

Sample Rating Trend

ISO

0

0

N/A

0

0

N/A

0

0

N/A

Lime Kilns Route #1 PREVODOVASKRIN 102389 Kiln #3 Ma

Component

Gear Reducer

MOBIL MOBILGEAR 600 XP 320 (50 GAL)

DIAGNOSIS

Recommendation

Check seals and/or filters for points of contaminant entry. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. We recommend you service the filters on this component. Resample in 30-45 days to monitor this situation.

Wear

All component wear rates are normal.

Contamination

There is a high amount of silt (particulates < 14 microns in size) present in the oil.

Fluid Condition

The AN level is acceptable for this fluid. The oil is still serviceable provided that the contaminant(s) can be reduced to acceptable levels.

Main Drive Reducer	192000 Sup 2010	Ap/2013 De2/014 De2/016	Apr2518 0cz2019 Oct	2022 Dec20:	X
SAMPLE INFORMATION	method	limit/base	current	history1	history2
Sample Number	Client Info	W	C0877632	WC0868738	WC0804942
Sample Date	Client Info	12	Dec 2023	16 Nov 2023	20 Apr 2023

Sample Status				SEVERE	SEVERE	SEVERE
CONTAMINATION	١	method	limit/base	current	history1	history2
Water		WC Method	>0.1	NEG	NEG	NEG
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185(m)	>150	19	20	20
Chromium	ppm	ASTM D5185(m)	>10	<1	0	0
Nickel	ppm	ASTM D5185(m)	>10	<1	<1	<1
Titanium	ppm	ASTM D5185(m)		0	0	0
Silver	ppm	ASTM D5185(m)		0	<1	0
Aluminum	ppm	ASTM D5185(m)	>25	<1	0	<1
Lead	ppm	ASTM D5185(m)	>100	<1	<1	3
Copper	ppm	ASTM D5185(m)	>50	<1	2	<1
Tin	ppm	ASTM D5185(m)	>10	0	0	0
Antimony	ppm	ASTM D5185(m)	>5	0	0	<1
Vanadium	ppm	ASTM D5185(m)		0	0	0
Beryllium	ppm	ASTM D5185(m)		0	0	0
Cadmium	ppm	ASTM D5185(m)		0	0	0
ADDITIVES		method	limit/base	current	history1	history2


ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185(m)		26	26	30
Barium	ppm	ASTM D5185(m)		0	<1	0
Molybdenum	ppm	ASTM D5185(m)		0	0	0
Manganese	ppm	ASTM D5185(m)		0	0	<1
Magnesium	ppm	ASTM D5185(m)		<1	0	<1
Calcium	ppm	ASTM D5185(m)		4	4	3
Phosphorus	ppm	ASTM D5185(m)		317	314	353
Zinc	ppm	ASTM D5185(m)		4	4	5
Sulfur	ppm	ASTM D5185(m)		11303	10898	11220
Lithium	ppm	ASTM D5185(m)		<1	<1	<1
CONTAMINANTS	6	method	limit/base	current	history1	history2

С	ONTAMINANTS		method	limit/base	current	history1	histor	y2
Sili	con	ppm	ASTM D5185(m)	>50	<1	<1	1	
Soc	dium	ppm	ASTM D5185(m)		0	<1	0	
Pot	assium	ppm	ASTM D5185(m)	>20	<1	0	0	

FLUID CLEANLINESS	method	limit/base	current	history1	history2
Particles >4µm	ASTM D7647	>20000	185379	132204	165662
			•		
Particles >6µm	ASTM D7647	>5000	△ 32817	42240	58629
Particles >14μm	ASTM D7647	>640	338	4 943	<u> 1881</u>
Particles >21μm	ASTM D7647	>160	43	145	<u>▲</u> 363
Particles >38μm	ASTM D7647	>40	2	6	10
Particles >71μm	ASTM D7647	>10	0	2	1
Oil Cleanliness	ISO 4406 (c)	>21/19/16	25/22/16	24/23/17	25/23/18



OIL ANALYSIS REPORT





CALA ISO 17025:2017 Accredited Laboratory

Laboratory Sample No. Lab Number Unique Number

: WC0877632 : 02609139

Recieved Diagnosed : 5710225 Diagnostician Test Package : IND 2 (Additional Tests: PrtCount)

: 16 Jan 2024 : 17 Jan 2024

: Wes Davis

374681 OXFORD COUNTY ROAD 6,, P.O. BOX 190 INGERSOLL, ON CA N5C 3K5

Contact: Jeff Geddes jeff.geddes@carmeusena.com

To discuss this sample report, contact Customer Service at 1-800-268-2131. Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab.

Validity of results and interpretation are based on the sample and information as supplied.

T: (519)423-6283 F: (519)423-6568