

PROBLEM SUMMARY

4 Calender Line 38-0081 Feedmill


Bearing


DOW CHEMICAL UCON CALENDAR OIL 51 (50 GAL)





COMPONENT CONDITION SUMMARY





RECOMMENDATION

Check seals and/or filters for points of contaminant entry. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. We recommend you service the filters on this component. Resample in 30-45 days to monitor this situation.

PROBLEMATIC T	EST RE	SULTS				
Sample Status				SEVERE	SEVERE	SEVERE
Particles >4µm		ASTM D7647	>10000	4 945800	1 76590	▲ 252558
Particles >6µm		ASTM D7647	>2500	176496	1 34581	172141
Particles >14µm		ASTM D7647	>160	4 355	24436	1 4820
Oil Cleanliness		ISO 4406 (c)	>20/18/14	27/25/16	2 5/24/22	2 5/25/21
Visc @ 40°C	cSt	ASTM D7279(m)	1150	<u> </u>	▲ 839	<u>▲</u> 861

Customer Id: CAN52CAM **Sample No.:** WC0867499 Lab Number: 02626751 Test Package: IND 2



To manage this report scan the QR code

To discuss the diagnosis or test data: Kevin Marson +1 (289)291-4644 x4644 Kevin.Marson@wearcheck.com

To change component or sample information: Gloria Gonzalez +1 (289)291-4643 x4643 gloria.gonzalez@wearcheck.com

RECOMMENDED ACTIONS					
Action	Status	Date	Done By	Description	
Change Filter			?	We recommend you service the filters on this component.	
Resample			?	Resample in 30-45 days to monitor this situation.	
Check Breathers			?	The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather.	
Check Seals			?	Check seals and/or filters for points of contaminant entry.	

HISTORICAL DIAGNOSIS

03 Jan 2024 Diag: Kevin Marson

ISO



We advise that you check all areas where contaminants can enter the system. We advise that you perform a filter service, and use off-line filtration to improve the cleanliness of the system fluid. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. Resample in 30-45 days to monitor this situation.All component wear rates are normal. There is a high amount of particulates (2 to 100 microns in size) present in the oil. Viscosity of sample indicates oil is within ISO 680 range, advise investigate. The AN level is acceptable for this fluid. The oil is still serviceable provided that the contaminant(s) can be reduced to acceptable levels.



03 Oct 2023 Diag: Kevin Marson

ISO



We advise that you check all areas where contaminants can enter the system. We advise that you perform a filter service, and use off-line filtration to improve the cleanliness of the system fluid. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. Resample in 30-45 days to monitor this situation. All component wear rates are normal. There is a high amount of particulates (2 to 100 microns in size) present in the oil. The oil viscosity is lower than typical, possibly indicating the addition of lighter grade oil. The AN level is acceptable for this fluid. The oil is still serviceable provided that the contaminant(s) can be reduced to acceptable levels.



06 Jul 2023 Diag: Kevin Marson

ISO



We advise that you check all areas where contaminants can enter the system. We advise that you perform a filter service, and use off-line filtration to improve the cleanliness of the system fluid. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. Resample in 30-45 days to monitor this situation. All component wear rates are normal. There is a high amount of particulates (2 to 100 microns in size) present in the oil. Viscosity of sample indicates oil is within ISO 1000 range, advise investigate. The AN level is acceptable for this fluid. The oil is still serviceable provided that the contaminant(s) can be reduced to acceptable levels.






OIL ANALYSIS REPORT

4 Calender Line 38-0081 Feedmill

Bearing

DOW CHEMICAL UCON CALENDAR OIL 51 (50 GAL)





DIAGNOSIS

Recommendation

Check seals and/or filters for points of contaminant entry. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. We recommend you service the filters on this component. Resample in 30-45 days to monitor this situation.

Wear

All component wear rates are normal.

Contamination

There is a high amount of silt (particulates < 14 microns in size) present in the oil.

Fluid Condition

Viscosity of sample indicates oil is within ISO 680 range, advise investigate. The AN level is acceptable for this fluid. The oil is still serviceable provided that the contaminant(s) can be reduced to acceptable levels.

SAMPLE INFOR	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		WC0867499	WC0744104	WC0808270
Sample Date		Client Info		20 Mar 2024	03 Jan 2024	03 Oct 2023
Machine Age	hrs	Client Info		0	0	0
Oil Age	hrs	Client Info		0	0	0
Oil Changed		Client Info		N/A	N/A	N/A
Sample Status				SEVERE	SEVERE	SEVERE
CONTAMINATIO	N	method	limit/base	current	history1	history2
Water		WC Method	>2	NEG	NEG	NEG
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185(m)	>20	0	0	0
Chromium	ppm	ASTM D5185(m)	>20	0	0	0
Nickel	ppm	ASTM D5185(m)	>20	0	0	0
Titanium	ppm	ASTM D5185(m)		0	0	0
Silver	ppm	ASTM D5185(m)		0	0	<1
Aluminum	ppm	ASTM D5185(m)		0	<1	0
Lead	ppm	ASTM D5185(m)	>20	0	0	0
Copper	ppm	ASTM D5185(m)		0	0	2
Tin	ppm	ASTM D5185(m)	>20	0	0	0
Antimony	ppm	ASTM D5185(m)		0	0	<1
Vanadium	ppm	ASTM D5185(m)		0	0	0
Beryllium	ppm	ASTM D5185(m)		0	0	0
Cadmium	ppm	ASTM D5185(m)		0	0	0
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185(m)		<1	0	0
Barium	ppm	ASTM D5185(m)		0	0	<1
Molybdenum	ppm	ASTM D5185(m)		0	0	0
Manganese	ppm	ASTM D5185(m)		0	0	0
Magnesium	ppm	ASTM D5185(m)		<1	<1	<1
Calcium	ppm	ASTM D5185(m)		0	0	<1
Phosphorus	ppm	ASTM D5185(m)		0	0	0
Zinc	ppm	ASTM D5185(m)		<1	<1	0
Sulfur	ppm	ASTM D5185(m)		39	65	453
Lithium	ppm	ASTM D5185(m)		<1	0	<1
CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185(m)	>15	0	1	1
Sodium	ppm	ASTM D5185(m)		0	2	2
Potassium	ppm	ASTM D5185(m)	>20	0	2	3
FLUID CLEANLII	NESS	method	limit/base	current	history1	history2
Particles >4µm		ASTM D7647	>10000	4 945800	1 76590	▲ 252558
Particles >6µm		ASTM D7647	>2500	176496	▲ 134581	▲ 172141
Particles >14μm		ASTM D7647	>160	△ 355	2 4436	1 4820
Particles >21μm		ASTM D7647	>40	51	▲ 5422	▲ 1580
Particles >38µm		ASTM D7647	>10	2	▲ 315	_ 20

ASTM D7647 >3

ISO 4406 (c) >20/18/14 **27/25/16**

Particles >71μm


Oil Cleanliness

1 25/24/22

25/25/21



OIL ANALYSIS REPORT







Laboratory Sample No.

Lab Number Unique Number : 5759883

: WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9 : WC0867499 Received

Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab.

: 02626751

To discuss this sample report, contact Customer Service at 1-800-268-2131.

: 04 Apr 2024 Tested : 11 Apr 2024 Diagnosed

: 11 Apr 2024 - Kevin Marson Test Package : IND 2 (Additional Tests: PRTCOUNT, TAN Man)

CANADIAN GENERAL TOWER LTD. 52 MIDDLETON STREET, P.O. BOX 160

CAMBRIDGE, ON **CA N1S 2R4** Contact: Bob Abell bob.abell@cgtower.com T: (519)623-1630

Validity of results and interpretation are based on the sample and information as supplied. Report Id: CAN52CAM [WCAMIS] 02626751 (Generated: 04/11/2024 08:18:38) Rev: 1

Contact/Location: Bob Abell - CAN52CAM

F: (519)623-7018