


# **PROBLEM SUMMARY**



1 [2534809] 01-0110-000-000


TRANSFER CONV N°2 (1M21)


Component

1 Gearbox

**MOBIL MOBILGEAR SHC 220 (2 GAL)** 

### COMPONENT CONDITION SUMMARY





#### **RECOMMENDATION**

We advise that you check all areas where dirt can enter the system. We advise that you perform a filter service, and use off-line filtration to improve the cleanliness of the system fluid. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. We recommend an early resample to monitor this condition.

PROBLEMATIC TEST RESULTS										
Sample Status				SEVERE	SEVERE	NORMAL				
Iron	ppm	ASTM D5185(m)	>200	<b>1110</b>	<b>4</b> 965	37				
Silicon	nnm	ASTM D5185(m)	>50	<u> 86</u>	A 91	16				

Customer Id: MACPEM **Sample No.:** WC0857993 Lab Number: 02629011 Test Package: IND 2



To manage this report scan the QR code

To discuss the diagnosis or test data: Kevin Marson +1 (289)291-4644 x4644 Kevin.Marson@wearcheck.com

To change component or sample information: Gloria Gonzalez +1 (289)291-4643 x4643 gloria.gonzalez@wearcheck.com

RECOMMENDED ACTIONS						
Action	Status	Date	Done By	Description		
Change Filter			?	We advise that you perform a filter service, and use off-line filtration to improve the cleanliness of the system fluid.		
Resample			?	We recommend an early resample to monitor this condition.		
Check Breathers			?	The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather.		
Check Dirt Access			?	We advise that you check all areas where dirt can enter the system.		
Filter Fluid			?	We advise that you perform a filter service, and use off-line filtration to improve the cleanliness of the system fluid.		

#### HISTORICAL DIAGNOSIS

WEAR



01 May 2023 Diag: Kevin Marson

We advise that you check all areas where dirt can enter the system. We recommend that you drain the oil from the component if this has not already been done. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. We recommend an early resample to monitor this condition. Iron ppm levels are severe. Gear wear is indicated. The low ferrous density (PQ) index indicates the wear metal levels are due to corrosion. There is a moderate concentration of dirt present in the oil. The AN level is acceptable for this fluid. The oil is no longer serviceable as a result of the abnormal and/or severe wear.



NORMAL



19 Jul 2018 Diag: Wes Davis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.



NORMAL



18 Sep 2002 Diag:

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the component. The condition of oil is suitable for further service.





## **OIL ANALYSIS REPORT**


1 [2534809] 01-0110-000-000

# TRANSFER CONV N°2 (1M21)

Component

1 Gearbox

**MOBIL MOBILGEAR SHC 220 (2 GAL)** 



#### DIAGNOSIS

#### Recommendation

We advise that you check all areas where dirt can enter the system. We advise that you perform a filter service, and use off-line filtration to improve the cleanliness of the system fluid. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. We recommend an early resample to monitor this condition.

### Wear

Iron ppm levels are severe. The low ferrous density (PQ) index indicates the wear metal levels are due to corrosion.

### Contamination

There is a moderate concentration of dirt present in the oil. High amount of ingressed dirt has caused abrasive wear to the component.

#### **Fluid Condition**

The AN level is acceptable for this fluid. The oil is no longer serviceable as a result of the abnormal and/or severe wear.

SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		WC0857993	WC0754110	WC980908
Sample Date		Client Info		11 Apr 2024	01 May 2023	19 Jul 2018
Machine Age	yrs	Client Info		0	0	0
Oil Age	yrs	Client Info		0	2	0
Oil Changed		Client Info		N/A	N/A	N/A
Sample Status				SEVERE	SEVERE	NORMAL
CONTAMINATION	V	method	limit/base	current	history1	history2
Water		WC Method	>0.2	NEG	NEG	NEG
WEAR METALS		method	limit/base	current	history1	history2
PQ		ASTM D8184*		1	3	28
Iron	ppm	ASTM D5185(m)	>200	<b>1110</b>	<b>4</b> 965	37
Chromium	ppm	ASTM D5185(m)	>15	3	3	1
Nickel	ppm	ASTM D5185(m)	>15	<1	<1	<1
Titanium	ppm	ASTM D5185(m)		0	0	0
Silver	ppm	ASTM D5185(m)		0	0	0
Aluminum	ppm	ASTM D5185(m)	>25	<1	1	2
Lead	ppm	ASTM D5185(m)	>100	0	0	<1
Copper	ppm	ASTM D5185(m)	>200	<1	0	<1
Tin	ppm	ASTM D5185(m)	>25	0	0	0
Antimony	ppm	ASTM D5185(m)	>5	0	<1	0
Vanadium	ppm	ASTM D5185(m)		0	0	0
Beryllium	ppm	ASTM D5185(m)		0	0	0
Cadmium	ppm	ASTM D5185(m)		0	0	0
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185(m)		20	20	24
Barium	ppm	ASTM D5185(m)		0	0	<1
Molybdenum	ppm	ASTM D5185(m)		0	0	<1
Manganese	ppm	ASTM D5185(m)		12	11	<1
Magnesium	ppm	ASTM D5185(m)		<1	<1	<1
Calcium	ppm	ASTM D5185(m)		33	37	28
Phosphorus	ppm	ASTM D5185(m)		323	384	241
Zinc	ppm	ASTM D5185(m)		4	4	11
Sulfur	ppm	ASTM D5185(m)		4278	4756	8610
Lithium	ppm	ASTM D5185(m)		<1	<1	4
CONTAMINANTS	;	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185(m)	>50	<u>^</u> 86	<b>△</b> 91	16
Sodium	ppm	ASTM D5185(m)		<1	<1	<1
Potassium	ppm	ASTM D5185(m)	>20	<1	1	2
FLUID DEGRADA	TION	method	limit/base	current	history1	history2
Acid Number (AN)	mg KOH/g	ASTM D974*		1.01	0.96	0.94



## **OIL ANALYSIS REPORT**







Laboratory Sample No.

Lab Number Unique Number : 5762143

: WC0857993 : 02629011

**Tested** Diagnosed

Test Package : IND 2 ( Additional Tests: TAN Man ) To discuss this sample report, contact Customer Service at 1-800-268-2131.

Received

: 15 Apr 2024

: 16 Apr 2024

: 17 Apr 2024 - Kevin Marson

Test denoted (\*) outside scope of accreditation, (m) method modified, (e) tested at external lab. Validity of results and interpretation are based on the sample and information as supplied.

Roseburg Pembroke MDF Inc.

777 Fibreboard Drive Pembroke, ON **CA K8A 6W5** Contact: Dan Havis danielh@rfpco.com T: (613)732-3939

F: (613)732-2869