

# **PROBLEM SUMMARY**

Sample Rating Trend




Area **6** Machine I


# 6-3-652 Coal Mill Slide Shoe L/P Gear

Compone

**MOBIL MOBILGEAR SHC 460 (300 LTR)** 

### COMPONENT CONDITION SUMMARY





### **RECOMMENDATION**

We advise that you check all areas where contaminants can enter the system. We advise that you perform a filter service, and use off-line filtration to improve the cleanliness of the system fluid. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. Resample in 30-45 days to monitor this situation.

PROBLEMATIC TEST RESULTS								
Sample Status				SEVERE	SEVERE	SEVERE		
Tin	ppm	ASTM D5185(m)	>9	<b>A</b> 84	<b>4</b> 19	<b>442</b>		
Particles >6µm		ASTM D7647	>20000	<b>197422</b>	▲ 385088	<b>251155</b>		
Particles >14µm		ASTM D7647	>5000	▲ 58474	▲ 208011	<b>1</b> 59645		
Particles >21µm		ASTM D7647	>1300	<b>13044</b>	<b>4</b> 96561	<b>83611</b>		
Oil Cleanliness		ISO 4406 (c)	>/21/19	<b>25/25/23</b>	<b>2</b> 6/26/25	<b>2</b> 5/25/24		

Customer Id: STMBOW Sample No.: WC0925352 Lab Number: 02629375 Test Package: IND 2



To manage this report scan the QR code

To discuss the diagnosis or test data: Kevin Marson +1 (289)291-4644 x4644 Kevin.Marson@wearcheck.com

To change component or sample information: Gloria Gonzalez +1 (289)291-4643 x4643 gloria.gonzalez@wearcheck.com

RECOMMENDED ACTIONS								
Action	Status	Date	Done By	Description				
Change Filter			?	We advise that you perform a filter service, and use off-line filtration to improve the cleanliness of the system fluid.				
Resample			?	Resample in 30-45 days to monitor this situation.				
Check Breathers			?	The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather.				
Check Dirt Access			?	We advise that you check all areas where contaminants can enter the system.				
Filter Fluid			?	We advise that you perform a filter service, and use off-line filtration to improve the cleanliness of the system fluid.				

### HISTORICAL DIAGNOSIS

WEAR



### 20 Feb 2024 Diag: Kevin Marson

We advise that you check all areas where contaminants can enter the system. We advise that you perform a filter service, and use off-line filtration to improve the cleanliness of the system fluid. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. Re-sampling is suggested to confirm test results prior to significant maintenance activities being performed. Please indicate that this is a resample on your Sample Information Form (SIF). Resample in 30-45 days to monitor this situation. Tin and antimony ppm levels are severe. Lead ppm levels are abnormal. Bearing and/or bushing wear is indicated. There is a high amount of particulates (2 to 100 microns in size) present in the oil. The system cleanliness code is much higher than the acceptable limit for the target ISO 4406 cleanliness code. The AN level is acceptable for this fluid. The oil is still serviceable provided that the contaminant(s) can be reduced to acceptable levels.



WEAR



## 28 Nov 2023 Diag: Kevin Marson

We advise that you check all areas where contaminants can enter the system. We advise that you perform a filter service, and use off-line filtration to improve the cleanliness of the system fluid. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. Re-sampling is suggested to confirm test results prior to significant maintenance activities being performed. Please indicate that this is a resample on your Sample Information Form (SIF). Resample in 30-45 days to monitor this situation. Tin and antimony ppm levels are severe. Lead ppm levels are abnormal. Copper ppm levels are noted. Bearing and/or bushing wear is indicated. There is a high amount of particulates (2 to 100 microns in size) present in the oil. The system cleanliness code is much higher than the acceptable limit for the target ISO 4406 cleanliness code. The AN level is acceptable for this fluid. The oil is still serviceable provided that the contaminant(s) can be reduced to acceptable levels.



ICO



### 14 Sep 2023 Diag: Wes Davis

We recommend you service the filters on this component. We recommend an early resample to monitor this condition. All component wear rates are normal. There is a moderate amount of silt (particulates < 14 microns in size) present in the oil. The system cleanliness is above the acceptable limit for the target ISO 4406 cleanliness code. The AN level is acceptable for this fluid. The oil is still serviceable provided that the contaminant(s) can be reduced to acceptable levels.






## **OIL ANALYSIS REPORT**

Oil Changed

Sample Status



N/A

**SEVERE** 

N/A

SEVERE





N/A

SEVERE

Area

# 6-3-652 Coal Mill Slide Shoe

Pump

**MOBIL MOBILGEAR SHC 460 (300 LTR)** 

_	A C	N I I	$\neg$	10
- 1 ) 1	Δι.	ìΝί		
- $           -$	<i>,</i> , , ,	41 V	$\sim$	,,,

### Recommendation

We advise that you check all areas where contaminants can enter the system. We advise that you perform a filter service, and use off-line filtration to improve the cleanliness of the system fluid. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. Resample in 30-45 days to monitor this situation.

### Wear

The tin level has decreased, but is still abnormal. Bearing and/or bushing wear is indicated.

### Contamination

There is a high amount of particulates (2 to 100 microns in size) present in the oil. The system cleanliness code is much higher than the acceptable limit for the target ISO 4406 cleanliness code.

### **Fluid Condition**

The AN level is acceptable for this fluid. The oil is still serviceable provided that the contaminant(s) can be reduced to acceptable levels.

oe L/P Gear	X815 April 1	116 Oct2017 Dec2018 Nov20	19 Jan 221 May 2022 1	Inglitta	X
SAMPLE INFORMAT	ION method	limit/base	current	history1	history2
Sample Number	Client Info	w	C0925352	WC0902065	WC0869895
Sample Date	Client Info	05	5 Apr 2024	20 Feb 2024	28 Nov 2023
Machine Age hrs	s Client Info	0		0	0
Oil Age hrs	s Client Info	0		0	0

Client Info

Sample Rating Trend

CONTAMINATIO	N	method	limit/base	current	history1	history2
Water		WC Method	>.1	NEG	NEG	NEG
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185(m)	>90	3	16	15
Chromium	ppm	ASTM D5185(m)	>5	0	0	0
Nickel	ppm	ASTM D5185(m)	>5	<1	<1	<1
Titanium	ppm	ASTM D5185(m)	>3	0	0	0
Silver	ppm	ASTM D5185(m)	>3	0	0	<1
Aluminum	ppm	ASTM D5185(m)	>7	<1	2	3
Lead	ppm	ASTM D5185(m)	>12	2	<u> </u>	<u> </u>
Copper	ppm	ASTM D5185(m)	>30	5	21	<b>2</b> 1
Tin	ppm	ASTM D5185(m)	>9	<u> </u>	<b>4</b> 19	<b>442</b>
Antimony	ppm	ASTM D5185(m)		12	<b>△</b> 64	<b>▲</b> 67
Vanadium	ppm	ASTM D5185(m)		0	0	0
Beryllium	ppm	ASTM D5185(m)		0	0	0
Cadmium	ppm	ASTM D5185(m)		0	2	2
A D D ITIV (EQ						


ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185(m)	5.7	4	8	8
Barium	ppm	ASTM D5185(m)	0.0	0	0	<1
Molybdenum	ppm	ASTM D5185(m)	0.0	0	0	0
Manganese	ppm	ASTM D5185(m)	0.0	0	0	0
Magnesium	ppm	ASTM D5185(m)	0.0	<1	<1	<1
Calcium	ppm	ASTM D5185(m)	0.0	2	6	9
Phosphorus	ppm	ASTM D5185(m)	180	401	365	361
Zinc	ppm	ASTM D5185(m)	0.8	<1	1	1
Sulfur	ppm	ASTM D5185(m)	4270	1715	4031	3969
Lithium	ppm	ASTM D5185(m)		<1	<1	<1
CONTAMINANTS		method	limit/base	current	history1	history2


CONTAMINANT	ΓS	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185(m)	>60	11	4	7
Sodium	ppm	ASTM D5185(m)		<1	<1	<1
Potassium	ppm	ASTM D5185(m)	>20	<1	1	<1


i o toto o toto			* *		
FLUID CLEANLINESS	method	limit/base	current	history1	history2
Particles >4µm	ASTM D7647		234624	420055	265842
Particles >6µm	ASTM D7647	>20000	<b>197422</b>	▲ 385088	<b>2</b> 51155
Particles >14μm	ASTM D7647	>5000	<b>▲</b> 58474	<b>2</b> 08011	<b>1</b> 59645
Particles >21µm	ASTM D7647	>1300	<b>13044</b>	<b>4</b> 96561	<b>83611</b>
Particles >38µm	ASTM D7647	>320	108	<b>▲</b> 3645	<u> </u>
Particles >71µm	ASTM D7647	>80	5	6	1
Oil Cleanliness	ISO 4406 (c)	>/21/19	<b>25/25/23</b>	<b>2</b> 6/26/25	<b>2</b> 5/25/24





## OIL ANALYSIS REPORT




















Laboratory

Report Id: STMBOW [WCAMIS] 02629375 (Generated: 04/17/2024 15:16:26) Rev: 1

Laboratory

Sample No. Lab Number Unique Number : 5762507

: WC0925352 : 02629375

: WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9 Received **Tested** 

: 16 Apr 2024 : 17 Apr 2024 : 17 Apr 2024 - Kevin Marson

Diagnosed Test Package : IND 2 (Additional Tests: TAN Man)

To discuss this sample report, contact Customer Service at 1-800-268-2131. Test denoted (\*) outside scope of accreditation, (m) method modified, (e) tested at external lab.

Validity of results and interpretation are based on the sample and information as supplied.

ST. MARYS CEMENT CO.

400 BOWMANVILLE AVENUE BOWMANVILLE, ON

**CA L1C 7B5** Contact: Lou Traiforos lou.traiforos@vcimentos.com

> T: (905)440-5874 F: (905)623-4695

Submitted By: ?