


# **PROBLEM SUMMARY**


Sample Rating Trend



# RHOB/HYDRAULICS E - 2 Hydraulics Repair Car Tank Hydraulic System

FIRE-RESISTANT FLUID ISO 46 (132 GAL)

# COMPONENT CONDITION SUMMARY



# **RECOMMENDATION**

We advise that you check all areas where contaminants can enter the system. We advise that you perform a filter service, and use off-line filtration to improve the cleanliness of the system fluid. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. Resample in 30-45 days to monitor this situation. Please specify the brand, type, and viscosity of the oil on your next sample.

PROBLEMATIC TEST RESULTS							
Sample Status			SEVERE	SEVERE	SEVERE		
Particles >4μm	ASTM D7647	>5000	<b>62139</b>	<b>▲</b> 162842	<b>4</b> 1349		
Particles >6μm	ASTM D7647	>1300	<b>10417</b>	<b>22180</b>	<u></u> 5606		
Particles >14μm	ASTM D7647	>160	<b>△</b> 573	<u>▲</u> 1029	<u></u> 587		
Particles >21µm	ASTM D7647	>40	<b>195</b>	<u>237</u>	<u> </u>		
Oil Cleanliness	ISO 4406 (c)	>19/17/14	<b>23/21/16</b>	<b>▲</b> 25/22/17	<b>2</b> 3/20/16		

Customer Id: LEWBOSC Sample No.: WC0934096 Lab Number: 02629393 Test Package: IND 2



To manage this report scan the QR code

To discuss the diagnosis or test data: Kevin Marson +1 (289)291-4644 x4644 Kevin.Marson@wearcheck.com

To change component or sample information: Gloria Gonzalez +1 (289)291-4643 x4643 gloria.gonzalez@wearcheck.com

RECOMMENDED ACTIONS						
Action	Status	Date	Done By	Description		
Change Filter			?	We advise that you perform a filter service, and use off-line filtration to improve the cleanliness of the system fluid.		
Resample			?	Resample in 30-45 days to monitor this situation.		
Information Required			?	Please specify the brand, type, and viscosity of the oil on your next sample.		
Check Breathers			?	The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather.		
Check Dirt Access			?	We advise that you check all areas where contaminants can enter the system.		
Filter Fluid			?	We advise that you perform a filter service, and use off-line filtration to improve the cleanliness of the system fluid.		

# HISTORICAL DIAGNOSIS

# 22 Mar 2024 Diag: Kevin Marson

X

We advise that you check all areas where contaminants can enter the system. We advise that you perform a filter service, and use off-line filtration to improve the cleanliness of the system fluid. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. Resample in 30-45 days to monitor this situation. Please specify the brand, type, and viscosity of the oil on your next sample.All component wear rates are normal. There is a high amount of particulates (2 to 100 microns in size) present in the oil. The AN level is acceptable for this fluid. The pH level of this fluid is within the acceptable limits. The reserve alkalinity of this fluid is acceptable. The water concentration level is acceptable for this fluid. The oil is still serviceable provided that the contaminant(s) can be reduced to acceptable levels.



# 16 Feb 2024 Diag: Kevin Marson



We advise that you check all areas where contaminants can enter the system. We advise that you perform a filter service, and use off-line filtration to improve the cleanliness of the system fluid. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. Resample in 30-45 days to monitor this situation. Please specify the brand, type, and viscosity of the oil on your next sample.All component wear rates are normal. There is a high amount of particulates (2 to 100 microns in size) present in the oil. The AN level is acceptable for this fluid. The pH level of this fluid is within the acceptable limits. The reserve alkalinity of this fluid is acceptable. The water concentration level is acceptable for this fluid. The oil is still serviceable provided that the contaminant(s) can be reduced to acceptable levels.



#### 22 Jan 2024 Diag: Bill Quesnel




We advise that you perform a filter service, and use off-line filtration to improve the cleanliness of the system fluid. We recommend an early resample to monitor this condition. Please specify the brand, type, and viscosity of the oil on your next sample. All component wear rates are normal. There is a moderate amount of particulates (2 to 100 microns in size) present in the oil. The AN level is acceptable for this fluid. The pH level of this fluid is within the acceptable limits. The reserve alkalinity of this fluid is acceptable. The water concentration level is acceptable for this fluid. The oil is still serviceable provided that the contaminant(s) can be reduced to acceptable levels.





# **OIL ANALYSIS REPORT**

# Sample Rating Trend



ISO



# RHOB/HYDRAULICS E - 2 Hydraulics Repair Car Component

**Tank Hydraulic System** 

Fluid

FIRE-RESISTANT FLUID ISO 46 (132 GAL)

# DIAGNOSIS

#### Recommendation

We advise that you check all areas where contaminants can enter the system. We advise that you perform a filter service, and use off-line filtration to improve the cleanliness of the system fluid. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. Resample in 30-45 days to monitor this situation. Please specify the brand, type, and viscosity of the oil on your next sample.

# Wear

All component wear rates are normal.

# Contamination

There is a high amount of particulates (2 to 100 microns in size) present in the oil.


#### Fluid Condition


The AN level is acceptable for this fluid. The pH level of this fluid is within the acceptable limits. The reserve alkalinity of this fluid is acceptable. The water concentration level is acceptable for this fluid. The oil is still serviceable provided that the contaminant(s) can be reduced to acceptable levels.


SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		WC0934096	WC0926481	WC0910441
Sample Date		Client Info		15 Apr 2024	22 Mar 2024	16 Feb 2024
Machine Age	hrs	Client Info		0	0	0
Oil Age	hrs	Client Info		0	0	0
Oil Changed		Client Info		N/A	N/A	N/A
Sample Status				SEVERE	SEVERE	SEVERE
WEAR METALS		method	limit/base	current	history1	history2
PQ		ASTM D8184*	>99999	0	0	0
Iron	ppm	ASTM D5185(m)	>20	0	0	0
Chromium	ppm	ASTM D5185(m)	>20	0	0	0
Nickel	ppm	ASTM D5185(m)	>20	0	0	0
Titanium	ppm	ASTM D5185(m)		0	0	0
Silver	ppm	ASTM D5185(m)		<1	<1	<1
Aluminum	ppm	ASTM D5185(m)	>20	0	0	0
Lead	ppm	ASTM D5185(m)	>20	0	0	0
Copper	ppm	ASTM D5185(m)	>20	0	0	0
Tin	ppm	ASTM D5185(m)	>20	0	0	0
Antimony	ppm	ASTM D5185(m)		<1	0	<1
Vanadium	ppm	ASTM D5185(m)		0	0	0
Beryllium	ppm	ASTM D5185(m)		0	0	0
Cadmium	ppm	ASTM D5185(m)		0	0	0
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185(m)	5	<1	0	<1
Barium	ppm	ASTM D5185(m)	5	1	0	<1
Molybdenum	ppm	ASTM D5185(m)	5	0	0	2
Manganese	ppm	ASTM D5185(m)		0	0	0
Magnesium	ppm	ASTM D5185(m)	5	<1	0	<1
Calcium	ppm	ASTM D5185(m)	50	<1	0	1
Phosphorus	ppm	ASTM D5185(m)	175	<1	0	301
Zinc	ppm	ASTM D5185(m)	62	0	0	0
Sulfur	ppm	ASTM D5185(m)	500	43	55	64
Lithium	ppm	ASTM D5185(m)		<1	<1	<1
CONTAMINANTS	8	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185(m)	>15	<1	0	1
Sodium	ppm	ASTM D5185(m)		159	161	421
Potassium	ppm	ASTM D5185(m)	>20	14	10	438
Water	%	ASTM D6304*	>55	37.1	38.4	41.3
ppm Water	ppm	ASTM D6304*	>55000	371000	384000	413000
FLUID CLEANLIN	NESS	method	limit/base	current	history1	history2
Particles >4µm		ASTM D7647	>5000	<b>62139</b>	<b>▲</b> 162842	<b>4</b> 1349
Particles >6μm		ASTM D7647	>1300	<b>10417</b>	<b>▲</b> 22180	<u></u> 5606
Particles >14μm		ASTM D7647	>160	<u>▲</u> 573	<b>△</b> 1029	<u></u> 587
Particles >21µm		ASTM D7647	>40	<u> </u>	<u>▲</u> 237	<u>^</u> 247
Particles >38μm		ASTM D7647	>10	13	<b>1</b> 9	<b>▲</b> 43
Particles >71μm		ASTM D7647		2	0	4
Oil Cleanliness 3:29:43) Rev: 1		ISO 4406 (c)	>19/17/14	<b>23/21/16</b>	▲ 25/22/17 Submitted By	23/20/16 : Bob Melansor



# **OIL ANALYSIS REPORT**







FLUID DEGRADA	TION	method	limit/base	current	history1	history2
Acid Number (AN)	mg KOH/g	ASTM D974*	3.63	3.38	3.41	3.04
Alkiline Reserve (Oils)	ml KOH/g	ASTM D1121*		199	194	204
VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	Visual*	NONE	NONE	NONE	NONE
Yellow Metal	scalar	Visual*	NONE	NONE	NONE	NONE
Precipitate	scalar	Visual*	NONE	NONE	NONE	NONE
Silt	scalar	Visual*	NONE	NONE	NONE	NONE
Debris	scalar	Visual*	NONE	VLITE	NONE	NONE
Sand/Dirt	scalar	Visual*	NONE	NONE	NONE	NONE
Appearance	scalar	Visual*	NORML	FRGLY	NORML	FRGLY
Odor	scalar	Visual*	NORML	NORML	NORML	NORML
<b>Emulsified Water</b>	scalar	Visual*	>55	>10%	NEG	>10%
Free Water	scalar	Visual*		NEG	NEG	NEG
FLUID PROPERT	IES	method	limit/base	current	history1	history2
рН	Scale 0-14	ASTM D1287*		9.64	9.67	9.67
Visc @ 40°C	cSt	ASTM D7279(m)	46	42.5	45.5	43.6
SAMPLE IMAGES	3	method	limit/base	current	history1	history2
Color						
				0		
Bottom						C C C C C C C C C C C C C C C C C C C



**CALA** ISO 17025:2017 Accredited Laboratory

Laboratory Sample No.

Lab Number : 02629393 Unique Number : 5762525

: WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9 : WC0934096 : 16 Apr 2024

Received **Tested** : 17 Apr 2024 Diagnosed

: 18 Apr 2024 - Kevin Marson Test Package : IND 2 ( Additional Tests: KF, pH, PQ, ReserveAlk, TAN Man )

To discuss this sample report, contact Customer Service at 1-800-268-2131. Test denoted (\*) outside scope of accreditation, (m) method modified, (e) tested at external lab. Validity of results and interpretation are based on the sample and information as supplied.

STELCO - BOSC - Basic Oxygen Slab Caster

2330 Regional Road #3, Door: BOSC8 NANTICOKE, ON CA NOA 1L0

Contact: Tom Walden Thomas.Walden@stelco.com T: (519)587-4541

F: (519)587-7702

Submitted By: Bob Melanson