

PROBLEM SUMMARY

Sample Rating Trend

ISO


106 Mill #2 COIL BOX COMPRESSOR (PLS081)

Reciprocating Compressor

SHELL TURBO T ISO 68 (--- GAL)



COMPONENT CONDITION SUMMARY



RECOMMENDATION

We advise that you check all areas where contaminants can enter the system. We advise that you perform a filter service, and use off-line filtration to improve the cleanliness of the system fluid. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. Resample in 30-45 days to monitor this situation.

PROBLEMATIC TEST RESULTS										
Sample Status		SEVERE	SEVERE	SEVERE						
Particles >4µm	ASTM D7647 >10	000 166704	1 45787	▲ 181278						
Particles >6µm	ASTM D7647 >25	00 106593	46677	114046						
Particles >14µm	ASTM D7647 >32	0 A 5271	297	▲ 2578						
Particles >21µm	ASTM D7647 >80	A 707	48	<u>421</u>						
Oil Cleanliness	ISO 4406 (c) >20	/18/15 4 25/24/2 0	2 4/23/15	2 5/24/19						

Customer Id: ALGSSM Sample No.: WC0813590 Lab Number: 02645484 Test Package: IND 2



To manage this report scan the QR code

To discuss the diagnosis or test data: Kevin Marson +1 (289)291-4644 x4644 Kevin.Marson@wearcheck.com

To change component or sample information: Gloria Gonzalez +1 (289)291-4643 x4643 gloria.gonzalez@wearcheck.com

RECOMMENDED ACTIONS								
Action	Status	Date	Done By	Description				
Change Filter			?	We advise that you perform a filter service, and use off-line filtration to improve the cleanliness of the system fluid.				
Resample			?	Resample in 30-45 days to monitor this situation.				
Check Breathers			?	The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather.				
Check Dirt Access			?	We advise that you check all areas where contaminants can enter the system.				
Filter Fluid			?	We advise that you perform a filter service, and use off-line filtration to improve the cleanliness of the system fluid.				

HISTORICAL DIAGNOSIS

ISO



04 Jun 2023 Diag: Kevin Marson

Check seals and/or filters for points of contaminant entry. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. We recommend either performing an oil change or oil filtration. We cannot recommend specific action as we have limited information with regards to reservoir capacity and/or lubricant type. Resample in 30-45 days to monitor this situation. Copper and iron ppm levels are abnormal. There is a high amount of silt (particulates < 14 microns in size) present in the oil. The AN level is acceptable for this fluid. The oil is no longer serviceable as a result of the abnormal and/or severe wear.



ISO



02 Nov 2022 Diag: Kevin Marson

We advise that you check all areas where contaminants can enter the system. We recommend either performing an oil change or oil filtration. We cannot recommend specific action as we have limited information with regards to reservoir capacity and/or lubricant type. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. Resample in 30-45 days to monitor this situation. Please specify the brand, type, and viscosity of the oil on your next sample. NOTE: Please provide information regarding reservoir capacity, filter type and micron rating with next sample.Copper and iron ppm levels are abnormal. Particles >14µm are severely high. Particles >6µm are severely high. Oil Cleanliness are severely high. Particles >4µm are severely high. Particles >21µm are abnormally high. Particles >38µm are notably high. The water content is negligible. Viscosity of sample indicates oil is within ISO 68 range, advise investigate. The AN level is acceptable for this fluid. The oil is no longer serviceable as a result of the abnormal and/or severe wear.





OIL ANALYSIS REPORT

106 Mill **#2 COIL BOX COMPRESSOR (PLS081)**

Reciprocating Compressor

SHELL TURBO T ISO 68 (--- GAL)

Sample Rating Trend

DIAGNOSIS

Recommendation

We advise that you check all areas where contaminants can enter the system. We advise that you perform a filter service, and use off-line filtration to improve the cleanliness of the system fluid. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. Resample in 30-45 days to monitor this situation.

Wear

All component wear rates are normal.

Contamination

There is a high amount of particulates (2 to 100 microns in size) present in the oil.

Fluid Condition

The AN level is acceptable for this fluid. The oil is still serviceable provided that the contaminant(s) can be reduced to acceptable levels.

		No	v2022	Jun2023 Jul21	124	
SAMPLE INFOR	RMATION	method	limit/base	current	history1	history2
Sample Number		Client Info		WC0813590	WC0714521	WC0714611
Sample Date		Client Info		01 Jul 2024	04 Jun 2023	02 Nov 2022
Machine Age	hrs	Client Info		0	0	0
Oil Age	hrs	Client Info		0	0	0
Oil Changed		Client Info		N/A	N/A	N/A
Sample Status				SEVERE	SEVERE	SEVERE
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185(m)	>50	44	6 0	△ 67
Chromium	ppm	ASTM D5185(m)	>10	<1	2	2
Nickel	ppm	ASTM D5185(m)		<1	0	0
Titanium	ppm	ASTM D5185(m)		0	0	0
Silver	ppm	ASTM D5185(m)		0	0	0
Aluminum	ppm	ASTM D5185(m)	>25	<1	2	1
Lead	ppm	ASTM D5185(m)	>25	3	8	9
Copper	ppm	ASTM D5185(m)		43	<u>▲</u> 136	<u> </u>
Tin	ppm	ASTM D5185(m)	>15	0	0	<1
Antimony	ppm	ASTM D5185(m)		0	<1	<1
Vanadium	ppm	ASTM D5185(m)		0	0	0
Beryllium	ppm	ASTM D5185(m)		0	0	0
Cadmium	ppm	ASTM D5105(m) ASTM D5185(m)		0	0	0
	ррпп	. ,	11 - 11 /1			
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185(m)		<1	<1	<1
Barium	ppm	ASTM D5185(m)		0	0	0
Molybdenum	ppm	ASTM D5185(m)		0	0	0
Manganese	ppm	ASTM D5185(m)		<1	<1	<1
Magnesium	ppm	ASTM D5185(m)		<1	<1	<1
Calcium	ppm	ASTM D5185(m)		4	0	<1
Phosphorus	ppm	ASTM D5185(m)		40	37	63
Zinc	ppm	ASTM D5185(m)		68	50	12
Sulfur	ppm	ASTM D5185(m)		269	230	146
Lithium	ppm	ASTM D5185(m)		<1	<1	<1
CONTAMINANT	S	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185(m)	>25	6	2	2
Sodium	ppm	ASTM D5185(m)		2	2	6
Potassium	ppm	ASTM D5185(m)	>20	3	1	<1
Water	%	ASTM D6304*	>0.1	0.003	0.002	0.008
ppm Water	ppm	ASTM D6304*	>1000	39	19.3	80.3
FLUID CLEANL	NESS	method	limit/base	current	history1	history2
Particles >4µm		ASTM D7647	>10000	166704	1 45787	▲ 181278
Particles >6µm		ASTM D7647	>2500	1 06593	4 6677	114046
Particles >14µm		ASTM D7647	>320	▲ 5271	297	2578
Particles >21µm		ASTM D7647		^ 707	48	<u>421</u>
Particles >38µm		ASTM D7647	>20	31	1	33
Particles >71μm		ASTM D7647	>4	3	0	5
Oil Cleanliness		ISO 4406 (a)	> 20/19/15	A 25/24/20	A 24/22/15	A 25/24/10

Oil Cleanliness


4 24/23/15

ISO 4406 (c) >20/18/15 **25/24/20**

25/24/19



OIL ANALYSIS REPORT





CALA ISO 17025:2017 Accredited Laboratory

Laboratory Sample No.

Lab Number : 02645484 Unique Number : 5803023

: WC0813590

Received : 04 Jul 2024 Tested : 05 Jul 2024

Diagnosed : 05 Jul 2024 - Kevin Marson Test Package : IND 2 (Additional Tests: KF, PrtCount, TAN Man)

To discuss this sample report, contact Customer Service at 1-800-268-2131. Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab. 301 WALLACE TERRACE SAULT STE MARIE, ON **CA P6C 1K8**

Contact: Algoma Reliability algomareliability@algoma.com T: (705)206-1059

Validity of results and interpretation are based on the sample and information as supplied.

F: (705)945-3585