

PROBLEM SUMMARY


Sample Rating Trend

5 Utilities/030 Boiler House/B Blower/Fan/713A #13 FD West N/A 30TB713A

Component **Turbine**

PETRO CANADA TURBOFLO 68 (20 LTR)

COMPONENT CONDITION SUMMARY



RECOMMENDATION

We advise that you check all areas where contaminants can enter the system. We advise that you perform a filter service, and use off-line filtration to improve the cleanliness of the system fluid. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. Resample in 30-45 days to monitor this situation.

PROBLEMATIC TEST RESULTS										
Sample Status			SEVERE	SEVERE	SEVERE					
Particles >4µm	ASTM D7647	>2500	△ 36599	▲ 36044	▲ 114427					
Particles >6µm	ASTM D7647	>640	8884	▲ 3260	△ 36630					
Particles >14μm	ASTM D7647	>80	△ 558	17	<u></u> 623					
Particles >21μm	ASTM D7647	>20	186	3	<u> 75</u>					
Particles >38μm	ASTM D7647	>4	<u>^</u> 27	1	3					
Oil Cleanliness	ISO 4406 (c)	>18/16/13	22/20/16	2 2/19/11	2 4/22/16					

Customer Id: PETMIS Sample No.: WC0957470 Lab Number: 02646704 Test Package: IND 2



To manage this report scan the QR code

To discuss the diagnosis or test data: Kevin Marson +1 (289)291-4644 x4644 Kevin.Marson@wearcheck.com

To change component or sample information: Gloria Gonzalez +1 (289)291-4643 x4643 gloria.gonzalez@wearcheck.com

RECOMMENDED ACTIONS							
Action	Status	Date	Done By	Description			
Change Filter			?	We advise that you perform a filter service, and use off-line filtration to improve the cleanliness of the system fluid.			
Resample			?	Resample in 30-45 days to monitor this situation.			
Check Breathers			?	The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather.			
Check Dirt Access			?	We advise that you check all areas where contaminants can enter the system.			
Filter Fluid			?	We advise that you perform a filter service, and use off-line filtration to improve the cleanliness of the system fluid.			

HISTORICAL DIAGNOSIS

ISO



04 Apr 2024 Diag: Kevin Marson

Check seals and/or filters for points of contaminant entry. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. We recommend you service the filters on this component. Resample in 30-45 days to monitor this situation. All component wear rates are normal. There is a high amount of silt (particulates < 14 microns in size) present in the oil. The AN level is acceptable for this fluid. The oil is still serviceable provided that the contaminant(s) can be reduced to acceptable levels.



ISO



01 Apr 2024 Diag: Kevin Marson

Check seals and/or filters for points of contaminant entry. We advise that you check all areas where contaminants can enter the system. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. We advise that you follow the water drain-off procedure for this component. We advise that you perform a filter service, and use off-line filtration to improve the cleanliness of the system fluid. Resample in 30-45 days to monitor this situation.All component wear rates are normal. There is a high amount of particulates (2 to 100 microns in size) present in the oil. Free water present. The AN level is acceptable for this fluid. The oil is still serviceable provided that the contaminant(s) can be reduced to acceptable levels.





05 Jan 2024 Diag: Bill Quesnel

Check seals and/or filters for points of contaminant entry. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. We recommend you service the filters on this component. Resample in 30-45 days to monitor this situation. All component wear rates are normal. There is a high amount of silt (particulates < 14 microns in size) present in the oil. The AN level is acceptable for this fluid. The oil is still serviceable provided that the contaminant(s) can be reduced to acceptable levels.






OIL ANALYSIS REPORT

Area

5 Utilities/030 Boiler House/B Blower/Fan/713A #13 FD West N/A 30TB713A

Turbine

PETRO CANADA TURBOFLO 68 (20 LTR)



Sample Rating Trend



DIAGNOSIS

Recommendation

We advise that you check all areas where contaminants can enter the system. We advise that you perform a filter service, and use off-line filtration to improve the cleanliness of the system fluid. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. Resample in 30-45 days to monitor this situation.

Wear

All component wear rates are normal.

Contamination

There is a high amount of particulates (2 to 100 microns in size) present in the oil. The water content is negligible.

Fluid Condition

The AN level is acceptable for this fluid. The oil is still serviceable provided that the contaminant(s) can be reduced to acceptable levels.

		12013 Mar20	14 Oct2015 May2017	Apr2018 Dec2019 Apr2021	Nov2023	
SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		WC0957470	WC	WC0925274
Sample Date		Client Info		02 Jul 2024	04 Apr 2024	01 Apr 2024
Machine Age	hrs	Client Info		0	0	0
Oil Age	hrs	Client Info		0	0	0
Oil Changed		Client Info		N/A	N/A	N/A
Sample Status				SEVERE	SEVERE	SEVERE
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185(m)	>15	<1	<1	3
Chromium	ppm	ASTM D5185(m)	>4	0	0	0
Nickel	ppm	ASTM D5185(m)	>2	<1	0	0
Titanium	ppm	ASTM D5185(m)		0	0	0
Silver	ppm	ASTM D5185(m)		0	0	0
Aluminum	ppm	ASTM D5185(m)	>10	0	0	0
Lead	ppm	ASTM D5185(m)		0	0	0
Copper	ppm	ASTM D5185(m)	>5	<1	<1	<1
Tin	ppm	ASTM D5185(m)	>5	0	0	0
Antimony	ppm	ASTM D5185(m)		0	0	0
Vanadium	ppm	ASTM D5185(m)		0	0	0
Beryllium	ppm	ASTM D5185(m)		0	0	0
Cadmium	ppm	ASTM D5185(m)		0	0	0
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185(m)	0	<1	0	0
Barium	ppm	ASTM D5185(m)	0	0	0	0
Molybdenum	ppm	ASTM D5185(m)	0	0	0	0
Manganese	ppm	ASTM D5185(m)	0	0	0	0
Magnesium	ppm	ASTM D5185(m)	0	<1	0	0
Calcium	ppm	ASTM D5185(m)	0	<1	<1	<1
Phosphorus	ppm	ASTM D5185(m)	120	<1	0	0
Zinc	ppm	ASTM D5185(m)	0.0	<1	<1	<1
Sulfur	ppm	ASTM D5185(m)	50	580	569	574
Lithium	ppm	ASTM D5185(m)		<1	<1	<1
CONTAMINANTS	3	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185(m)	>15	0	0	0
Sodium	ppm	ASTM D5185(m)		0	0	0
Potassium	ppm	ASTM D5185(m)	>20	0	0	0
Water	%	ASTM D6304*	>0.03	0.003		
ppm Water	ppm	ASTM D6304*	>300	26		
FLUID CLEANLIN	IESS	method	limit/base	current	history1	history2
Particles >4µm		ASTM D7647	>2500	36599	▲ 36044	▲ 114427
Particles >6µm		ASTM D7647		▲ 8884	▲ 3260	36630
Particles >14µm		ASTM D7647	>80	<u> </u>	17	▲ 623
Particles >21µm		ASTM D7647		▲ 186	3	<u> </u>
Particles >38µm		ASTM D7647	>4	<u>△</u> 27	1	3
Particles >71µm		ASTM D7647		2	1	1
			. •	_		

ISO 4406 (c) >18/16/13 **22/20/16**


Oil Cleanliness


24/22/16


22/19/11





OIL ANALYSIS REPORT
















Color









CALA ISO 17025:2017 Accredited

Laboratory

Laboratory

Sample No. Lab Number Unique Number : 5812256

: WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9 : WC0957470

: 02646704

Received : 09 Jul 2024 **Tested** : 11 Jul 2024

Diagnosed : 11 Jul 2024 - Kevin Marson

Test Package : IND 2 (Additional Tests: KF, TAN Man) To discuss this sample report, contact Customer Service at 1-800-268-2131.

Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab. Validity of results and interpretation are based on the sample and information as supplied.

Petro Canada Lubricants Inc.

385 Southdown Road Mississauga, ON CA L5J 2Y3 Contact: Kyle Blezard kyle.blezard@HFSinclair.com

T: (905)403-6768 F: (905)822-6025

Submitted By: ?