


PROBLEM SUMMARY

Sample Rating Trend




Machine Id

KHS L3 MAIN

Gearbox

KLUBER KLUBEROIL 4 UH1-460 N (--- GAL)

COMPONENT CONDITION SUMMARY



RECOMMENDATION

We advise that you check for the source of water entry. Check seals and/or filters for points of contaminant entry. We advise that you check all areas where dirt can enter the system. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. We recommend that you drain the oil from the component if this has not already been done. Confirm the source of the lubricant being utilized for top-up/fill. We recommend an early resample to monitor this condition. NOTE: Please provide information regarding reservoir capacity, filter type and micron rating with next sample.

PROBLEMATIC TEST RESULTS									
Sample Status				SEVERE					
Aluminum	ppm	ASTM D5185(m)	>25	144					
Silicon	ppm	ASTM D5185(m)	>50	108					
Water	%	ASTM D6304*	>0.2	△ 0.475					
ppm Water	ppm	ASTM D6304*	>2000	4757					
Appearance	scalar	Visual*	NORML	▲ MILKY					
Emulsified Water	scalar	Visual*	>0.2	.2 %					

Customer Id: COC15BRA **Sample No.:** WC0953990 Lab Number: 02648242 Test Package: IND 1



To manage this report scan the QR code

To discuss the diagnosis or test data: Kevin Marson +1 (289)291-4644 x4644 Kevin.Marson@wearcheck.com

To change component or sample information: Gloria Gonzalez +1 (289)291-4643 x4643 gloria.gonzalez@wearcheck.com


RECOMMENDED ACTIONS							
Action	Status	Date	Done By	Description			
Change Fluid			?	We recommend that you drain the oil from the component if this has not already been done.			
Resample			?	We recommend an early resample to monitor this condition.			
Information Required			?	NOTE: Please provide information regarding reservoir capacity, filter type and micron rating with next sample.			
Check Breathers			?	The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather.			
Check Dirt Access			?	We advise that you check all areas where dirt can enter the system.			
Check Fluid Source			?	Confirm the source of the lubricant being utilized for top-up/fill.			
Check Water Access			?	We advise that you check for the source of water entry.			
Check Seals			?	Check seals and/or filters for points of contaminant entry.			

HISTORICAL DIAGNOSIS



OIL ANALYSIS REPORT

Sample Rating Trend





Machine Id

KHS L3 MAIN

Gearbox

KLUBER KLUBEROIL 4 UH1-460 N (--- GAL)

DIAGNOSIS

Recommendation

We advise that you check for the source of water entry. Check seals and/or filters for points of contaminant entry. We advise that you check all areas where dirt can enter the system. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. We recommend that you drain the oil from the component if this has not already been done. Confirm the source of the lubricant being utilized for top-up/fill. We recommend an early resample to monitor this condition. NOTE: Please provide information regarding reservoir capacity, filter type and micron rating with next sample.

Wear

Aluminum ppm levels are severe. Thrust washer and/or bearing/bushing wear is indicated.

Contamination

There is a moderate concentration of water present in the oil. There is a moderate concentration of dirt present in the oil. High amount of ingressed dirt has caused abrasive wear to the component.


Fluid Condition

Additive levels indicate the addition of a different brand, or type of oil. The oil is no longer serviceable as a result of the abnormal and/or severe wear.

.)		1		Jul2024		
SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		WC0953990		
Sample Date		Client Info		02 Jul 2024		
Machine Age	hrs	Client Info		0		
Oil Age	hrs	Client Info		0		
Oil Changed		Client Info		N/A		
Sample Status				SEVERE		
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185(m)	>200	35		
Chromium	ppm	ASTM D5185(m)	>15	<1		
Nickel	ppm	ASTM D5185(m)	>15	<1		
Titanium	ppm	ASTM D5185(m)		0		
Silver	ppm	ASTM D5185(m)		0		
Aluminum	ppm	ASTM D5185(m)	>25	144		
Lead	ppm	ASTM D5185(m)	>100	3		
Copper	ppm	ASTM D5185(m)	>200	37		
Tin	ppm	ASTM D5185(m)	>25	2		
Antimony	ppm	ASTM D5185(m)	>5	0		
Vanadium	ppm	ASTM D5185(m)		0		
Beryllium	ppm	ASTM D5185(m)		0		
Cadmium	ppm	ASTM D5185(m)		0		
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185(m)		3		
Barium	ppm	ASTM D5185(m)		0		
Molybdenum	ppm	ASTM D5185(m)		0		
Manganese	ppm	ASTM D5185(m)		<1		
Magnesium	ppm	ASTM D5185(m)		3		
Calcium	ppm	ASTM D5185(m)		739		
Phosphorus	ppm	ASTM D5185(m)		810		
Zinc	ppm	ASTM D5185(m)		2007		
Sulfur	ppm	ASTM D5185(m)		1448		
Lithium	ppm	ASTM D5185(m)		<1		
CONTAMINANTS	3	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185(m)	>50	108		
Sodium	ppm	ASTM D5185(m)		961		
Potassium	ppm	ASTM D5185(m)	>20	16		
Water	%	ASTM D6304*	>0.2	0.475		
ppm Water	ppm	ASTM D6304*	>2000	4757		



OIL ANALYSIS REPORT





CALA ISO 17025:2017 Accredited Laboratory

Laboratory Sample No.

: WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9 COCA COLA CANADA BOTTLING LTD.

Lab Number : 02648242 Unique Number : 5813794

: WC0953990

Received : 16 Jul 2024 **Tested** : 19 Jul 2024 Diagnosed

: 19 Jul 2024 - Kevin Marson

BRAMPTON, ON **CA L6T 5T4** Contact: Chandan Ahuja

cahuja@cokecanada.com T: (635)440-5087

15 WEST CREEK BLVD

Test Package : IND 1 (Additional Tests: KF) To discuss this sample report, contact Customer Service at 1-800-268-2131.

Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab. Validity of results and interpretation are based on the sample and information as supplied.