

# **PROBLEM SUMMARY**

Sample Rating Trend



Area


# PUMPHOUSE/HOOD COOLING PUMPS C - Hood Cooling 2 Electric Pump IB

Lube System

Fluid

PETRO CANADA HYDREX AW 100 (1 GAL)

# COMPONENT CONDITION SUMMARY



# RECOMMENDATION

We advise that you check all areas where contaminants can enter the system. We advise that you perform a filter service, and use off-line filtration to improve the cleanliness of the system fluid. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. Resample in 30-45 days to monitor this situation.

PROBLEMATIC TEST RESULTS									
Sample Status		SEVERE	SEVERE	SEVERE					
Particles >4µm	ASTM D7647 >5000	<b>124539</b>	▲ 239928	<b>▲</b> 95253					
Particles >6μm	ASTM D7647 >1300	<b>49624</b>	<b>2</b> 06511	<b>▲</b> 23382					
Particles >14µm	ASTM D7647 >160	<b>2835</b>	▲ 86020	<b>1</b> 655					
Particles >21µm	ASTM D7647 >40	<b>4</b> 391	▲ 32309	<b>427</b>					
Oil Cleanliness	ISO 4406 (c) >19/17/	14 <b>4 24/23/19</b>	<b>1</b> 25/25/24	<b>4</b> 24/22/18					

Customer Id: LEWBOSC Sample No.: WC0968451 Lab Number: 02648441 Test Package: IND 2



To manage this report scan the QR code

To discuss the diagnosis or test data: Kevin Marson +1 (289)291-4644 x4644 Kevin.Marson@wearcheck.com

To change component or sample information: Gloria Gonzalez +1 (289)291-4643 x4643 gloria.gonzalez@wearcheck.com

RECOMMENDED ACTIONS							
Action	Status	Date	Done By	Description			
Change Filter			?	We advise that you perform a filter service, and use off-line filtration to improve the cleanliness of the system fluid.			
Resample			?	Resample in 30-45 days to monitor this situation.			
Check Breathers			?	The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather.			
Check Dirt Access			?	We advise that you check all areas where contaminants can enter the system.			
Filter Fluid			?	We advise that you perform a filter service, and use off-line filtration to improve the cleanliness of the system fluid.			

## HISTORICAL DIAGNOSIS

ISO



# 10 Jan 2024 Diag: Kevin Marson

Check seals and/or filters for points of contaminant entry. We advise that you check all areas where contaminants can enter the system. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. We advise that you follow the water drain-off procedure for this component. We advise that you perform a filter service, and use off-line filtration to improve the cleanliness of the system fluid. Resample in 30-45 days to monitor this situation.All component wear rates are normal. There is a high amount of particulates (2 to 100 microns in size) present in the oil. There is a moderate concentration of water present in the oil. Free water present. The system cleanliness code is much higher than the acceptable limit for the target ISO 4406 cleanliness code. The AN level is acceptable for this fluid. The oil is still serviceable provided that the contaminant(s) can be reduced to acceptable levels.



ISO



## 16 Aug 2023 Diag: Kevin Marson

We advise that you check all areas where contaminants can enter the system. We advise that you check for visible metal particles in the oil. We advise that you perform a filter service, and use off-line filtration to improve the cleanliness of the system fluid. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. Resample in 30-45 days to monitor this situation. We suspect that the abnormal contaminant(s) is the result of incorrect sampling technique. DISCLAIMER: Interpretation of results is based on the sample as received from the customer. The condition of the sample and the method of sampling cannot be verified. Light concentration of visible metal present. There is a high amount of particulates (2 to 100 microns in size) present in the oil. Light concentration of visible dirt/debris present in the oil. The system cleanliness code is much higher than the acceptable limit for the target ISO 4406 cleanliness code. The AN level is acceptable for this fluid. The oil is no longer serviceable as a result of the abnormal and/or severe wear.



ISO.



## 31 May 2023 Diag: Bill Quesnel

We advise that you check all areas where contaminants can enter the system. We advise that you perform a filter service, and use off-line filtration to improve the cleanliness of the system fluid. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. Resample in 30-45 days to monitor this situation. All component wear rates are normal. There is a high amount of particulates (2 to 100 microns in size) present in the oil. The system cleanliness code is much higher than the acceptable limit for the target ISO 4406 cleanliness code. The AN level is acceptable for this fluid. The oil is still serviceable provided that the contaminant(s) can be reduced to acceptable levels.






# **OIL ANALYSIS REPORT**

# **PUMPHOUSE/HOOD COOLING PUMPS** C - Hood Cooling 2 Electric Pump IB

**Lube System** 

PETRO CANADA HYDREX AW 100 (1 GAL)





# DIAGNOSIS

#### Recommendation

We advise that you check all areas where contaminants can enter the system. We advise that you perform a filter service, and use off-line filtration to improve the cleanliness of the system fluid. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. Resample in 30-45 days to monitor this situation.

#### Wear

All component wear rates are normal.

## ▲ Contamination

There is a high amount of particulates (2 to 100 microns in size) present in the oil. The system cleanliness code is much higher than the acceptable limit for the target ISO 4406 cleanliness code.


# **Fluid Condition**

The AN level is acceptable for this fluid. The oil is still serviceable provided that the contaminant(s) can be reduced to acceptable levels.

SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		WC0968451	WC0898658	WC0850127
Sample Date		Client Info		17 Jul 2024	10 Jan 2024	16 Aug 2023
Machine Age	hrs	Client Info		0	0	0
Oil Age	hrs	Client Info		0	0	0
Oil Changed		Client Info		N/A	N/A	N/A
Sample Status				SEVERE	SEVERE	SEVERE
CONTAMINATION	١	method	limit/base	current	history1	history2
Water		WC Method	>5	NEG	NEG	NEG
WEAR METALS		method	limit/base	current	history1	history2
PQ		ASTM D8184*	>DFLT	0	0	0
Iron	ppm	ASTM D5185(m)	>20	28	14	19
Chromium	ppm	ASTM D5185(m)	>20	<1	0	<1
Nickel	ppm	ASTM D5185(m)	>20	0	<1	<1
Titanium	ppm	ASTM D5185(m)		0	0	0
Silver	ppm	ASTM D5185(m)		0	0	0
Aluminum	ppm	ASTM D5185(m)	>20	<1	<1	<1
Lead	ppm	ASTM D5185(m)	>20	0	<1	0
Copper	ppm	ASTM D5185(m)	>20	<1	<1	<1
Tin	ppm	ASTM D5185(m)	>20	0	0	0
Antimony	ppm	ASTM D5185(m)		0	0	0
Vanadium	ppm	ASTM D5185(m)		0	0	0
Beryllium	ppm	ASTM D5185(m)		0	0	0
Cadmium	ppm	ASTM D5185(m)		0	0	0
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185(m)	0	0	<1	<1
Barium	ppm	ASTM D5185(m)	0	<1	<1	<1
Molybdenum	ppm	ASTM D5185(m)	0	0	0	0
Manganese	ppm	ASTM D5185(m)	0	<1	0	<1
Magnesium	ppm	ASTM D5185(m)	0	<1	1	1
Calcium	ppm	ASTM D5185(m)	50	55	51	52
Phosphorus	ppm	ASTM D5185(m)	330	337	339	351
Zinc	ppm	ASTM D5185(m)	430	419	423	412
Sulfur	ppm	ASTM D5185(m)	760	2581	2731	2584
Lithium	ppm	ASTM D5185(m)		<1	<1	<1
CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185(m)	>15	4	6	4
Sodium	ppm	ASTM D5185(m)		16	80	5
Potassium	ppm	ASTM D5185(m)	>20	<1	1	<1



# OIL ANALYSIS REPORT





CALA ISO 17025:2017 Accredited Laboratory

Laboratory

Sample No. Lab Number

: WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9

: 02648441

Unique Number : 5813993

: WC0968451 Received **Tested** 

Diagnosed Test Package : IND 2 ( Additional Tests: Bottom, PQ ) : 17 Jul 2024

: 18 Jul 2024

To discuss this sample report, contact Customer Service at 1-800-268-2131. Test denoted (\*) outside scope of accreditation, (m) method modified, (e) tested at external lab. Validity of results and interpretation are based on the sample and information as supplied.

STELCO - BOSC - Basic Oxygen Slab Caster

2330 Regional Road #3, Door: BOSC8 NANTICOKE, ON CA NOA 1L0 : 18 Jul 2024 - Kevin Marson

Contact: Tom Walden Thomas.Walden@stelco.com

T: (519)587-4541 F: (519)587-7702

Submitted By: Bob Melanson