

PROBLEM SUMMARY


WOOD SUPPLY **FALK 0120 CC01**

Component Gearbox

SUMMIT SINGEAR SH 1022 (10 LTR)

Sample Rating Trend ISO

COMPONENT CONDITION SUMMARY



RECOMMENDATION

We recommend you service the filters on this component. We recommend an early resample to monitor this condition.

PROBLEMATIC TEST RESULTS									
Sample Status			ABNORMAL	ABNORMAL	SEVERE				
Particles >4µm	ASTM D7647	>20000	<u> </u>	<u>41461</u>	68282				
Particles >6µm	ASTM D7647	>5000	19075	2100	4 083				
Oil Cleanliness	ISO 4406 (c)	>21/19/16	<u> 24/21/13</u>	<u>\</u> 23/18/12	23/19/12				

Customer Id: FLAMONNC **Sample No.:** WC0730510 Lab Number: 05844421 Test Package: IND 2

To manage this report scan the QR code

To discuss the diagnosis or test data: Wes Davis +1 905-569-8600 x223 wesd@wearcheck.ca

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

Action Status Date Done By Description Change Filter MISSED Sep 22 2023 ? We recommend you service the filters on this component. Resample MISSED Sep 22 2023 ? We recommend an early resample to monitor this condition.

HISTORICAL DIAGNOSIS

15 Nov 2022 Diag: Wes Davis



We recommend you service the filters on this component. We recommend an early resample to monitor this condition. All component wear rates are normal. Oil Cleanliness are abnormally high. Particles $>4\mu m$ are abnormally high. The water content is negligible. The system cleanliness is above the acceptable limit for the target ISO 4406 cleanliness code. The AN level is acceptable for this fluid. The oil is still serviceable provided that the contaminant(s) can be reduced to acceptable levels.



(X)

17 Aug 2022 Diag: Wes Davis

Check seals and/or filters for points of contaminant entry. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. We recommend you service the filters on this component. Resample in 30-45 days to monitor this situation. All component wear rates are normal. Oil Cleanliness are severely high. Particles >6µm are abnormally high. The water content is negligible. The system cleanliness code is much higher than the acceptable limit for the target ISO 4406 cleanliness code. The AN level is acceptable for this fluid. The oil is still serviceable provided that the contaminant(s) can be reduced to acceptable levels.







Check seals and/or filters for points of contaminant entry. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. We recommend you service the filters on this component. Resample in 30-45 days to monitor this situation.All component wear rates are normal. Oil Cleanliness are severely high. Particles $>4\mu m$ are severely high. Particles $>6\mu m$ are abnormally high. The system cleanliness code is much higher than the acceptable limit for the target ISO 4406 cleanliness code. The AN level is acceptable for this fluid. The oil is still serviceable provided that the contaminant(s) can be reduced to acceptable levels.





OIL ANALYSIS REPORT

ORT

method

SAMPLE INFORMATION

ISO

history2

history1

WOOD SUPPLY Machine Id FALK 0120 CC01

Component

Gearbox

SUMMIT SINGEAR SH 1022 (10 LTR)

DIAGNOSIS

Recommendation

We recommend you service the filters on this component. We recommend an early resample to monitor this condition.

Wear


All component wear rates are normal.

Contamination

There is a moderate amount of silt (particulates < 14 microns in size) present in the oil. The system cleanliness is above the acceptable limit for the target ISO 4406 cleanliness code.

Fluid Condition


The AN level is acceptable for this fluid. The oil is still serviceable provided that the contaminant(s) can be reduced to acceptable levels.



Sample Number		Client Info		WC0730510	WC0668089	WC0635777
Sample Date		Client Info		13 Feb 2023	15 Nov 2022	17 Aug 2022
Machine Age	hrs	Client Info		0	0	0
Oil Age	hrs	Client Info		0	0	0
Oil Changed		Client Info		N/A	Not Changd	N/A
Sample Status				ABNORMAL	ABNORMAL	SEVERE
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>200	21	16	15
Chromium	ppm	ASTM D5185m	>15	0	0	0
Nickel	ppm	ASTM D5185m	>15	0	0	0
Titanium	ppm	ASTM D5185m		0	0	0
Silver	ppm	ASTM D5185m		0	0	<1
Aluminum	ppm	ASTM D5185m	>25	0	0	<1
Lead	ppm	ASTM D5185m	>100	0	0	0
Copper	ppm	ASTM D5185m	>200	0	0	<1
Tin	ppm	ASTM D5185m	>25	0	0	<1
Vanadium	ppm	ASTM D5185m		0	0	0
Cadmium	ppm	ASTM D5185m		0	0	<1
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m		147	134	146
Barium	ppm	ASTM D5185m		0	1	0
Molybdenum	ppm	ASTM D5185m		0	0	0
Manganese	ppm	ASTM D5185m		<1	<1	<1
Magnesium	ppm	ASTM D5185m		<1	0	<1
Calcium	ppm	ASTM D5185m		<1	2	2
Phosphorus	ppm	ASTM D5185m		511	503	530
Zinc	ppm	ASTM D5185m		0	<1	0
Sulfur	ppm	ASTM D5185m		9787	8930	9352
CONTAMINANTS	8	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>50	3	1	5
Sodium	ppm	ASTM D5185m		0	0	0
Potassium	ppm	ASTM D5185m	>20	0	1	<1
FLUID CLEANLIN	NESS	method	limit/base	current	history1	history2
Particles >4µm		ASTM D7647	>20000	<u> </u>	<u>41461</u>	68282
Particles >6µm		ASTM D7647	>5000	<u> </u>	2100	△ 4083
Particles >14µm		ASTM D7647	>640	47	29	22
Particles >21µm		ASTM D7647	>160	6	7	5
Particles >38µm		ASTM D7647	>40	0	2	3
Particles >71μm		ASTM D7647	>10	0	1	2
Oil Cleanliness		ISO 4406 (c)	>21/19/16	<u>4</u> 24/21/13	<u>△</u> 23/18/12	23/19/12
FLUID DEGRADA	ATION	method	limit/base	current	history1	history2
Acid Number (AN)	mg KOH/g	ASTM D8045		0.99	0.90	0.98



OIL ANALYSIS REPORT







Certificate L2367

Laboratory Sample No. **Unique Number**

Lab Number

: 05844421 : 10468528

180

Received : WC0730510 Diagnosed

: 11 May 2023 : 12 May 2023 : Wes Davis Diagnostician

Aug17/22

May18/21

: WearCheck USA - 501 Madison Ave., Cary, NC 27513

Test Package : IND 2 (Additional Tests: PrtCount)

Jan 12/17

To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

ARAUCO FLAKEBOARD - MDF

985 CORINTH RD MONCURE, NC US

Aug17/22,

Contact: CHRISTOPHER JACKSON christopher.jackson@arauco.com

T: F:

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

P 0.00

Feb13/23