

PROBLEM SUMMARY

Sample Rating Trend

FUEL






CATERPILLAR C15 HOBBS GENERATOR


Component

Diesel Engine

SHELL ROTELLA T 15W40 (--- GAL)

COMPONENT CONDITION SUMMARY





RECOMMENDATION

We recommend that you drain the oil from the component if this has not already been done. We recommend an early resample to monitor this condition.

PROBLEMATIC TEST RESULTS									
Sample Status				ABNORMAL	ABNORMAL	ABNORMAL			
Fuel	%	ASTM D3524	>5	△ 6.0	△ 6.2	△ 5.4			
Visc @ 100°C	cSt	ASTM D445	15.7	12.4	▲ 12.3	▲ 12.4			

Customer Id: RAMHOB Sample No.: KL0011667 Lab Number: 05902733 Test Package: FLEET



To manage this report scan the QR code

To discuss the diagnosis or test data: Wes Davis +1 905-569-8600 x223 wesd@wearcheck.ca

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

RECOMMENDED ACTIONS

Action	Status	Date	Done By	Description
Change Fluid			?	We recommend that you drain the oil from the component if this has not already been done.
Resample			?	We recommend an early resample to monitor this condition.

HISTORICAL DIAGNOSIS

25 May 2023 Diag: Wes Davis

FUEL



We recommend that you drain the oil from the component if this has not already been done. We recommend an early resample to monitor this condition. All component wear rates are normal. There is a moderate amount of fuel present in the oil. The system cleanliness is acceptable for your target ISO 4406 cleanliness code. Tests confirm the presence of fuel in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. The oil is no longer serviceable due to the presence of contaminants.



21 Apr 2023 Diag: Jonathan Hester

WEAR



We advise that you check the fuel injection system. Resample at the next service interval to monitor. The copper level is abnormal. In the absence of other significant wear metals, suspect copper due to sources other than wear (i.e. cooling core). There is a moderate amount of fuel present in the oil. Fuel is present in the oil and is lowering the viscosity. The BN result indicates that there is suitable alkalinity remaining in the oil.

view report

23 Mar 2023 Diag: Doug Bogart

WEAR



No corrective action is recommended at this time. Resample at the next service interval to monitor. The copper level is abnormal. In the absence of other significant wear metals, suspect copper due to sources other than wear (i.e. cooling core). All other component wear rates are normal. There is no indication of any contamination in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.






OIL ANALYSIS REPORT



CATERPILLAR C15 HOBBS GENERATOR

Component **Diesel Engine**

SHELL ROTELLA T 15W40 (--- GAL)





DIAGNOSIS

Recommendation

We recommend that you drain the oil from the component if this has not already been done. We recommend an early resample to monitor this condition.

Wear

All component wear rates are normal.

Contamination

There is a moderate amount of fuel present in the oil. Tests confirm the presence of fuel in the oil.

Fluid Condition

The BN result indicates that there is suitable alkalinity remaining in the oil. The oil is no longer serviceable due to the presence of contaminants.

II-IO (GAL)		Mar2022	Jun2022 Sep2022	Dec2022 Mar2023 M	ay2023	
SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		KL0011667	KL0012433	KL0011467
Sample Date		Client Info		22 Jun 2023	25 May 2023	21 Apr 2023
Machine Age	hrs	Client Info		0	45069	0
Oil Age	hrs	Client Info		0	0	0
Oil Changed		Client Info		N/A	N/A	N/A
Sample Status				ABNORMAL	ABNORMAL	ABNORMAL
CONTAMINATIO	V	method	limit/base	current	history1	history2
Glycol		WC Method		NEG	0.0	NEG
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>100	10	9	8
Chromium	ppm	ASTM D5185m	>6	0	<1	0
Nickel	ppm	ASTM D5185m	>4	<1	0	0
Titanium	ppm	ASTM D5185m	>2	0	0	0
Silver	ppm	ASTM D5185m	>2	0	0	0
Aluminum	ppm	ASTM D5185m	>30	4	<1	5
Lead	ppm	ASTM D5185m	>10	8	8	11
Copper	ppm	ASTM D5185m	>150	362	374	443
Tin	ppm	ASTM D5185m	>4	<1	<1	0
Vanadium	ppm	ASTM D5185m		0	0	0
Cadmium	ppm	ASTM D5185m		0	0	0
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m	316	293	270	282
Barium	ppm	ASTM D5185m	0.0	0	0	0
Molybdenum	ppm	ASTM D5185m	1.2	97	96	103
Manganese	ppm	ASTM D5185m		<1	<1	0
Magnesium	ppm	ASTM D5185m	24	435	497	532
Calcium	ppm	ASTM D5185m	2292	1722	1846	1888
Phosphorus	ppm	ASTM D5185m	1064	858	901	945
Zinc	ppm	ASTM D5185m	1160	1064	1135	1183
Sulfur	ppm	ASTM D5185m	4996	2868	3631	3656
CONTAMINANTS	5	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>20	5	5	4
Sodium	ppm	ASTM D5185m		0	1	1
Potassium	ppm	ASTM D5185m	>20	3	2	2
Fuel	%	ASTM D3524	>5	△ 6.0	△ 6.2	<u></u> 5.4
INFRA-RED		method	limit/base	current	history1	history2
Soot %	%	*ASTM D7844	>3	0.1	0.1	0.1
Nitration	Abs/cm	*ASTM D7624	>20	10.0	10.3	9.9
Sulfation	Abs/.1mm	*ASTM D7415	>30	23.8	23.9	24.2
FLUID DEGRADA	ATION	method	limit/base	current	history1	history2
Oxidation	Abs/.1mm	*ASTM D7414	>25	22.4	22.1	22.8
Base Number (BN)	mg KOH/g	ASTM D2896	10.1	8.0	11.29	7.9



OIL ANALYSIS REPORT







Certificate L2367

Laboratory Sample No. Lab Number **Unique Number**

: KL0011667

: 05902733 : 10564089

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 19 Jul 2023 Diagnosed

: 21 Jul 2023 Diagnostician : Wes Davis

0.0

Test Package : FLEET (Additional Tests: PercentFuel) To discuss this sample report, contact Customer Service at 1-800-237-1369.

Jun17/22

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012) **RAMIREZ & SONS**

3404 N ENTERPRISE DR HOBBS, NM US 88240

Contact: Rick Davidson

rickdavidson.rsi@gmail.com

T: F:

Report Id: RAMHOB [WUSCAR] 05902733 (Generated: 07/21/2023 09:56:18) Rev: 1

Contact/Location: Rick Davidson - RAMHOB