

PROBLEM SUMMARY

Component
Inboard Journal Bearing
Fluid
ESSO NUTO H ISO 68 (1 QTS)





COMPONENT CONDITION SUMMARY

71 BANBURY MOTOR

No relevant graphs to display

RECOMMENDATION

The oil change at the time of sampling has been noted. We recommend you service the filters on this component if applicable. We recommend an early resample to monitor this condition. We were unable to perform a particle count due to metal particles present in this sample.

PROBLEMATIC TEST RESULTS								
Sample Status				ABNORMAL	ABNORMAL	ABNORMAL		
White Metal	scalar	*Visual	NONE	MODER	▲ MODER	▲ MODER		

Customer Id: BRIDES Sample No.: WC0397550 Lab Number: 05923336 Test Package: IND 2



To manage this report scan the QR code

To discuss the diagnosis or test data: Doug Bogart +1 (800)237-1369 x4016 dougb@wearcheckusa.com

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

RECOMMENDED ACTIONS

Action	Status	Date	Done By	Description
Change Filter			?	We recommend you service the filters on this component if applicable.
Resample			?	We recommend an early resample to monitor this condition.
Alert			?	We were unable to perform a particle count due to metal particles present in this sample.

HISTORICAL DIAGNOSIS

05 Jul 2023 Diag: Angela Borella

VISUAL METAL



The oil change at the time of sampling has been noted. We advise that you inspect for the source(s) of wear. We recommend an early resample to monitor this condition. We were unable to perform a particle count due to metal particles present in this sample. The tin level is abnormal. Moderate concentration of visible metal present. All other component wear rates are normal. No other contaminants were detected in the oil. The AN level is acceptable for this fluid. The condition of the oil is acceptable for the time in service.



09 Apr 2023 Diag: Don Baldridge

VISUAL METAL



The oil change at the time of sampling has been noted. We advise that you inspect for the source(s) of metal. We recommend an early resample to monitor this condition. We were unable to perform a particle count due to metal particles present in this sample. Moderate concentration of visible metal present. All component wear rates are normal. No other contaminants were detected in the oil. The AN level is acceptable for this fluid. The condition of the oil is acceptable for the time in service.



30 Dec 2022 Diag: Angela Borella

WEAR



The oil change at the time of sampling has been noted. We advise that you inspect for the source(s) of wear. We recommend an early resample to monitor this condition. A sharp increase in the tin level is noted. Bearing wear is indicated. There is a high amount of particulates present in the oil. The AN level is acceptable for this fluid. The condition of the oil is acceptable for the time in service.





OIL ANALYSIS REPORT

71 BANBURY MOTOR

Inboard Journal Bearing

ESSO NUTO H ISO 68 (1 QTS)

Sample Rating Trend



DIAGNOSIS

Recommendation

The oil change at the time of sampling has been noted. We recommend you service the filters on this component if applicable. We recommend an early resample to monitor this condition. We were unable to perform a particle count due to metal particles present in this sample.

Wear

Moderate concentration of visible metal present. All component wear rates are normal.

Contamination

No other contaminants were detected in the oil.

Fluid Condition

The AN level is acceptable for this fluid. The condition of the oil is acceptable for the time in

0.44404 5 1445004						
SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		WC0397550	WC0569517	WC0569576
Sample Date		Client Info		07 Aug 2023	05 Jul 2023	09 Apr 2023
Machine Age	mths	Client Info		1	6	0
Oil Age	mths	Client Info		0	0	4
Oil Changed		Client Info		Changed	Changed	Changed
Sample Status				ABNORMAL	ABNORMAL	ABNORMAL
WEAR METALS		method	limit/base	current	history1	history2
PQ		ASTM D8184		11	12	9
Iron	ppm	ASTM D5185m	>60	<1	2	0
Chromium	ppm	ASTM D5185m	>20	0	0	0
Nickel	ppm	ASTM D5185m	>20	0	0	0
Titanium	ppm	ASTM D5185m		<1	0	0
Silver	ppm	ASTM D5185m		<1	0	0
Aluminum	ppm	ASTM D5185m	>4	<1	<1	0
Lead	ppm	ASTM D5185m	>250	6	12	10
Copper	ppm	ASTM D5185m	>125	12	27	16
Tin	ppm	ASTM D5185m	>80	46	<u>→</u> 91	65
Vanadium	ppm	ASTM D5185m	700	<1	0	0
Cadmium	ppm	ASTM D5185m		<1	0	0
Caumum	ррпп			<1	U	0
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m	0	0	0	0
Barium	ppm	ASTM D5185m	0	<1	0	0
Molybdenum	ppm	ASTM D5185m	0	<1	<1	<1
Manganese	ppm	ASTM D5185m		<1	0	<1
Magnesium	ppm	ASTM D5185m	5	7	0	4
Calcium	ppm	ASTM D5185m	50	43	37	47
Phosphorus	ppm	ASTM D5185m	330	324	333	337
Zinc	ppm	ASTM D5185m	420	399	408	420
Sulfur	ppm	ASTM D5185m	3100	3196	3124	2702
CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>50	2	4	2
Sodium	ppm	ASTM D5185m		2	0	0
Potassium	ppm	ASTM D5185m	>20	<1	1	0
FLUID CLEANLIN	IESS	method	limit/base	current	history1	history2
Particles >4µm		ASTM D7647	>10000			
Particles >6µm		ASTM D7647	>2500			
Particles >14µm		ASTM D7647	>160			
Particles >21µm		ASTM D7647	>40			
Particles >38µm		ASTM D7647	>10			
Particles >71µm		ASTM D7647	>3			
Oil Cleanliness		ISO 4406 (c)	>20/18/14			
FLUID DEGRADA	TION	method	limit/base	current	history1	history2

Acid Number (AN)

mg KOH/g ASTM D8045 .40

0.45

0.43

0.49



OIL ANALYSIS REPORT







Laboratory Sample No. **Lab Number Unique Number**

: WC0397550 : 05923336 : 10603283

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received Diagnosed

: 14 Aug 2023

: 18 Aug 2023 Diagnostician : Doug Bogart

Test Package : IND 2 (Additional Tests: PQ, PrtCount) To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

BRIDGESTONE FIRESTONE - DES MOINES

4600 NW 2ND AVE DES MOINES, IA US 50313

Contact: SCOTT CARTER

CarterScottA@FirestoneAg.com T: x:

F: x: