

PROBLEM SUMMARY

Sample Rating Trend

V



Machine Id MLU-2
Component Inboard Pump
Fluid ROYAL PURPLE SYNFILM GT 32 (--- GAL)

COMPONENT CONDITION SUMMARY

No relevant graphs to display

RECOMMENDATION

We suspect abnormal metal contamination may be due to sampling method. No corrective action is recommended at this time. Resample at the next service interval to monitor.

PROBLEMATIC ¹	TEST RE	SULTS				
Sample Status				ABNORMAL	ABNORMAL	
White Metal	scalar	*Visual	NONE	▲ MODER	▲ MODER	

Customer Id: ENEKAR Sample No.: RP0032080 Lab Number: 05927336 Test Package: IND 2

To manage this report scan the QR code

To discuss the diagnosis or test data: Jonathan Hester +1 919-379-4092 x4092 jhester@wearcheckusa.com

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

RECOMMENDED ACTIONS

There are no recommended actions for this sample.

HISTORICAL DIAGNOSIS

21 Apr 2023 Diag: Jonathan Hester

VISUAL METAL




We suspect abnormal metal contamination may be due to sampling method. No corrective action is recommended at this time. Resample at the next service interval to monitor. Moderate concentration of visible metal present. All component wear rates are normal. There is no indication of any contamination in the oil. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.





OIL ANALYSIS REPORT







MLU-2 Component **Inboard Pump**

DIAGNOSIS

Recommendation

Wear


Contamination

Fluid Condition

OYAL PURPLE SYNFILM GT 32 (GAL)				Apr2023	Jul2023		
DIAGNOSIS	SAMPLE INFORM	MATION	method	limit/base	current	history1	history
Recommendation	Sample Number		Client Info		RP0032080	RP0033383	
e suspect abnormal metal contamination may be	Sample Date		Client Info		31 Jul 2023	21 Apr 2023	
e to sampling method. No corrective action is	Machine Age	hrs	Client Info		0	0	
commended at this time. Resample at the next	Oil Age	hrs	Client Info		0	0	
rvice interval to monitor.	Oil Changed		Client Info		N/A	N/A	
Wear	Sample Status				ABNORMAL	ABNORMAL	
oderate concentration of visible metal present. All imponent wear rates are normal.	WEAR METALS		method	limit/base	current	history1	history
ontamination	Iron	ppm	ASTM D5185m	>90	0	<1	
ere is no indication of any contamination in the	Chromium	ppm	ASTM D5185m	>5	0	0	
	Nickel	ppm	ASTM D5185m	>5	0	0	
uid Condition	Titanium	ppm	ASTM D5185m	>3	<1	0	
e AN level is acceptable for this fluid. The	Silver	ppm	ASTM D5185m	>3	0	0	
ndition of the oil is suitable for further service.	Aluminum	ppm	ASTM D5185m	>7	<1	<1	
	Lead	ppm	ASTM D5185m		<1	0	
	Copper	ppm	ASTM D5185m		2	2	
	Tin	ppm	ASTM D5185m		3	5	
	Vanadium	ppm	ASTM D5185m		<1	<1	
	Cadmium	ppm	ASTM D5185m		0	0	
	ADDITIVES		method	limit/base	current	history1	history
	Boron	ppm	ASTM D5185m		0	0	
	Barium	ppm	ASTM D5185m		0	0	
	Molybdenum	ppm	ASTM D5185m		0	0	
	Manganese	ppm	ASTM D5185m		<1	<1	
	Magnesium	ppm	ASTM D5185m		86	81	
	Calcium	ppm	ASTM D5185m		1	<1	
	Phosphorus	ppm	ASTM D5185m		4	4	
	Zinc	ppm	ASTM D5185m		0	0	
	CONTAMINANTS	3	method	limit/base	current	history1	history
	Silicon	ppm	ASTM D5185m	>60	<1	<1	
	Sodium	ppm	ASTM D5185m		2	<1	
	Potassium	ppm	ASTM D5185m	>20	2	0	
	Water	%	ASTM D6304		0.023	0.018	
	ppm Water	ppm	ASTM D6304	>.1	238.1	187.9	
	FLUID DEGRADA	ATION	method	limit/base	current	history1	history
	Acid Number (AN)	mg KOH/g	ASTM D8045		0.34	0.36	
	VISUAL		method	limit/base	current	history1	history
	White Metal	scalar	*Visual	NONE	▲ MODER	▲ MODER	
	Yellow Metal	scalar	*Visual	NONE	NONE	NONE	
	Precipitate	scalar	*Visual	NONE	NONE	NONE	
	Silt	scalar	*Visual	NONE	NONE	NONE	
	Debris	scalar	*Visual	NONE	NONE	LIGHT	
	Sand/Dirt	scalar	*Visual	NONE	NONE	NONE	
	Appearance	scalar	*Visual	NORML	NORML	NORML	
	0-1	cooler	*Visual	NORML	NORML	NORML	
	Odor	scalar	Visuai	TACTUVIE	HOHIME	INOTHIVIE	
	Emulsified Water	scalar	*Visual	NOTHIVIE	NEG	NEG	



OIL ANALYSIS REPORT







Laboratory Sample No. Lab Number

Unique Number : 10607283

: RP0032080 : 05927336 Test Package : IND 2

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received Diagnosed

: 21 Aug 2023 Diagnostician : Jonathan Hester

: 17 Aug 2023

ENERGY TRANSFER - KARNACK

11398 SH-43 KARNACK, TX US 75661

Contact: Service Manager

To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

T:

F: