


PROBLEM SUMMARY

GUAY SON [CONHER] Machine Id BM SONORENSE II MAIN ENGINE


Component

Bottom Transmission (Manual)

RALOY SAE 50 (--- LTR)



COMPONENT CONDITION SUMMARY



RECOMMENDATION

No corrective action is recommended at this time. Resample at the next service interval to monitor. (Customer Sample Comment: Please Add particule count)

PROBLEMATIC TEST RESULTS									
Sample Status			ABNORMAL	ABNORMAL	SEVERE				
Particles >6µm	ASTM D7647	>2500	44967	<u>▲</u> 170885					
Oil Cleanliness	ISO 4406 (c)	>18/15	23/12	<u>\$\text{\scale}\$ 25/19</u>					

Customer Id: CONHERKL Sample No.: KL0012274 Lab Number: 05964564 Test Package: FLEET

To manage this report scan the QR code

To discuss the diagnosis or test data:

Don Baldridge +1 don.b505@comcast.net

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

RECOMMENDED ACTIONS

There are no recommended actions for this sample.

HISTORICAL DIAGNOSIS

15 Sep 2023 Diag: Don Baldridge

WEAR



We recommend you service the filters on this component. Resample at the next service interval to monitor. The iron level has decreased, but is still abnormal. All other component wear rates are normal. There is a high amount of silt (particulates < 14 microns in size) present in the fluid. The AN level is acceptable for this fluid. The condition of the fluid is acceptable for the time in service.



16 Jun 2023 Diag: Angela Borella

WEAR



We recommend that you drain the fluid and perform a filter service on this component if not already done. We advise that you inspect for the source(s) of wear. We recommend an early resample to monitor this condition. We were unable to perform a particle count due to a high concentration of particles present in this sample. Gear wear is indicated. There is a high amount of visible silt present in the sample. The AN level is acceptable for this fluid. The fluid is no longer serviceable as a result of the abnormal and/or severe wear.



01 Mar 2023 Diag: Jonathan Hester

WEAR



We recommend that you drain the fluid and perform a filter service on this component if not already done. We advise that you inspect for the source(s) of wear. We recommend an early resample to monitor this condition. Gear wear is indicated. There is a high amount of particulates present in the fluid. The AN level is acceptable for this fluid. The fluid is no longer serviceable as a result of the abnormal and/or severe wear.






OIL ANALYSIS REPORT

GUAY SON [CONHER] **BM SONORENSE II MAIN ENGINE**

Bottom Transmission (Manual)

RALOY SAE 50 (--- LTR)





DIAGNOSIS

Recommendation

No corrective action is recommended at this time. Resample at the next service interval to monitor. (Customer Sample Comment: Please Add particule count)

Wear

All component wear rates are normal.

Contamination

There is a high amount of silt (particulates < 14 microns in size) present in the fluid.

Fluid Condition

The AN level is acceptable for this fluid. The condition of the fluid is suitable for further service.

		Jan2020	Mar2022 Oct2022	Mar2023 Jun2023 Sep2023	Sep2023	
SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		KL0012274	KL0012804	KL0012383
Sample Date		Client Info		21 Sep 2023	15 Sep 2023	16 Jun 2023
Machine Age	hrs	Client Info		9848	9848	9838
Oil Age	hrs	Client Info		0	1120	3
Oil Changed		Client Info		Not Changd	Not Changd	Not Changd
Sample Status				ABNORMAL	ABNORMAL	SEVERE
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>200	68	▲ 338	1 740
Chromium	ppm	ASTM D5185m	>5	<1	1	3
Nickel	ppm	ASTM D5185m	>5	0	0	<1
Titanium	ppm	ASTM D5185m		0	0	<1
Silver	ppm	ASTM D5185m	>7	0	0	0
Aluminum	ppm	ASTM D5185m	>25	<1	<1	5
Lead	ppm	ASTM D5185m	>45	<1	8	5
Copper	ppm	ASTM D5185m	>225	<1	9	7
Tin	ppm	ASTM D5185m	>10	<1	0	<1
Vanadium	ppm	ASTM D5185m		0	0	<1
Cadmium	ppm	ASTM D5185m		0	0	0
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m		0	0	0
Barium	ppm	ASTM D5185m		0	0	0
Molybdenum	ppm	ASTM D5185m		0	<1	<1
Manganese	ppm	ASTM D5185m		1	3	7
Magnesium	ppm	ASTM D5185m		13	9	29
Calcium	ppm	ASTM D5185m		3492	2791	3206
Phosphorus	ppm	ASTM D5185m		986	732	861
Zinc	ppm	ASTM D5185m		867	665	778
Sulfur	ppm	ASTM D5185m		6693	5553	6712
CONTAMINANTS	3	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>125	18	8	14
Sodium	ppm	ASTM D5185m		0	<1	2
Potassium	ppm	ASTM D5185m	>20	0	<1	3
FLUID CLEANLIN	IESS	method	limit/base	current	history1	history2
Particles >4µm		ASTM D7647		146025	230295	
Particles >6µm		ASTM D7647	>2500	44967	▲ 170885	
Particles >14µm		ASTM D7647	>320	34	<u>▲</u> 4455	
Particles >21µm		ASTM D7647	>80	8	18	
Particles >38µm		ASTM D7647	>20	1	1	
Particles >71µm		ASTM D7647	>4	1	1	
Oil Cleanliness		ISO 4406 (c)	>18/15	<u>^</u> 23/12	2 5/19	
FLUID DEGRADA	ATION	method	limit/base	current	history1	history2
Acid Number (AN)	mg KOH/g	ASTM D8045		0.87	0.45	0.66



OIL ANALYSIS REPORT







Certificate L2367

Laboratory Sample No. Lab Number **Unique Number**

: KL0012274 : 05964564 : 10671115

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 : 29 Sep 2023 Received Diagnosed

: 02 Oct 2023 Diagnostician : Don Baldridge

Test Package : FLEET (Additional Tests: PrtCount) To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

CONOR JUAREZ 348 HERMOSILLO. MX 83140

Contact: EDUARDO GARCIA egarcia.comsa@gmail.com

T: (526)622-1581 x:81

F: x: