

PROBLEM SUMMARY

Sample Rating Trend

WATER




LINE 41 BMR 2ND BRIDGE

Component **Gearbox**

ENI AGIP TELLUM VSF 320 (--- LTR)

COMPONENT CONDITION SUMMARY



RECOMMENDATION

We advise that you check for the source of water entry. We advise that you follow the water drain-off procedure for this component. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. We recommend an early resample to monitor this condition.

PROBLEMATIC TEST RESULTS								
Sample Status				ABNORMAL				
Water	%	ASTM D6304	>0.2	△ 0.896				
ppm Water	ppm	ASTM D6304	>2000	A 8960				
Silt	scalar	*Visual	NONE	▲ MODER				
Appearance	scalar	*Visual	NORML	▲ SOLID				
Free Water	scalar	*Visual		△ 5.0				

Customer Id: FLOCLA Sample No.: KFS0004174 Lab Number: 05999154 Test Package: IND 2

To manage this report scan the QR code

To discuss the diagnosis or test data: Angela Borella +1 800-237-1369 angela.borella@wearcheckusa.com

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

RECOMMENDED ACTIONS							
Action	Status	Date	Done By	Description			
Water Drain-off			?	We advise that you follow the water drain-off procedure for this component.			
Resample			?	We recommend an early resample to monitor this condition.			
Check Breathers			?	The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather.			
Check Water Access			?	We advise that you check for the source of water entry.			

HISTORICAL DIAGNOSIS



OIL ANALYSIS REPORT

Sample Rating Trend



LINE 41 BMR 2ND BRIDGE

Component

Gearbox

ENI AGIP TELLUM VSF 320 (--- LTR)

DIAGNOSIS

Recommendation

We advise that you check for the source of water entry. We advise that you follow the water drain-off procedure for this component. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. We recommend an early resample to monitor this condition.

Wear

All component wear rates are normal.

Contamination

Appearance is solid. There is a moderate concentration of water present in the oil. Excessive free water present. There is a moderate amount of visible silt present in the sample.

Fluid Condition

The AN level is acceptable for this fluid. The condition of the oil is acceptable for the time in service.

				Oct2023		
SAMPLE INFORM	IATION	method	limit/base	current	history1	history2
Sample Number		Client Info		KFS0004174		
Sample Date		Client Info		26 Oct 2023		
Machine Age	hrs	Client Info		0		
Oil Age	hrs	Client Info		0		
Oil Changed		Client Info		N/A		
Sample Status				ABNORMAL		
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>200	8		
Chromium	ppm	ASTM D5185m	>15	<1		
Nickel	ppm	ASTM D5185m	>15	<1		
Titanium	ppm	ASTM D5185m		0		
Silver	ppm	ASTM D5185m		0		
Aluminum	ppm	ASTM D5185m	>25	3		
Lead	ppm	ASTM D5185m	>100	<1		
Copper	ppm	ASTM D5185m	>200	<1		
Tin	ppm	ASTM D5185m	>25	0		
Vanadium	ppm	ASTM D5185m		<1		
Cadmium	ppm	ASTM D5185m		<1		
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m		4		
Barium	ppm	ASTM D5185m		3		
Molybdenum	ppm	ASTM D5185m		0		
Manganese	ppm	ASTM D5185m		0		
Magnesium	ppm	ASTM D5185m		<1		
Calcium	ppm	ASTM D5185m		3		
Phosphorus	ppm	ASTM D5185m		712		
Zinc	ppm	ASTM D5185m		<1		
Sulfur	ppm	ASTM D5185m		889		
CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>50	1		
Sodium	ppm	ASTM D5185m		7		
Potassium	ppm	ASTM D5185m	>20	2		
Water	%	ASTM D6304	>0.2	△ 0.896		
ppm Water	ppm	ASTM D6304	>2000	A 8960		
FLUID DEGRADA	TION	method	limit/base	current	history1	history2
A si al Niversala a v. (ANI)	VOLV-	ACTM DODAE		0.07		


0.07

Acid Number (AN)

mg KOH/g ASTM D8045



OIL ANALYSIS REPORT







Certificate L2367

Laboratory Sample No. Lab Number **Unique Number**

: KFS0004174 : 05999154

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received

Diagnosed Test Package : IND 2 (Additional Tests: KF)

: 06 Nov 2023 : 07 Nov 2023 Diagnostician : Angela Borella

FLORIM 300 INTERNATIONAL CLARKSVILLE, TN US 37040 Contact: Service Manager

: 10727514 To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

T: F: