


PROBLEM SUMMARY

Sample Rating Trend

HOTLINE/130 REVERSING MILL 130 MAIN DRIVE PINION-INACTIVE 1414-014-0230


Component Gearbox

CITGO EP COMPOUND ISO 800 (--- GAL)





COMPONENT CONDITION SUMMARY



RECOMMENDATION

Check seals and/or filters for points of contaminant entry. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. We recommend you service the filters on this component. Resample in 30-45 days to monitor this situation. NOTE: Please provide information regarding reservoir capacity, filter type and micron rating with next sample.

PROBLEMATIC TEST RESULTS										
Sample Status		SEVERE	ABNORMAL	SEVERE						
Particles >4µm	ASTM D7647 >200	00 • 164991	<u>▲</u> 152408	168692						
Particles >6µm	ASTM D7647 >500	0 🔺 33215	<u> </u> 30211	▲ 32470						
Oil Cleanliness	ISO 4406 (c) >21/1	9/16 • 25/22/15	<u></u> 24/22/15	25/22/15						

Customer Id: CONMUSAL Sample No.: KFS0004924 Lab Number: 06007653 Test Package: IND 2



To manage this report scan the QR code

To discuss the diagnosis or test data: Wes Davis +1 905-569-8600 x223 wesd@wearcheck.ca

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

RECOMMENDED ACTIONS Action **Status** Date Done By Description Change Filter ? We recommend you service the filters on this component. Resample ? Resample in 30-45 days to monitor this situation. NOTE: Please provide information regarding reservoir capacity, filter type ? Information Required and micron rating with next sample. The air breather requires service. If unrated, we recommend that you replace with a **Check Breathers** ? suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather Check Seals Check seals and/or filters for points of contaminant entry.

HISTORICAL DIAGNOSIS

29 Sep 2023 Diag: Wes Davis

We recommend you service the filters on this component. We recommend an early resample to monitor this condition. NOTE: Please provide information regarding reservoir capacity, filter type and micron rating with next sample.All component wear rates are normal. There is a moderate amount of silt (particulates < 14 microns in size) present in the oil. The AN level is acceptable for this fluid. The oil is still serviceable provided that the contaminant(s) can be reduced to acceptable levels.



19 Jul 2023 Diag: Wes Davis



Check seals and/or filters for points of contaminant entry. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. We recommend you service the filters on this component. Resample in 30-45 days to monitor this situation. NOTE: Please provide information regarding reservoir capacity, filter type and micron rating with next sample. All component wear rates are normal. There is a high amount of silt (particulates < 14 microns in size) present in the oil. The AN level is acceptable for this fluid. The oil is still serviceable provided that the contaminant(s) can be reduced to acceptable levels.



23 Jun 2023 Diag: Wes Davis





We recommend you service the filters on this component. We recommend an early resample to monitor this condition. NOTE: Please provide information regarding reservoir capacity, filter type and micron rating with next sample.All component wear rates are normal. There is a moderate amount of silt (particulates < 14 microns in size) present in the oil. The AN level is acceptable for this fluid. The oil is still serviceable provided that the contaminant(s) can be reduced to acceptable levels.





OIL ANALYSIS REPORT


Sample Rating Trend

HOTLINE/130 REVERSING MILL 130 MAIN DRIVE PINION-INACTIVE 1414-014-0230

Component

Gearbox

CITGO EP COMPOUND ISO 800 (--- GAL)





DIAGNOSIS

Recommendation

Check seals and/or filters for points of contaminant entry. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. We recommend you service the filters on this component. Resample in 30-45 days to monitor this situation. NOTE: Please provide information regarding reservoir capacity, filter type and micron rating with next sample.

Wear

All component wear rates are normal.

Contamination

There is a high amount of silt (particulates < 14 microns in size) present in the oil.

Fluid Condition

The AN level is acceptable for this fluid. The oil is still serviceable provided that the contaminant(s) can be reduced to acceptable levels.

		May2022	Nov2022 Feb2023	Apr2023 Jul2023	Nov2023	
SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		KFS0004924	KFS0004887	KFS0003800
Sample Date		Client Info		10 Nov 2023	29 Sep 2023	19 Jul 2023
Machine Age	hrs	Client Info		0	0	0
Oil Age	hrs	Client Info		0	0	0
Oil Changed		Client Info		N/A	N/A	N/A
Sample Status				SEVERE	ABNORMAL	SEVERE
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>200	29	28	28
Chromium	ppm	ASTM D5185m	>15	0	<1	0
Nickel	ppm	ASTM D5185m	>15	0	0	0
Titanium	ppm	ASTM D5185m		0	0	0
Silver	ppm	ASTM D5185m		0	0	0
Aluminum	ppm	ASTM D5185m	>25	0	0	0
Lead	ppm	ASTM D5185m	>100	0	0	<1
Copper	ppm	ASTM D5185m	>200	1	1	1
Tin	ppm	ASTM D5185m	>25	0	0	0
Vanadium	ppm	ASTM D5185m		0	0	0
Cadmium	ppm	ASTM D5185m		0	0	0
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m		0	<1	<1
Barium	ppm	ASTM D5185m		0	0	2
Molybdenum	ppm	ASTM D5185m		0	0	0
Manganese	ppm	ASTM D5185m		0	<1	<1
Magnesium	ppm	ASTM D5185m		0	<1	<1
Calcium	ppm	ASTM D5185m		4	5	4
Phosphorus	ppm	ASTM D5185m		112	109	118
Zinc	ppm	ASTM D5185m		10	5	3
Sulfur	ppm	ASTM D5185m		6480	7170	7277
CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>50	0	<1	<1
Sodium	ppm	ASTM D5185m		<1	1	0
Potassium	ppm	ASTM D5185m	>20	0	<1	0
FLUID CLEANLIN	IESS	method	limit/base	current	history1	history2
Particles >4µm		ASTM D7647	>20000	164991	<u>▲</u> 152408	168692
Particles >6µm		ASTM D7647	>5000	33215	▲ 30211	<u>▲</u> 32470
Particles >14µm		ASTM D7647	>640	276	184	232
Particles >21µm		ASTM D7647	>160	33	15	26
Particles >38µm		ASTM D7647	>40	1	1	1
Particles >71µm		ASTM D7647	>10	0	0	0
Oil Cleanliness		ISO 4406 (c)	>21/19/16	25/22/15	△ 24/22/15	25/22/15
FLUID DEGRADA	TION _	method	limit/base	current	history1	history2

0.45

Acid Number (AN) mg KOH/g ASTM D8045

0.46

0.48



OIL ANALYSIS REPORT







Certificate L2367

Laboratory Sample No. Lab Number **Unique Number**

: 06007653 : 10741415 Test Package : IND 2 (Additional Tests: PrtCount)

: KFS0004924

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 : 14 Nov 2023 Received Diagnosed Diagnostician

: 15 Nov 2023 : Wes Davis

To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012) **CONSTELLIUM**

4805 SECOND STREET MUSCLE SHOALS, AL US 35661

Contact: Joel Even joel.even@constellium.com

T: (256)740-7490