


PROBLEM SUMMARY

74 BANBURY MOTOR

Inboard Journal Bearing

ESSO NUTO H ISO 68 (1 QTS)





COMPONENT CONDITION SUMMARY

No relevant graphs to display

RECOMMENDATION

No corrective action is recommended at this time. The oil change at the time of sampling has been noted. Resample at the next service interval to monitor. We were unable to perform a particle count due to metal particles present in this sample.

PROBLEMATIC 1	EST RE	SULTS				
Sample Status				ABNORMAL	ABNORMAL	ABNORMAL
White Metal	scalar	*Visual	NONE	▲ MODER	NONE	▲ MODER

Customer Id: BRIDES Sample No.: WC0838866 Lab Number: 06009510 Test Package: IND 2

To manage this report scan the QR code

To discuss the diagnosis or test data:

Don Baldridge +1 don.b505@comcast.net

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

RECOMMENDED ACTIONS

Action	Status	Date	Done By	Description
Alert			?	We were unable to perform a particle count due to metal particles present in this sample.

HISTORICAL DIAGNOSIS

04 Sep 2023 Diag: Don Baldridge





No corrective action is recommended at this time. The oil change at the time of sampling has been noted. Resample at the next service interval to monitor. All component wear rates are normal. There is a high amount of silt (particulates < 14 microns in size) present in the oil. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.



07 Aug 2023 Diag: Doug Bogart

VISUAL METAL



No corrective action is recommended at this time. The oil change at the time of sampling has been noted. Resample at the next service interval to monitor. We were unable to perform a particle count due to metal particles present in this sample. Moderate concentration of visible metal present. All component wear rates are normal. No other contaminants were detected in the oil. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.



05 Jul 2023 Diag: Angela Borella

VISUAL METAL




The oil change at the time of sampling has been noted. We advise that you inspect for the source(s) of wear. We recommend an early resample to monitor this condition. We were unable to perform a particle count due to metal particles present in this sample. The tin level is abnormal. Moderate concentration of visible metal present. Bearing wear is indicated. All other component wear rates are normal. No other contaminants were detected in the oil. The AN level is acceptable for this fluid. The condition of the oil is acceptable for the time in service.





OIL ANALYSIS REPORT

Sample Rating Trend



VISUAL METAL



Area **412 74 BANBURY MOTOR**

Inboard Journal Bearing

ESSO NUTO H ISO 68 (1 QTS)

DIAGNOSIS

Recommendation

No corrective action is recommended at this time. The oil change at the time of sampling has been noted. Resample at the next service interval to monitor. We were unable to perform a particle count due to metal particles present in this sample.

Moderate concentration of visible metal present. All component wear rates are normal.

Contamination

No other contaminants were detected in the oil.

Fluid Condition

The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

		rc2013 Jan2019	Jun 2016 Dec 2017 Mar 201	8 Nov2018 Jun2020 Apr2021 Apr20	023 Sep 2023	
SAMPLE INFORM	ATION	method	limit/base	current	history1	history2
Sample Number		Client Info		WC0838866	WC0838903	WC0397551
Sample Date		Client Info		10 Nov 2023	04 Sep 2023	07 Aug 2023
Machine Age	mths	Client Info		6	1	1
Oil Age	mths	Client Info		0	0	0
Oil Changed		Client Info		Changed	Changed	Changed
Sample Status				ABNORMAL	ABNORMAL	ABNORMAL
WEAR METALS		method	limit/base	current	history1	history2
PQ		ASTM D8184		11	15	9
Iron	ppm	ASTM D5185m	>60	2	<1	0
Chromium	ppm	ASTM D5185m	>20	0	0	0
Nickel	ppm	ASTM D5185m	>20	0	0	0
Titanium	ppm	ASTM D5185m		0	<1	<1
Silver	ppm	ASTM D5185m		0	0	0
Aluminum	ppm	ASTM D5185m	>4	<1	0	<1
Lead	ppm	ASTM D5185m	>250	11	5	11
Copper	ppm	ASTM D5185m	>125	12	4	12
Tin	ppm	ASTM D5185m	>80	48	22	44
Vanadium	ppm	ASTM D5185m		0	0	<1
Cadmium	ppm	ASTM D5185m		0	0	<1
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m	0	0	0	0
Barium	ppm	ASTM D5185m	0	6	0	<1
Molybdenum	ppm	ASTM D5185m	0	0	0	<1
Manganese	ppm	ASTM D5185m		0	0	<1
Magnesium	ppm	ASTM D5185m	5	1	0	6
Calcium	ppm	ASTM D5185m	50	41	52	41
Phosphorus	ppm	ASTM D5185m	330	322	347	332
Zinc	ppm	ASTM D5185m	420	387	439	400
Sulfur	ppm	ASTM D5185m	3100	3357	3833	3093
CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>50	3	3	3
Sodium	ppm	ASTM D5185m		0	<1	2
Potassium	ppm	ASTM D5185m	>20	<1	0	<1
FLUID CLEANLINE	ESS	method	limit/base	current	history1	history2
Particles >4µm		ASTM D7647	>10000		△ 99824	
Particles >6µm		ASTM D7647	>2500		△ 6815	
Particles >14μm		ASTM D7647	>160		51	
Particles >21μm		ASTM D7647	>40		6	
Particles >38μm		ASTM D7647	>10		0	
Particles >71μm		ASTM D7647	>3		0	
Oil Cleanliness		ISO 4406 (c)	>20/18/14		4 24/20/13	
FLUID DEGRADA	TION	method	limit/base	current	history1	history2
A ! I N	1/011/	40TM D0045	40		0.40	0.10

Acid Number (AN)

mg KOH/g ASTM D8045 .40

0.40

0.41

0.43



OIL ANALYSIS REPORT







Certificate L2367

Laboratory Sample No. Lab Number **Unique Number**

: 06009510 : 10743272

: WC0838866

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 16 Nov 2023 Diagnosed : 19 Nov 2023 Diagnostician : Don Baldridge

Test Package : IND 2 (Additional Tests: PQ, PrtCount) To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

BRIDGESTONE FIRESTONE - DES MOINES

4600 NW 2ND AVE DES MOINES, IA US 50313

Contact: SCOTT CARTER

CarterScottA@FirestoneAg.com T: x:

F: x: