

PROBLEM SUMMARY

1DW310EXJNF716118 5111

JOHN DEERE ENGINE OIL PLUS 50 II 15W40 (9 GAL)



COMPONENT CONDITION SUMMARY



Contracting

Component Diesel Engine

Fluic



RECOMMENDATION

We advise that you check for the source of the coolant leak. Suspect Oil Cooler leaching. We recommend that you check the cooling system for the presence of oil. If oil is present in the cooling system we recommend that the oil cooler be removed and tested. We recommend that you drain the oil and perform a filter service on this component if not already done. We recommend an early resample to monitor this condition.

PROBLEMATIC TEST RESULTS								
Sample Status				SEVERE	SEVERE	ATTENTION		
Copper	ppm	ASTM D5185m	>26	🔺 216	<u> </u>	4		
Potassium	ppm	ASTM D5185m	>20	<u> </u>	4 06	10		
Glycol	%	*ASTM D2982		0.020	0.10	NEG		

Customer Id: CARBUTNC Sample No.: WC0861886 Lab Number: 06056569 Test Package: CONST



To manage this report scan the QR code

To discuss the diagnosis or test data: Doug Bogart +1 (800)237-1369 x4016 <u>dougb@wearcheckusa.com</u>

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

Action	Status	Date	Done By	Description		
Change Fluid			?	We recommend that you drain the oil and perform a filter service on this component if not already done.		
Change Filter			?	We recommend that you drain the oil and perform a filter service on this component if not already done.		
Resample			?	We recommend an early resample to monitor this condition.		
Check Cooling System			?	Suspect Oil Cooler leaching. We recommend that you check the cooling system for the presence of oil. If oil is present in the cooling system we recommend that the oil cooler be removed and tested.		
Check Glycol Access			?	We advise that you check for the source of the coolant leak.		

HISTORICAL DIAGNOSIS

DECOMMENDED ACTIONS

17 Nov 2023 Diag: Jonathan Hester



We advise that you check for the source of the coolant leak. Check for low coolant level. Oil and filter change at the time of sampling has been noted. We recommend an early resample to monitor this condition. The copper level is abnormal. Valve wear is indicated. In the absence of other significant wear metals, suspect copper due to sources other than wear (i.e. cooling core). Sodium and/or potassium levels are high. Test for glycol is positive. Elemental level of silicon (Si) above normal indicating ingress of seal material. The amount and size of particulates present in the system are acceptable. The BN result indicates that there is suitable alkalinity remaining in the oil. The oil is no longer serviceable due to the presence of contaminants.



view report

GLYCOL

18 May 2023 Diag: Jonathan Hester

 \checkmark

Oil and filter change at the time of sampling has been noted. Resample at the next service interval to monitor.All component wear rates are normal. Sodium and/or potassium levels are high. Test for glycol is negative. The amount and size of particulates present in the system are acceptable. The oil viscosity is lower than normal. The BN result indicates that there is suitable alkalinity remaining in the oil. Confirm oil type.

21 Nov 2022 Diag: Jonathan Hester

NORMAL



Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. The amount and size of particulates present in the system are acceptable. The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.





OIL ANALYSIS REPORT

Sample Rating Trend

GLYCOL



Area Contracting Machine Id 1DW310EXJNF716118 5111 Component Discol Function

Diesel Engine

JOHN DEERE ENGINE OIL PLUS 50 II 15W40 (9 GAL)

	(••••=)	0ct2022	Nov2022	May2023 Nov2023	Jan2024	
SAMPLE INFOR	RMATION	method	limit/base	current	history1	history
Sample Number		Client Info		WC0861886	WC0861661	WC080894
Sample Date		Client Info		08 Jan 2024	17 Nov 2023	18 May 20
Machine Age	hrs	Client Info		1329	1243	772
Oil Age	hrs	Client Info		111	471	103
Oil Changed		Client Info		N/A	Changed	Changed
Sample Status				SEVERE	SEVERE	ATTENTIC
CONTAMINATIO	ON	method	limit/base	current	history1	history
Fuel		WC Method	>2.1	<1.0	<1.0	<1.0
Water		WC Method	>0.21	NEG	NEG	NEG
WEAR METALS		method	limit/base	current	history1	history
Iron	ppm	ASTM D5185m	>51	11	32	18
Chromium	ppm	ASTM D5185m	>11	0	<1	<1
Nickel	ppm	ASTM D5185m	>5	2	1 0	4
Titanium	ppm	ASTM D5185m		<1	0	0
Silver	ppm	ASTM D5185m	>3	0	0	0
Aluminum	ppm	ASTM D5185m	>31	2	4	4
Lead	ppm	ASTM D5185m	>26	2	<1	<1
Copper	ppm	ASTM D5185m	>26	<u> </u>	A 230	4
Tin	ppm	ASTM D5185m	>4	1	3	1
Vanadium	ppm	ASTM D5185m		<1	0	0
Cadmium	ppm	ASTM D5185m		0	0	0
ADDITIVES		method	limit/base	current	history1	histor
Boron	ppm	ASTM D5185m		190	92	62
Barium	ppm	ASTM D5185m		0	0	0
Molybdenum	ppm	ASTM D5185m		216	130	83
Manganese	ppm	ASTM D5185m		<1	2	1
Magnesium	ppm	ASTM D5185m		740	475	577
Calcium	ppm	ASTM D5185m		1252	1464	1622
Phosphorus	ppm	ASTM D5185m		911	778	784
Zinc	ppm	ASTM D5185m		1038	882	995
Sulfur	ppm	ASIM D5185m		2890	2385	3173
CONTAMINANT	S	method	limit/base	current	history1	histor
Silicon	ppm	ASTM D5185m	>22	21	41	8
Sodium	ppm	ASTM D5185m	>31	330	A 1350	A 79
Potassium	ppm	ASTM D5185m	>20	▲ 160	406	10
Giycol	%	^ASTM D2982		0.020	0.10	NEG
INFRA-RED		method	limit/base	current	history1	histor
Soot %	%	*ASTM D7844	>3	0.1	0.2	0.2
Nitration	Abs/cm	*ASTM D7624	>20	6.9	11.6	7.4
Sulfation	Abs/ 1mm	*ASTM D7415	>30	20 5	24 7	21.8

DIAGNOSIS

Recommendation

We advise that you check for the source of the coolant leak. Suspect Oil Cooler leaching. We recommend that you check the cooling system for the presence of oil. If oil is present in the cooling system we recommend that the oil cooler be removed and tested. We recommend that you drain the oil and perform a filter service on this component if not already done. We recommend an early resample to monitor this condition.

🔺 Wear

The copper level is abnormal. In the absence of other significant wear metals, suspect copper due to sources other than wear (i.e. cooling core).

Contamination

Sodium and/or potassium levels are high. Test for glycol was a strong positive. The amount and size of particulates present in the system are acceptable.

Fluid Condition

The BN result indicates that there is suitable alkalinity remaining in the oil. The oil is no longer serviceable due to the presence of contaminants.



OIL ANALYSIS REPORT







FLUID CLEANLIN	ESS	method	limit/base	current	history1	history2
Particles >4µm		ASTM D7647	>20000	3976	6107	4802
Particles >6µm		ASTM D7647	>5000	2166	3327	2616
Particles >14µm		ASTM D7647	>640	369	566	445
Particles >21µm		ASTM D7647	>160	124	191	150
Particles >38µm		ASTM D7647	>40	19	29	23
Particles >71µm		ASTM D7647	>10	2	3	2
Oil Cleanliness		ISO 4406 (c)	>21/19/16	19/18/16	20/19/16	19/19/16
FLUID DEGRADA	TION	method	limit/base	current	history1	history2
Oxidation	Abs/.1mm	*ASTM D7414	>25	15.1	19.9	19.8
Base Number (BN)	mg KOH/g	ASTM D2896	13.6	11.6	14.5	9.9
VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Yellow Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Precipitate	scalar	*Visual	NONE	NONE	NONE	NONE
Silt	scalar	*Visual	NONE	NONE	NONE	NONE
Debris	scalar	*Visual	NONE	NONE	NONE	NONE
Sand/Dirt	scalar	*Visual	NONE	NONE	NONE	NONE
Appearance	scalar	*Visual	NORML	NORML	NORML	NORML
Odor	scalar	*Visual	NORML	NORML	NORML	NORML
Emulsified Water	scalar	*Visual	>0.21	NEG	NEG	NEG
Free Water	scalar	*Visual		NEG	NEG	NEG
FLUID PROPERT	IES	method	limit/base	current	history1	history2
Visc @ 100°C	cSt	ASTM D445	15.4	14.8	14.1	1 1.9
GRAPHS						
Ferrous Alloys			491 520	Particle Count		-26
30 - iron		-	100,020	Severe		20
20 - nickel	_		122,880			+24
10			30,720	Abnormal		-22
	and the Real Property lies in the local division of the local divi	and or West west of the Owner of the local division of the local d	and the second se	Γ 💊		
22 23	23	23	5 € 7,680			-20 3
0ct31/22	lay18/23	ov17/23	Jan 8/24 (per 1 ml) 1,920		•	-20 20

0 120 2 0 8/23 an 8/24 Jov17/23 Jov21/22 14 21µ 384 Viscosity @ 100°C Base Number (^B/H03 Base Ê 10.0 lumbe 5.0 Base 0.0 5 0ct31/22 -Jan8/24 -Jan8/24 -Nov21/22 May18/23 Nov17/23 Nov21/22 May18/23 Nov17/23 : WearCheck USA - 501 Madison Ave., Cary, NC 27513 **CAROLINA SUNROCK** : WC0861886 Recieved : 10 Jan 2024 PO BOX 25 : 06056569 Diagnosed BUTNER, NC : 11 Jan 2024 : 10822518 Diagnostician : Doug Bogart US 27509 Test Package : CONST (Additional Tests: PrtCount, TBN) Contact: Leigh Dennis rdennis@thesunrockgroup.com

To discuss this sample report, contact Customer Service at 1-800-237-1369. * - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

T: (919)575-4505

F: (919)575-0162