

PROBLEM SUMMARY

Sample Rating Trend


WEAR


BLUE CRANE SOUTH BRIDGE

Component Gearbox

{not provided} (--- GAL)

COMPONENT CONDITION SUMMARY





RECOMMENDATION

We recommend that you drain the oil from the component if this has not already been done. We advise that you inspect for the source(s) of wear. We recommend an early resample to monitor this condition.

PROBLEMATIC TEST RESULTS									
Sample Status				SEVERE					
Iron	ppm	ASTM D5185m	>200	124					
Acid Number (AN)	ma KOH/a	ASTM D8045		2.209					

Customer Id: THEERI Sample No.: WC0819600 Lab Number: 06061329 Test Package: IND 2



To manage this report scan the QR code

To discuss the diagnosis or test data: Jonathan Hester +1 919-379-4092 x4092 ihester@wearcheckusa.com

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

RECOMMENDED ACTIONS							
Action	Status	Date	Done By	Description			
Inspect Wear Source			?	We advise that you inspect for the source(s) of wear.			
Change Fluid			?	We recommend that you drain the oil from the component if this has not already been done.			
Resample			?	We recommend an early resample to monitor this condition.			

HISTORICAL DIAGNOSIS



OIL ANALYSIS REPORT

Sample Rating Trend




BLUE CRANE SOUTH BRIDGE

Component

Gearbox

{not provided} (--- GAL)





DIAGNOSIS

Recommendation

We recommend that you drain the oil from the component if this has not already been done. We advise that you inspect for the source(s) of wear. We recommend an early resample to monitor this condition.

Wear

Gear wear is indicated.

Contamination

There is no indication of any contamination in the


▲ Fluid Condition

The AN level is at the top-end of the recommended limit. The oil is no longer serviceable as a result of the abnormal and/or severe wear.

				Jan2024		
SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		WC0819600		
Sample Date		Client Info		09 Jan 2024		
Machine Age	hrs	Client Info		0		
Oil Age	hrs	Client Info		0		
Oil Changed		Client Info		N/A		
Sample Status				SEVERE		
CONTAMINATION		method	limit/base	current	history1	history2
Water		WC Method	>0.2	NEG		
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>200	724		
Chromium	ppm	ASTM D5185m	>15	5		
Nickel	ppm	ASTM D5185m	>15	2		
Titanium	ppm	ASTM D5185m		<1		
Silver	ppm	ASTM D5185m		0		
Aluminum	ppm	ASTM D5185m	>25	5		
Lead	ppm	ASTM D5185m	>100	<1		
Copper	ppm	ASTM D5185m	>200	3		
Tin	ppm	ASTM D5185m	>25	0		
Vanadium	ppm	ASTM D5185m		0		
Cadmium	ppm	ASTM D5185m		0		
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m		2		
Barium	ppm	ASTM D5185m		0		
Molybdenum	ppm	ASTM D5185m		<1		
Manganese	ppm	ASTM D5185m		6		
Magnesium	ppm	ASTM D5185m		<1		
Calcium	ppm	ASTM D5185m		12		
Phosphorus	ppm	ASTM D5185m		247		
Zinc	ppm	ASTM D5185m		<1		
Sulfur	ppm	ASTM D5185m		7047		
CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>50	21		
Sodium	ppm	ASTM D5185m		12		
Potassium	ppm	ASTM D5185m	>20	4		
FLUID DEGRADA	TION	method	limit/base	current	history1	history2
Acid Number (AN)	mg KOH/g	ASTM D8045		2.209		



OIL ANALYSIS REPORT







Certificate L2367

Laboratory Sample No. Lab Number **Unique Number**

: WC0819600 : 06061329 : 10832711 Test Package : IND 2

To discuss this sample report, contact Customer Service at 1-800-237-1369.

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Recieved Diagnosed

: 18 Jan 2024 : Jonathan Hester Diagnostician

: 16 Jan 2024

THE WARREN CO.

2201 LOVELAND AVE ERIE, PA US 16506

Contact: RILEY WARREN

riley.warren@thewarrencompany.com

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

F: (814)833-7251 Contact/Location: RILEY WARREN - THEERI

T: