


## **PROBLEM SUMMARY**

Sample Rating Trend




Machine Id

# **TB-4 REDUCER**

Gearbox

**CHEVRON MEROPA 220 (20 GAL)** 

### COMPONENT CONDITION SUMMARY



### **RECOMMENDATION**

We advise that you check all areas where contaminants can enter the system. We advise that you perform a filter service, and use off-line filtration to improve the cleanliness of the system fluid. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. Resample in 30-45 days to monitor this situation.

PROBLEMATIC TEST RESULTS								
Sample Status		SEVERE	ABNORMAL	ABNORMAL				
Particles >4µm	ASTM D7647 >1300	<b>21367</b>	<u>▲</u> 12658	<u>▲</u> 5447				
Particles >6µm	ASTM D7647 >320	<b>5849</b>	<u>^</u> 2630	378				
Particles >14µm	ASTM D7647 >80	<b>477</b>	<u>^</u> 203	16				
Particles >21μm	ASTM D7647 >20	<u> </u>	<b>4</b> 4	4				
Oil Cleanliness	ISO 4406 (c) >17/15/	13 <b>A 22/20/16</b>	<u>^</u> 21/19/15	<u>^</u> 20/16/11				

Customer Id: HYDBELFL Sample No.: ST46853 Lab Number: 06143048 Test Package: IND 2



To manage this report scan the QR code

To discuss the diagnosis or test data: Wes Davis +1 905-569-8600 x223 wesd@wearcheck.ca

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

RECOMMENDED ACTIONS							
Action	Status	Date	Done By	Description			
Change Filter			?	We advise that you perform a filter service, and use off-line filtration to improve the cleanliness of the system fluid.			
Resample			?	Resample in 30-45 days to monitor this situation.			
Check Breathers			?	The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather.			
Check Dirt Access			?	We advise that you check all areas where contaminants can enter the system.			
Filter Fluid			?	We advise that you perform a filter service, and use off-line filtration to improve the cleanliness of the system fluid.			

#### HISTORICAL DIAGNOSIS

13 Apr 2023 Diag: Jonathan Hester



We recommend you service the filters on this component if applicable. Resample at the next service interval to monitor. Please note that this is a corrected copy for diagnostic comment updates. Due to an abnormal test result it is recommended to contact Stauff Corp at (201)-444-7800 for help resolving the issue. All component wear rates are normal. There is a high amount of particulates present in the oil. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.



20 Apr 2022 Diag: Wes Davis



We recommend you service the filters on this component. We recommend an early resample to monitor this condition. All component wear rates are normal. Particles >4µm are abnormally high. Particles >6µm are notably high. The water content is negligible. The system cleanliness is above the acceptable limit for the target ISO 4406 cleanliness code. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.



02 Apr 2021 Diag: Wes Davis




We recommend you service the filters on this component. We recommend an early resample to monitor this condition. All component wear rates are normal. Particles >4µm are abnormally high. Particles >6µm are abnormally high. The water content is negligible. The system cleanliness is above the acceptable limit for the target ISO 4406 cleanliness code. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.





## **OIL ANALYSIS REPORT**

### Sample Rating Trend



Machine Id

## **TB-4 REDUCER**

Gearbox

**CHEVRON MEROPA 220 (20 GAL)** 

### **DIAGNOSIS**

#### Recommendation

We advise that you check all areas where contaminants can enter the system. We advise that you perform a filter service, and use off-line filtration to improve the cleanliness of the system fluid. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. Resample in 30-45 days to monitor this situation.

#### Wear

All component wear rates are normal.

#### ▲ Contamination

There is a high amount of particulates (2 to 100 microns in size) present in the oil. The water content is negligible. The system cleanliness code is much higher than the acceptable limit for the target ISO 4406 cleanliness code.


### **Fluid Condition**

The AN level is acceptable for this fluid. The oil is still serviceable provided that the contaminant(s) can be reduced to acceptable levels.

SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		ST46853	ST44814	ST42840
Sample Date		Client Info		02 Apr 2024	13 Apr 2023	20 Apr 2022
Machine Age	mths	Client Info		0	0	0
Oil Age	mths	Client Info		0	0	0
Oil Changed		Client Info		N/A	N/A	N/A
Sample Status				SEVERE	ABNORMAL	ABNORMAL
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>200	52	64	54
Chromium	ppm	ASTM D5185m	>15	0	<1	0
Nickel	ppm	ASTM D5185m	>15	0	0	0
Titanium	ppm	ASTM D5185m		0	0	0
Silver	ppm	ASTM D5185m		0	0	0
Aluminum	ppm	ASTM D5185m	>25	0	0	<1
Lead	ppm	ASTM D5185m	>100	0	0	0
Copper	ppm	ASTM D5185m	>200	9	10	7
Tin	ppm	ASTM D5185m	>25	0	0	<1
Antimony	ppm	ASTM D5185m	>5			
Vanadium	ppm	ASTM D5185m		<1	0	0
Cadmium	ppm	ASTM D5185m		0	0	0
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m	40	0	0	<1
Barium	ppm	ASTM D5185m		0	0	0
Molybdenum	ppm	ASTM D5185m		0	<1	<1
Manganese	ppm	ASTM D5185m		0	<1	<1
Magnesium	ppm	ASTM D5185m		0	<1	0
Calcium	ppm	ASTM D5185m		1	<1	0
Phosphorus	ppm	ASTM D5185m	270	148	167	171
Zinc	ppm	ASTM D5185m		<1	3	0
Sulfur	ppm	ASTM D5185m	8600	14127	15509	11166
CONTAMINANTS	3	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>50	3	3	4
Sodium	ppm	ASTM D5185m		1	1	0
Potassium	ppm	ASTM D5185m	>20	0	<1	1
Water	%	ASTM D6304	>0.2	0.011	0.014	0.00
ppm Water	ppm	ASTM D6304	>2000	115	140.9	0.00
FLUID CLEANLIN	IESS	method	limit/base	current	history1	history2
Particles >4µm		ASTM D7647	>1300	<b>1</b> 21367	<u> </u>	<u></u> 5447
Particles >6µm		ASTM D7647	>320	<b>5849</b>	<u>^</u> 2630	378
Particles >14µm		ASTM D7647	>80	<b>477</b>	<u>^</u> 203	16
Particles >21µm		ASTM D7647	>20	<u> </u>	<u>44</u>	4
Particles >38µm		ASTM D7647	>4	5	3	0
Particles >71µm		ASTM D7647		1	0	0
Oil Cleanliness		ISO 4406 (c)	>17/15/13	<b>22/20/16</b>	<u>^</u> 21/19/15	<u>^</u> 20/16/11
FLUID DEGRADA	ATION	method	limit/base	current	history1	history2
						<i>j</i> -



## OIL ANALYSIS REPORT







Certificate 12367

Laboratory Sample No.

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Lab Number Unique Number : 10967856

: ST46853 : 06143048

To discuss this sample report, contact Customer Service at 1-800-237-1369.

 $^st$  - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Received : 09 Apr 2024 Tested

: 10 Apr 2024 Diagnosed Test Package : IND 2 ( Additional Tests: KF, PrtCount )

: 10 Apr 2024 - Wes Davis

US 33430 Contact: ROBERT RETALEATO r.retaleato@hydraulic-supply.com;rsr@hydraulic-supply.com

**HYDRAULIC SUPPLY COMPANY** 

T: (561)996-4431 F: (561)996-8531

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

Contact/Location: ROBERT RETALEATO - HYDBELFL

326 SE 1ST ST

BELLE GLADE, FL