

PROBLEM SUMMARY

Sample Rating Trend




Machine Id

TA-3 REDUCER

Gearbox

CHEVRON MEROPA 220 (20 GAL)

COMPONENT CONDITION SUMMARY



RECOMMENDATION

We advise that you check all areas where contaminants can enter the system. We advise that you perform a filter service, and use off-line filtration to improve the cleanliness of the system fluid. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. Resample in 30-45 days to monitor this situation.

PROBLEMATIC TEST RESULTS							
Sample Status			SEVERE	ABNORMAL	ABNORMAL		
Particles >4µm	ASTM D7647	>1300	163442	<u></u> 84401			
Particles >6µm	ASTM D7647	>320	▲ 56915	△ 6465			
Particles >14μm	ASTM D7647	>80	2067	<u>^</u> 259			
Particles >21µm	ASTM D7647	>20	312	△ 59			
Oil Cleanliness	ISO 4406 (c)	>17/15/13	25/23/18	<u>4</u> 24/20/15			

Customer Id: HYDBELFL Sample No.: ST46865 Lab Number: 06143049 Test Package: IND 2



To manage this report scan the QR code

To discuss the diagnosis or test data: Wes Davis +1 905-569-8600 x223 wesd@wearcheck.ca

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

RECOMMENDED ACTIONS						
Action	Status	Date	Done By	Description		
Change Filter			?	We advise that you perform a filter service, and use off-line filtration to improve the cleanliness of the system fluid.		
Resample			?	Resample in 30-45 days to monitor this situation.		
Check Breathers			?	The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather.		
Check Dirt Access			?	We advise that you check all areas where contaminants can enter the system.		
Filter Fluid			?	We advise that you perform a filter service, and use off-line filtration to improve the cleanliness of the system fluid.		

HISTORICAL DIAGNOSIS

13 Apr 2023 Diag: Jonathan Hester



We recommend you service the filters on this component if applicable. Resample at the next service interval to monitor. Due to an abnormal test result it is recommended to contact Stauff Corp at (201)-444-7800 for help resolving the issue. Please note that this is a corrected copy for diagnostic comment updates. All component wear rates are normal. There is a high amount of particulates present in the oil. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.



VIS DEBRIS



20 Apr 2022 Diag: Don Baldridge

We recommend you service the filters on this component. Resample at the next service interval to monitor. We were unable to perform a particle count due to a high concentration of particles present in this sample. Due to an abnormal test result it is recommended to contact Stauff Corp at (201)-444-7800 for help resolving the issue.All component wear rates are normal. Moderate concentration of visible dirt/debris present in the oil. The AN level is acceptable for this fluid.



ISO



08 Apr 2021 Diag: Wes Davis


Check seals and/or filters for points of contaminant entry. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. We recommend you service the filters on this component. Resample in 30-45 days to monitor this situation.All component wear rates are normal. Particles >4µm are severely high. Particles >6µm are abnormally high. The water content is negligible. The system cleanliness code is much higher than the acceptable limit for the target ISO 4406 cleanliness code. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.





OIL ANALYSIS REPORT

Sample Rating Trend



Machine Id

TA-3 REDUCER

Gearbox

CHEVRON MEROPA 220 (20 GAL)

DIAGNOSIS

Recommendation

We advise that you check all areas where contaminants can enter the system. We advise that you perform a filter service, and use off-line filtration to improve the cleanliness of the system fluid. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. Resample in 30-45 days to monitor this situation.

Wear

All component wear rates are normal.

▲ Contamination

There is a high amount of particulates (2 to 100 microns in size) present in the oil. The water content is negligible. The system cleanliness code is much higher than the acceptable limit for the target ISO 4406 cleanliness code.


Fluid Condition

The AN level is acceptable for this fluid. The oil is still serviceable provided that the contaminant(s) can be reduced to acceptable levels.

			rŽ017 DecŽ017 AprŽ019			
SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		ST46865	ST44629	ST44312
Sample Date		Client Info		03 Apr 2024	13 Apr 2023	20 Apr 2022
Machine Age	mths	Client Info		0	0	0
Oil Age	mths	Client Info		0	0	0
Oil Changed		Client Info		N/A	N/A	N/A
Sample Status				SEVERE	ABNORMAL	ABNORMAL
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>200	92	117	128
Chromium	ppm	ASTM D5185m	>15	0	<1	<1
Nickel	ppm	ASTM D5185m	>15	<1	<1	0
Titanium	ppm	ASTM D5185m		0	0	<1
Silver	ppm	ASTM D5185m		0	0	0
Aluminum	ppm	ASTM D5185m	>25	2	3	3
Lead	ppm	ASTM D5185m	>100	<1	0	<1
Copper	ppm	ASTM D5185m	>200	4	5	6
Tin	ppm	ASTM D5185m	>25	0	0	<1
Antimony	ppm	ASTM D5185m	>5			
Vanadium	ppm	ASTM D5185m		<1	0	0
Cadmium	ppm	ASTM D5185m		0	<1	<1
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m	40	<1	0	2
Barium	ppm	ASTM D5185m		0	0	0
Molybdenum	ppm	ASTM D5185m		0	<1	<1
Manganese	ppm	ASTM D5185m		<1	<1	<1
Magnesium	ppm	ASTM D5185m		1	1	<1
Calcium	ppm	ASTM D5185m		12	6	7
Phosphorus	ppm	ASTM D5185m	270	182	207	209
Zinc	ppm	ASTM D5185m		11	8	6
Sulfur	ppm	ASTM D5185m	8600	12832	15390	11200
CONTAMINANTS	;	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>50	7	9	9
Sodium	ppm	ASTM D5185m		2	2	<1
Potassium	ppm	ASTM D5185m	>20	0	<1	2
Water	%	ASTM D6304	>0.2	0.006	0.008	0.00
ppm Water	ppm	ASTM D6304	>2000	65	89.3	0.00
FLUID CLEANLIN	IESS	method	limit/base	current	history1	history2
		ASTM D7647	>1300	163442	84401	
Particles >4μm						
Particles >6µm		ASTM D7647	>320	▲ 56915	<u>▲</u> 6465	
Particles >6µm			>320 >80	▲ 56915 ▲ 2067	△ 6465 △ 259	
Particles >4μm Particles >6μm Particles >14μm Particles >21μm		ASTM D7647				
Particles >6μm Particles >14μm		ASTM D7647 ASTM D7647	>80	▲ 2067	△ 259	
Particles >6μm Particles >14μm Particles >21μm		ASTM D7647 ASTM D7647 ASTM D7647	>80 >20 >4	▲ 2067 ▲ 312	△ 259 △ 59	
Particles >6µm Particles >14µm Particles >21µm Particles >38µm		ASTM D7647 ASTM D7647 ASTM D7647 ASTM D7647	>80 >20 >4	▲ 2067 ▲ 312 4	△ 259 △ 59	



OIL ANALYSIS REPORT







Certificate 12367

Report Id: HYDBELFL [WUSCAR] 06143049 (Generated: 04/10/2024 11:40:36) Rev: 1

Lab Number

Laboratory Sample No.

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 : ST46865

: 06143049 Unique Number: 10967857

Received : 09 Apr 2024 Tested Diagnosed

: 10 Apr 2024 : 10 Apr 2024 - Wes Davis

Test Package : IND 2 (Additional Tests: KF, PrtCount) To discuss this sample report, contact Customer Service at 1-800-237-1369. st - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Contact: ROBERT RETALEATO r.retaleato@hydraulic-supply.com;rsr@hydraulic-supply.com

HYDRAULIC SUPPLY COMPANY

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

Contact/Location: ROBERT RETALEATO - HYDBELFL

326 SE 1ST ST

US 33430

BELLE GLADE, FL

T: (561)996-4431

F: (561)996-8531