







PROBLEM SUMMARY

Sample Rating Trend



Machine Id
TURBINA 20 - FRONT BEARING (S/N 101181)
 Component
Grease
 Fluid
KLUBER KLUBERPLEX BEM 41-141 (--- LTR)

COMPONENT CONDITION SUMMARY



RECOMMENDATION

Re-sample to verify the actual oil condition. Purge old grease if still abnormal and monitor the trend of iron level. No corrective action is recommended at this time.

PROBLEMATIC TEST RESULTS

Sample Status			SEVERE	ABNORMAL	ABNORMAL
PQ		ASTM D8184 >200	▲ 17477	▲ 2638	629
Iron	ppm	ASTM D5185m >250	▲ 1083	▲ 938	215
Chromium	ppm	ASTM D5185m >10	▲ 40	▲ 14	3
Copper	ppm	ASTM D5185m >75	▲ 134	32	25

Customer Id: EOLOMAN
 Sample No.: WC0881147
 Lab Number: 06194911
 Test Package: GRS 1



To manage this report scan the QR code

To discuss the diagnosis or test data:
 Doug Bogart +1 (800)237-1369 x4016
dougb@wearcheckusa.com

To change component or sample information:
 Customer Service +1 1-800-237-1369
customerservice@wearcheck.com

RECOMMENDED ACTIONS

Action	Status	Date	Done By	Description
Monitor	---	---	?	Re-sample to verify the actual oil condition. Purge old grease if still abnormal and monitor the trend of iron level.
Change Fluid	---	---	?	Re-sample to verify the actual oil condition. Purge old grease if still abnormal and monitor the trend of iron level.
Resample	---	---	?	Re-sample to verify the actual oil condition. Purge old grease if still abnormal and monitor the trend of iron level.

HISTORICAL DIAGNOSIS

WEAR



04 May 2024 Diag: Doug Bogart

No corrective action is recommended at this time. We recommend an early resample to monitor this condition. Bearing and/or bushing wear is indicated. There is no indication of any contamination in the grease. The condition of the grease is acceptable for the time in service.

[view report](#)



DIRT



23 Aug 2023 Diag: Doug Bogart

No corrective action is recommended at this time. All component wear rates are normal. Elemental level of silicon (Si) above normal. The condition of the grease is acceptable for the time in service.

[view report](#)



WEAR



30 Mar 2022 Diag: Doug Bogart

We recommend an early resample to monitor this condition. The iron level is abnormal. The very high ferrous density (PQ) index indicates that severe wear is occurring. There is a trace of moisture present in the grease. The AN level is acceptable for this fluid.


[view report](#)





GREASE ANALYSIS

Sample Rating Trend



Machine Id
TURBINA 20 - FRONT BEARING (S/N 101181)
 Component
Grease
 Fluid
KLUBER KLUBERPLEX BEM 41-141 (--- LTR)

DIAGNOSIS

Recommendation
 Re-sample to verify the actual oil condition. Purge old grease if still abnormal and monitor the trend of iron level. No corrective action is recommended at this time.

Wear
 An increase in the wear is noted. Bearing and/or bushing wear is indicated.

Grease Condition
 The condition of the grease is acceptable for the time in service.

Contaminants
 There is no indication of any contamination in the grease.

SAMPLE INFORMATION

	method	limit/base	current	history1	history2
Sample Number	Client Info		WC0881147	WC0881139	WC0505300
Sample Date	Client Info		05 May 2024	04 May 2024	23 Aug 2023
Machine Age	yrs	Client Info	12	2	11
Grease Age	yrs	Client Info	1	1	1
Grease Serviced	Client Info		N/A	N/A	N/A
Sample Status			SEVERE	ABNORMAL	ABNORMAL

CONTAMINATION

	method	limit/base	current	history1	history2
Water	WC Method	>0.1	NEG	NEG	NEG

WEAR METALS

	method	limit/base	current	history1	history2
PQ	ASTM D8184	>200	▲ 17477	▲ 2638	629
Iron	ppm	ASTM D5185m	>250	▲ 1083	▲ 938
Chromium	ppm	ASTM D5185m	>10	▲ 40	▲ 14
Nickel	ppm	ASTM D5185m	>5	<1	0
Cadmium	ppm	ASTM D5185m		0	1
Titanium	ppm	ASTM D5185m		<1	1
Vanadium	ppm	ASTM D5185m		<1	2
Lead	ppm	ASTM D5185m	>25	0	1
Copper	ppm	ASTM D5185m	>75	▲ 134	32
Tin	ppm	ASTM D5185m	>5	0	0
Silver	ppm	ASTM D5185m	>5	0	0

ADDITIVES

	method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m		137	165
Magnesium	ppm	ASTM D5185m		0	0
Manganese	ppm	ASTM D5185m		7	3
Molybdenum	ppm	ASTM D5185m		550	4935
Phosphorus	ppm	ASTM D5185m		528	971
Zinc	ppm	ASTM D5185m		60	277

THICKENER/SOAP





	method	limit/base	current	history1	history2
Aluminum	ppm	ASTM D5185m		0	0
Barium	ppm	ASTM D5185m		0	13
Calcium	ppm	ASTM D5185m		10	21
Sodium	ppm	ASTM D5185m		2	22
Lithium	ppm	ASTM D5185m		384	3341
Sulfur	ppm	ASTM D5185m		4000	4823

CONTAMINANTS

	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>150	420	249
Potassium	ppm	ASTM D5185m		<1	5





GREASE CONDITION

	method	limit/base	current	history1	history2
Grease Color	*Visual	yellow	Brown	Yellow	---
Texture	*In-house		Buttery	Short fiber	---
NLGI Consistency	NLGI Scale	*SKF Method	1	0-1	0-1



SAMPLE IMAGES	method	limit/base	current	history1	history2
Color					
Bottom					
PrtFilter			no image	no image	no image

GRAPHS



Certificate L2367

Laboratory : WearCheck USA - 501 Madison Ave., Cary, NC 27513

Sample No. : WC0881147

Lab Number : 06194911

Unique Number : 11057034

Test Package : GRS 1 (Additional Tests: KV40, SCREEN)

To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

Received : 29 May 2024

Tested : 13 Jun 2024

Diagnosed : 13 Jun 2024 - Doug Bogart

EOL DE NICARAGUA S.A.

DEL SEMAFORO DEL CLUB TERRAZA, 1 CUADRA AL SUR

MANAGUA, ZZ

NI

Contact: Rafael Bermudez

T:

F: