


PROBLEM SUMMARY

Sample Rating Trend




HYBON SYNTHETIC 150 QUINCY TU261 - HYBON ENGINEERING


Component Compressor





COMPONENT CONDITION SUMMARY





RECOMMENDATION

We advise that you follow the water drain-off procedure for this component. We recommend an early resample to monitor this condition.

PROBLEMATIC 1	EST RE	SULTS				
Sample Status				SEVERE	SEVERE	SEVERE
Water	%	ASTM D6304	>0.1	2.90	▲ 1.53	2.07
ppm Water	ppm	ASTM D6304	>1000	29000	1 5300	2 0700
Emulsified Water	scalar	*Visual	>0.1	0.2%	▲ 0.2%	▲ 0.2%
Visc @ 40°C	cSt	ASTM D445		99.8	152	<u> </u>

Customer Id: UCCIMEVA **Sample No.:** UCH06219873 Lab Number: 06219873 Test Package: IND 2



To manage this report scan the QR code

To discuss the diagnosis or test data: Angela Borella +1 800-237-1369 angela.borella@wearcheckusa.com

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

RECOMMENDED ACTIONS						
Action	Status	Date	Done By	Description		
Water Drain-off			?	We advise that you follow the water drain-off procedure for this component.		
Resample			?	We recommend an early resample to monitor this condition.		

HISTORICAL DIAGNOSIS

21 May 2024 Diag: Angela Borella

We advise that you follow the water drain-off procedure for this component. We recommend an early resample to monitor this condition. All component wear rates are normal. There is a high concentration of water present in the oil. The AN level is acceptable for this fluid.



WATER

WATER



14 May 2024 Diag: Angela Borella

We advise that you follow the water drain-off procedure for this component. We recommend an early resample to monitor this condition.All component wear rates are normal. There is a high concentration of water present in the oil. Moderate concentration of visible dirt/debris present in the oil. Viscosity of sample indicates oil is within ISO 100 range, advise investigate. Confirm oil type. The AN level is acceptable for this fluid.





03 May 2024 Diag: Angela Borella

We advise that you inspect for the source(s) of wear. We recommend an early resample to monitor this condition. The iron level is abnormal. All other component wear rates are normal. There is a light concentration of water present in the oil. The AN level is acceptable for this fluid. The oil is no longer serviceable as a result of the abnormal and/or severe wear.






OIL ANALYSIS REPORT

HYBON SYNTHETIC 150 QUINCY TU261 - HYBON ENGINEERING

Component Compressor



DIAGNOSIS

Recommendation

We advise that you follow the water drain-off procedure for this component. We recommend an early resample to monitor this condition.

All component wear rates are normal.

Contamination

There is a high concentration of water present in the oil.


Fluid Condition

Viscosity of sample indicates oil is within ISO 100 range, advise investigate. Confirm oil type. The AN level is acceptable for this fluid.

nistory2)621987(
10213070
ay 2024
ay 2024
ERE
_NL
nistory2
nistory2
1
nistory2
07
07 700
i





OIL ANALYSIS REPORT


















Certificate 12367

Laboratory Sample No.

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 : UCH06219873 Lab Number : 06219873

Unique Number : 11098070

Received **Tested** Diagnosed

: 25 Jun 2024 : 26 Jun 2024

: 27 Jun 2024 - Angela Borella

EVANS, CO US 80620 Contact: COLLEEN GRIFFITH CGRIFFITH@CIMARRON.COM

CIMARRON FIELD SERVICES

To discuss this sample report, contact Customer Service at 1-800-237-1369. st - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Test Package : IND 2 (Additional Tests: KF)

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

Report Id: UCCIMEVA [WUSCAR] 06219873 (Generated: 06/28/2024 03:18:04) Rev: 1

Contact/Location: COLLEEN GRIFFITH - UCCIMEVA

T:

F:

1400 42ND ST