


PROBLEM SUMMARY

Sample Rating Trend




Machine Id


EX SLIP STICK TRANSITION (NORTH PLANT)

Upper Gearbox

JAX Flow Guard ISO FG 150 (--- GAL)

COMPONENT CONDITION SUMMARY





RECOMMENDATION

We advise that you check for the source of water entry. Recommend drain oil if not already done and flush before refilling with oil. We advise that you inspect for the source(s) of wear. We recommend an early resample to monitor this condition. We were unable to perform a particle count due to a high concentration of water present in this sample.

PROBLEMATIC TEST RESULTS									
Sample Status				SEVERE	SEVERE				
Iron	ppm	ASTM D5185m	>200	507	4 444				
Silicon	ppm	ASTM D5185m	>50	214	294				
Water	%	ASTM D6304	>0.2	△ 0.892	▲ 6.29				
ppm Water	ppm	ASTM D6304	>2000	8926	▲ 62900				

Customer Id: TYSSAI Sample No.: USP0012376 Lab Number: 06237823 Test Package: IND 2



To manage this report scan the QR code

To discuss the diagnosis or test data: Doug Bogart +1 (800)237-1369 x4016 dougb@wearcheckusa.com

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

RECOMMENDED ACTIONS						
Action	Status	Date	Done By	Description		
Inspect Wear Source			?	We advise that you inspect for the source(s) of wear.		
Change Fluid			?	Recommend drain oil if not already done and flush with cleaner before refilling with oil.		
Flush System			?	Recommend drain oil if not already done and flush with cleaner before refilling with oil.		
Resample			?	We recommend an early resample to monitor this condition.		
Alert			?	We were unable to perform a particle count due to a high concentration of particles present in this sample.		
Check Water Access			?	We advise that you check for the source of water entry.		

HISTORICAL DIAGNOSIS

29 Oct 2023 Diag: Doug Bogart

WEAR




We advise that you check for the source of water entry. Recommend drain oil if not already done and flush with cleaner before refilling with oil. We recommend an early resample to monitor this condition. Please note that there was too much water present in the oil to perform an accurate viscosity test. Gear wear is indicated. Appearance is unacceptable. Sodium and/or potassium levels are high. There is a high amount of visible silt present in the sample. Elemental level of silicon (Si) above normal indicating ingress of dirt/seal material. Excessive free water present. There is a high concentration of water present in the oil. The AN level is acceptable for this fluid. The oil is no longer serviceable due to the presence of contaminants.





OIL ANALYSIS REPORT

Sample Rating Trend





Machine Id

EX SLIP STICK TRANSITION (NORTH PLANT)

Upper Gearbox

JAX Flow Guard ISO FG 150 (--- GAL)

DIAGNOSIS

Recommendation

We advise that you check for the source of water entry. Recommend drain oil if not already done and flush before refilling with oil. We advise that you inspect for the source(s) of wear. We recommend an early resample to monitor this condition. We were unable to perform a particle count due to a high concentration of water present in this sample.

Gear wear is indicated.

Contamination

There is a high concentration of water present in the oil. Elemental level of silicon (Si) above normal indicating ingress of seal material.

Fluid Condition

The AN level is acceptable for this fluid. The oil is no longer serviceable due to the presence of contaminants.

			0ct2023	Jul 2 024		
SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		USP0012376	USP0002868	
Sample Date		Client Info		15 Jul 2024	29 Oct 2023	
Machine Age	hrs	Client Info		0	0	
Oil Age	hrs	Client Info		0	0	
Oil Changed		Client Info		N/A	N/A	
Sample Status				SEVERE	SEVERE	
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>200	▲ 507	444	
Chromium	ppm	ASTM D5185m	>15	12	<u></u> 19	
Nickel	ppm	ASTM D5185m	>15	5	10	
Titanium	ppm	ASTM D5185m		2	3	
Silver	ppm	ASTM D5185m		0	0	
Aluminum	ppm	ASTM D5185m	>25	<u> </u>	69	
Lead	ppm	ASTM D5185m	>100	<1	0	
Copper	ppm	ASTM D5185m	>200	<1	1	
Tin	ppm	ASTM D5185m	>25	2	<1	
Vanadium	ppm	ASTM D5185m		<1	<1	
Cadmium	ppm	ASTM D5185m		0	<1	
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m		109	139	
Barium	ppm	ASTM D5185m		0	0	
Molybdenum	ppm	ASTM D5185m		0	<1	
Manganese	ppm	ASTM D5185m		4	5	
Magnesium	ppm	ASTM D5185m		35	50	
Calcium	ppm	ASTM D5185m		2580	3678	
Phosphorus	ppm	ASTM D5185m		597	549	
Zinc	ppm	ASTM D5185m		722	1521	
Sulfur	ppm	ASTM D5185m		1597	1764	
CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>50	214	294	
		ASTM D5185m		2050	<u> 1717</u>	
Sodium	ppm	AO INI DO IOOIII				
Sodium Potassium	ppm	ASTM D5185m	>20	124	△ 166	
			>20 >0.2	124 ^ 0.892	▲ 166 ▲ 6.29	
Potassium	ppm	ASTM D5185m				

0.28

1.41

Acid Number (AN)

mg KOH/g ASTM D8045



OIL ANALYSIS REPORT





Certificate 12367

Laboratory Sample No.

: USP0012376 Lab Number : 06237823

Received : 16 Jul 2024 **Tested** : 18 Jul 2024

Unique Number : 11126657 Diagnosed : 18 Jul 2024 - Doug Bogart Test Package : IND 2

To discuss this sample report, contact Customer Service at 1-800-237-1369.

 st - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

Report Id: TYSSAI [WUSCAR] 06237823 (Generated: 07/18/2024 09:48:11) Rev: 1

Contact/Location: ? ? - TYSSAI

5807 MITCHELL AVE

SAINT JOSEPH, MO

US 64507

Contact:

T:

F: