



# FLUID ANALYSIS REPORTS

**To: MIKE HOLT**  
 PALFINGER - BRANCH 420  
 21708 SE 291ST STREET  
 SEATTLE, WA, USA 98010

**Laboratory**  
 WearCheck USA  
 501 Madison Ave.  
 Cary, NC, USA 27513

## PALFINGER - BRANCH 420 - 21708 SE 291ST STREET, SEATTLE, WA 98010

<b>Sample No.</b> : WC0470609				WEAR	<b>NORMAL</b>
<b>Lab Number</b> : 05221433	Machine Id	<b>100417350 - FISHER ROOFING</b>		CONTAMINATION	<b>NORMAL</b>
<b>Test Package</b> : MOBCE	Component	Hydraulic System		FLUID CONDITION	<b>NORMAL</b>
<b>Sampled</b> : 21 Oct 2020	Fluid	NOT GIVEN (--- GAL)			
<hr/>					
<b>Sample No.</b> : WC0517101				WEAR	<b>NORMAL</b>
<b>Lab Number</b> : 05221432	Machine Id	<b>22982 - ABC SUPPLY</b>		CONTAMINATION	<b>ABNORMAL</b>
<b>Test Package</b> : MOBCE	Component	Hydraulic System		FLUID CONDITION	<b>NORMAL</b>
<b>Sampled</b> : 30 Mar 2021	Fluid	NOT GIVEN (--- GAL)			
<hr/>					
<b>Sample No.</b> : WC0470608				WEAR	<b>NORMAL</b>
<b>Lab Number</b> : 05221435	Machine Id	<b>25 - DEALERS SUPPLY</b>		CONTAMINATION	<b>ABNORMAL</b>
<b>Test Package</b> : MOBCE	Component	Hydraulic System		FLUID CONDITION	<b>NORMAL</b>
<b>Sampled</b> : 26 Oct 2020	Fluid	AW HYDRAULIC OIL ISO 32 (--- GAL)			
<hr/>					
<b>Sample No.</b> : WC0470606				WEAR	<b>NORMAL</b>
<b>Lab Number</b> : 05221434	Machine Id	<b>80 - DALWIG BROS</b>		CONTAMINATION	<b>ABNORMAL</b>
<b>Test Package</b> : MOBCE	Component	Hydraulic System		FLUID CONDITION	<b>NORMAL</b>
<b>Sampled</b> : 30 Nov 2020	Fluid	NOT GIVEN (--- GAL)			

*This page left intentionally blank*