

WEAR
CONTAMINATION
FLUID CONDITION

NORMAL NORMAL



VOLVO EC360 03048

Component Hydraulic System

{not provided} (--- GAL)


	DATION

Resample at the next service interval to monitor.

Test	UOM	Method	Limit/Abn	Current	History1	History2
Sample Number		Client Info		VC061851		
Sample Date		Client Info		09 May 2003		
Machine Age	hrs	Client Info		5639		
Oil Age	hrs	Client Info		0		
Filter Age	hrs	Client Info		0		
Oil Changed		Client Info		Not Changd		
Filter Changed		Client Info		Not Changd		
Sample Status				NORMAL		
Water		WC Method		NFG		

WEAR

All component wear rates are normal.





Certificate L2367

Laboratory Sample No. Lab Number

: VC061851 : 00513192 **Unique Number** : 1671605 Test Package : MOB 2

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Recieved : 13 May 2003 Diagnosed : 19 May 2003

Diagnostician : Doug Bogart

ASCENDUM MACHINERY INC - GARNER 3561 JONES SAUSAGE ROAD GARNER, NC

US 27529 Contact: TOMMY TORRENCE tommy.torrence@lbsmith.com

T: (919)661-8710 F: (919)661-9038

To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)