
WEAR CONTAMINATION **FLUID CONDITION**

NORMAL **NORMAL ATTENTION**

Machine Id

7776
Component
Diesel Engine

| RECOMMENDATION | Test | UOM | Method | Limit/Abn | Current | History1 | History2 |
|---|-------------------------|----------|---------------|-----------|-------------|-------------|-------------|
| Check for low coolant level. The oil change at the time of sampling has been noted. We recommend an early resample to monitor this condition. | Sample Number | | Client Info | | GFL0120070 | GFL0113182 | GFL0104502 |
| | Sample Date | | Client Info | | 30 May 2024 | 23 Feb 2024 | 04 Dec 2023 |
| | Machine Age | kms | Client Info | | 169812 | 165979 | 162607 |
| | Oil Age | kms | Client Info | | 0 | 0 | 0 |
| | Filter Age | kms | Client Info | | 0 | 0 | 0 |
| | Oil Changed | | Client Info | | Changed | Changed | Changed |
| | Filter Changed | | Client Info | | Changed | Changed | Changed |
| | Sample Status | | | | ATTENTION | ATTENTION | NORMAL |
| WEAR | Iron | ppm | ASTM D5185(m) | >165 | 11 | 13 | 4 |
| VEAIT | Chromium | ppm | ASTM D5185(m) | | <1 | <1 | 0 |
| All component wear rates are normal. | Nickel | ppm | ASTM D5185(m) | | 0 | <1 | <1 |
| | Titanium | ppm | ASTM D5185(m) | | 0 | 0 | 0 |
| | Silver | ppm | ASTM D5185(m) | | 0 | 0 | <1 |
| | Aluminum | ppm | ASTM D5185(m) | | <1 | 2 | 1 |
| | Lead | ppm | ASTM D5185(m) | >150 | <1 | 5 | 0 |
| | Copper | ppm | ASTM D5185(m) | >90 | <1 | 1 | <1 |
| | Tin | ppm | ASTM D5185(m) | >5 | 0 | 0 | 0 |
| | Vanadium | ppm | ASTM D5185(m) | | 0 | 0 | 0 |
| | White Metal | scalar | Visual* | NONE | NONE | | |
| | Yellow Metal | scalar | Visual* | NONE | NONE | | |
| CONTAMINATION | Silicon | nnm | ASTM D5185(m) | >35 | 3 | 6 | 7 |
| CONTAMINATION | Potassium | ppm | ASTM D5185(m) | | 3 | 13 | 0 |
| Water treatment chemicals present, indicating slow coolant leak. Test for glycol is negative. There is no indication of any contamination in the oil. | Fuel | ррпп | WC Method | | <1.0 | ▲ 1.1 | <1.0 |
| | Water | | WC Method | | NEG | NEG | NEG |
| | Glycol | % | ASTM D7922* | 70.L | 0.0 | 0.0 | NEG |
| | Soot % | % | ASTM D7844* | >7.5 | 1.9 | 3 | 0.8 |
| | Nitration | Abs/cm | ASTM D7624* | >20 | 8.7 | 11.1 | 5.5 |
| | Sulfation | Abs/.1mm | ASTM D7415* | >30 | 22.8 | 25.7 | 19.3 |
| | Silt | scalar | Visual* | NONE | NONE | | |
| | Debris | scalar | Visual* | NONE | NONE | | |
| | Sand/Dirt | scalar | Visual* | NONE | NONE | | |
| | Appearance | scalar | Visual* | NORML | NORML | | |
| | Odor | scalar | Visual* | NORML | NORML | NORML | NORM |
| | Emulsified Water | scalar | Visual* | >0.2 | NEG | NEG | NEG |
| FLUID CONDITION | Sodium | ppm | ASTM D5185(m) | | 274 | 412 | 25 |
| LOID CONDITION | Boron | ppm | ASTM D5185(m) | 0 | 4 | 4 | 7 |
| The condition of the oil is acceptable for the time in service (see recommendation). | Barium | ppm | ASTM D5185(m) | | 0 | 0 | <1 |
| | Molybdenum | ppm | ASTM D5185(m) | | 58 | 59 | 58 |
| | Manganese | ppm | ASTM D5185(m) | | 0 | 0 | 0 |
| | Magnesium | ppm | ASTM D5185(m) | | 919 | 881 | 938 |
| | Calcium | ppm | (/ | 1070 | 1007 | 973 | 1020 |
| | Phosphorus | ppm | ASTM D5185(m) | | 987 | 953 | 952 |
| | Zinc | ppm | | 1270 | 1140 | 1099 | 1145 |
| | Sulfur | ppm | ASTM D5185(m) | | 2733 | 2586 | 2549 |
| | Oxidation | Abs/.1mm | ASTM D7414* | | 14.7 | 16.1 | 12.9 |
| | Visc @ 100°C | cSt | ASTM D7279(m) | | 15.1 | 15.7 | 14.6 |





CALA ISO 17025:2017 Accredited

Sample No. Lab Number

Laboratory : WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9

: GFL0120070 : 02639311

Received **Tested** Unique Number : 5788473 Diagnosed : 03 Jun 2024

: 03 Jun 2024

: 03 Jun 2024 - Kevin Marson Test Package : MOB 1 (Additional Tests: Glycol, Visual)

To discuss this sample report, contact Customer Service at 1-800-268-2131. Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab. Validity of results and interpretation are based on the sample and information as supplied.

20 Brydon Drive Etobicoke, ON CA M9W 5R6 Contact: Rick Philip rphilip@gflenv.com

T: (416)745-8080