WEAR
CONTAMINATION
FLUID CONDITION


NORMAL NORMAL ATTENTION



## [661207 GENERAL RV] Machine Id VOLVO L20H 1220266

Component Rear Axle

DECOMMENDATION .						١	
RECOMMENDATION	Test	UOM	Method	Limit/Abn	Current	History1	History2
Resample at the next service interval to monitor.	Sample Number		Client Info		VCP441529		
	Sample Date		Client Info		24 Feb 2024		
	Machine Age	hrs	Client Info		6045		
	Oil Age	hrs	Client Info		0		
	Filter Age	hrs	Client Info		0		
	Oil Changed		Client Info		Not Change		
	Filter Changed Sample Status		Client Info		Not Changd ATTENTION		
WEAR	Iron	ppm	ASTM D5185m	>500	470		
All component wear rates are normal.	Chromium	ppm	ASTM D5185m	>20	7		
	Nickel	ppm	ASTM D5185m	>10	1		
	Titanium	ppm	ASTM D5185m		<1		
	Silver	ppm	ASTM D5185m		0		
	Aluminum	ppm	ASTM D5185m	>30	1		
	Lead	ppm	ASTM D5185m		0		
	Copper	ppm	ASTM D5185m		6		
	Tin	ppm	ASTM D5185m	>20	0		
	Vanadium	ppm	ASTM D5185m		0		
	White Metal	scalar	*Visual	NONE	NONE		
	Yellow Metal	scalar	*Visual	NONE	NONE		
CONTAMINATION	Silicon	ppm	ASTM D5185m	>50	13		
There is no indication of any contamination in the oil.	Potassium	ppm	ASTM D5185m	>20	4		
	Water		WC Method	>0.2	NEG		
	Silt	scalar	*Visual	NONE	NONE		
	Debris	scalar	*Visual	NONE	NONE		
	Sand/Dirt	scalar	*Visual	NONE	NONE		
	Appearance	scalar	*Visual	NORML	NORML		
	Odor	scalar	*Visual	NORML	NORML		
	Emulsified Water	scalar	*Visual	>0.2	NEG		
FLUID CONDITION	Sodium	ppm	ASTM D5185m		18		
The oil viscosity is lower than normal. This plus the additive levels indicates the addition of a different brand, or type of oil. Confirm oil type.	Boron	ppm	ASTM D5185m	111	114		
	Barium	ppm	ASTM D5185m		0		
	Molybdenum	ppm	ASTM D5185m		<1		
	Manganese	ppm	ASTM D5185m		18		
	Magnesium	ppm	ASTM D5185m	39	12		
	Calcium	ppm	ASTM D5185m	93	3747		
	Phosphorus	ppm	ASTM D5185m	920	<u> </u>		
	Zinc	ppm	ASTM D5185m		<b>1559</b>		
	Sulfur	ppm	ASTM D5185m	20179	<b>4278</b>		
	Visc @ 40°C	cSt	ASTM D445	333	52.1		





Certificate L2367

Laboratory Sample No.

Lab Number : 06103372

: VCP441529

Unique Number : 10901602 Test Package : MOB 1

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 28 Feb 2024 **Tested** : 29 Feb 2024

: 01 Mar 2024 - Sean Felton Diagnosed

ALTA EQUIPMENT/FLAGLER CONSTRUCTION EQUIPMENT LLC 8418 PALM RIVER ROAD

TAMPA, FL US 33619

Contact: KENNY HANEY khaney@flaglerce.com T: (813)630-0077

F: (813)630-2233

To discuss this sample report, contact Customer Service at 1-800-237-1369. \* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)