

Machine Id **1FF160GXEMF058349** Component **Left Final Drive** Fluid **JOHN DEERE GL-5 80W90 (--- QTS)**

RECOMMENDATION

We suspect abnormal contamination may be due to sampling method. No corrective action is recommended at this time. Resample at the next service interval to monitor.

WEAR

All component wear rates are normal.

CONTAMINATION


Moderate concentration of visible dirt/debris present in the oil.


FLUID CONDITION


The condition of the oil is acceptable for the time in service.

Test	UOM	Method	Limit/Abn	Current	History1	History2
Sample Number		Client Info		JR0225335		
Sample Date		Client Info		01 Jul 2024		
Machine Age	hrs	Client Info		957		
Oil Age	hrs	Client Info		957		
Filter Age	hrs	Client Info		0		
Oil Changed		Client Info		Not Changd		
Filter Changed		Client Info		None		
Sample Status				ABNORMAL		
PQ		ASTM D8184	500	220		
Iron	ppm	ASTM D5185m	>500	100		
Chromium	ppm	ASTM D5185m	>10	2		
Nickel	ppm	ASTM D5185m	>10	<1		
Titanium	ppm	ASTM D5185m		<1		
Silver	ppm	ASTM D5185m	. 05	<1		
Aluminum	ppm	ASTM D5185m	>25	3		
Lead	ppm	ASTM D5185m	>25	0		
Copper	ppm	ASTM D5185m	>50	<1		
Tin	ppm	ASTM D5185m	>10	<1		
Vanadium	ppm	ASTM D5185m	NONE	<1		
White Metal	scalar	*Visual	NONE	NONE		
Yellow Metal	scalar	*Visual	NONE	NONE		
Silicon	ppm	ASTM D5185m	>75	17		
Potassium	ppm	ASTM D5185m	>20	3		
Water		WC Method	>0.2	NEG		
Silt	scalar	*Visual	NONE	NONE		
Debris	scalar	*Visual	NONE	A MODER		
Sand/Dirt	scalar	*Visual	NONE	NONE		
Appearance	scalar	*Visual	NORML	NORML		
Odor	scalar	*Visual	NORML	NORML		
Emulsified Water	scalar	*Visual	>0.2	NEG		
Codium				•		
Sodium	ppm	ASTM D5185m		0		
Boron Barium	ppm	ASTM D5185m		67 6		
Molybdenum	ppm	ASTM D5185m		ہ <1		
,	ppm					
Manganese	ppm	ASTM D5185m ASTM D5185m		7 <1		
Magnesium Calcium	ppm	ASTM D5185m		<1 7		
Phosphorus	ppm	ASTM D5185m		7 435		
Zinc	ppm	ASTM D5185m		435 24		
Sulfur	ppm	ASTM D5185m		24 12456		
Visc @ 40°C	ppm cSt	ASTM D5165ml		12450		
	COL	ASTIVI D445	<u> </u>	10/		

Submitted By: TECHNICIAN ACCOUNT







Submitted By: TECHNICIAN ACCOUNT Page 2 of 2