




LINE 26 BOILER 2



Customer: PTRHTF10179	System Information	Sample Information
SHAW INDUSTRIES PLANT SI 12454 NORTH US HWY 27 CHICKAMAUGA, GA 30707 USA Attn: Randy Visage Tel: (706)375-3121 E-Mail: randy.visage@shawinc.com	System Volume: 250 gal Bulk Operating Temp: 450F / 232C Heating Source: Blanket: Fluid: COASTAL THERMALANE 800 Make:	Lab No: 02132749 Analyst: Manny Garcia Sample Date: 03/08/17 Received Date: 03/15/17 Completed: 03/27/17

Recommendation: The Clean & Flush of this system was performed satisfactory as all of the lab analysis results are satisfactory. Please move forward with the conversion of the system to Petro-Canada Calflo LT and continue annual fluid analysis samples

Comments: System parameters are satisfactory for all variables.



Sample Date	Received Date	Fluid Age	Sample Location	Flash Point (COC)	Water (KF)	Viscosity (40°C)	Acid Number	Solids	GCD 10%	GCD 50%	GCD 90%	GCD % < 335°C
	mm/dd/yy			°F/°C	ppm	cSt	mg/KOH/g	%wt	°F/°C	°F/°C	°F/°C	%
03/08/17	03/15/17	3c	FILL LINE	399 / 204	10.5	16.7	0.052	0.043	765 / 407	803 / 429	898 / 481	3.40
10/24/16	11/01/16	0c	FILL LINE	324 / 162	4.1	15.1	0.028	0.078	769 / 410	812 / 434	899 / 482	3.32
Baseline Data				444 / 229		15	0.02		754 / 401		853 / 456	0.0





Sample Date	Iron	Chromium	Nickel	Aluminum	Copper	Lead	Tin	Cadmium	Silver	Vanadium	Silicon	Sodium	Potassium	Titanium	Molybdenum	Antimony	Manganese	Lithium	Boron	Magnesium	Calcium	Barium	Phosphorus	Zinc
03/08/17	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
10/24/16	6	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Baseline Data			0	0						0			0	0					0				0	

Elemental analysis results (above) in parts per million (ppm). [10,000 ppm = 1.0%]



Historical Comments

10/24/16	Age if the oil must be addressed as decisions are made to modify or change out the system and replace with Petro-Canada Calflo Heat Transfer Fluids. The very low flash point (dangerous) and the 90% distillation curve may be mitigated by 'venting' the system. Fluid must be filtered to clean up the metals/debris. Any maintenance performed on this fluid system should be followed up with a sample to verify improvement. Wear metals are acceptable/Contamination is low/Viscosity is in range/COC Flash Point is severely low and must be addressed asap at 162oC/(GCD) 90% Distillation Point is abnormally high/White metal is moderate as the 100x filter patch shows/Debris is visible

Petro-Canada makes no representation or warranty of any kind, either express or implied, as to the accuracy or completeness of the analysis and assumes no responsibility and shall have no liability whatsoever with respect to such analysis, or a party's use of it. Petro-Canada is a division of HollyFrontier Corporation.