


MODIFIED ROOM SYSTEM

Customer: PTRHTF10094	System Information	Sample Information
CERTAINTEED CORPORATION -	System Volume: 0 gal	Lab No: 02217743
OXFORD	Bulk Operating Temp: 0F / -18C	Analyst: Gaston Arseneault
200 CERTAINTEED RD	Heating Source:	Sample Date: 05/03/18
OXFORD, NC 27565 USA	Blanket:	Received Date: 05/23/18
Attn: Andy Davis	Fluid: PETRO CANADA PETRO-THERM	Completed: 05/25/18
Tel: (919)693-1141	Make:	To discuss this report contact Gaston
E-Mail: andy.j.davis@saint-gobain.com		Arseneault at 973-986-6503

Recommendation: Some of the test results from the previous samples are blank because they were tested as normal industrial oils. This sample appears to be in decent condition. No vanadium and normal viscosity so no reason to believe that asphalt is leaking. Based on the results of this analysis no action seems to be needed at this time, unless feedback from your own operations and monitoring of your process warrants it.


Comments: (GCD) 90% Distillation Point is marginally low.

Sample Date	Received Date	Fluid Age	Sample Location	Flash Point (COC)	Water (KF)	Viscosity (40°C)	Acid Number	Solids	GCD 10%	GCD 50%	GCD 90%	GCD % < 335°C
	mm/dd/yy			°F/°C	ppm	cSt	mg/KOH/ g	%wt	°F/°C	°F/°C	°F/°C	%
05/03/18	05/23/18	1y	MAIN SUPPLY LINE	435 / 224	15.7	33.7	0.033	0.017	706 / 375	785 / 418	878 / 470	0.00
12/31/14	01/05/15	Оy				32.74	0.081					
01/28/14	01/31/14	Оy				32.76	0.057					
03/14/13	03/15/13	Oy	L1	410 / 210	0.00	31.6	0.014	0.107	697 / 370	795 / 424	897 / 480	1.89
03/09/12	03/12/12		NA	426 / 219	50	30.8	0.01	0.047	703 / 373	792 / 422	887 / 475	1.188
04/25/10	04/26/10	Оy				27.3	0.117					






Elemental anaysis results (above) in parts per million (ppm). [10,000 ppm = 1.0%]



% Boiling < 335°C



Historical Comments

12/31/14	Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the component. The amount and size of particulates present in the system is acceptable. The AN level is acceptable for this fluid. The condition of the fluid is suitable for further service.
01/28/14	Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the component. The condition of oil is suitable for further service.
03/14/13	The fluid appears to be in excellent condition, in all aspects. Suitabel for further use.
03/09/12	The oil condition appears to be most definitely suitable for further use based on these results. We will set reminders to sample every 6-9 months.
04/25/10	Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the component. The condition of oil is suitable for further service.

Petro-Canada makes no representation or warranty of any kind, either express or implied, as to the accuracy or completeness of the analysis and assumes no responsibility and shall have no liability whatsoever with respect to such analysis, or a party's use of it. Petro-Canada is a division of HollyFrontier Corporation.