

VTA HOT OIL PUMP

Customer: PTRHTF10004

ADM VITAMIN E PLANT 3700 EAST DIVISION STREET DECATUR, IL 62526 USA

Attn: Rick Cluck Tel: (217)451-7770

E-Mail: ricky.cluck@adm.com

System Information

System Volume: 1800 gal

Bulk Operating Temp: 650F / 343C

Heating Source:

Blanket:

Fluid: PETRO CANADA PURITY FG HEAT TRANSFER FLUID

Make: AMERICAN HEATING

Sample Information


Lab No: 02353746 Analyst: Joe Goecke Sample Date: 05/08/20 Received Date: 05/13/20 Completed: 05/21/20


Joe Goecke


Joe.goecke@petrocanadalsp.com

Recommendation: Viscosity is good, and although the flash point is lower than new it is still in an acceptable range for operating and the low boilers are less than 10%. Continue to operate and resample in 60-90 days.

Comments: COC Flash Point is abnormally low. (GCD) % < 335°C is marginally high. (GCD) 10% Distillation Point is marginally low.









Sample Date	Iron	Chromium	Nickel	Aluminum	Copper	Lead	Tin	Cadmium	Silver	Vanadium	Silicon	Sodium	Potassium	Titanium	Molybdenum	Antimony	Manganese	Lithium	Boron	Magnesium	Calcium	Barium	Phosphorus	Zinc
05/08/20	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	30	0
11/13/19	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	43	0
05/14/19	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	48	0
10/11/18	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	22	0
09/20/18	1	0	0	0	0	0	4	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	56	0
Baseline Data			0	0						0			0	0					0				230	
Baseline Data		/ مداد					III:	([10			1 00/		0					0				230	

Elemental analysis results (above) in parts per million (ppm). [10,000 ppm = 1.0%]





	Historical Comments
11/13/19	Viscosity is still low and flash point has decreased I suggest planning a change or partial change to get the system in better condition within the next 45 days. (GCD) 10% Distillation Point is severely low. COC Flash Point is severely low. Visc @ 40°C is severely low. (GCD) % < 335°C is abnormally high.
05/14/19	This system is extremely low on viscosity at 12.2 cSt. Flash point is over 100 degrees C less than a fresh charge and the low boilers are over 14%. I recommend planning a change of this oil soon since venting is currently not an option. Heat transfer ability and safety are main concerns. (GCD) 10% Distillation Point is severely low. COC Flash Point is severely low. Visc @ 40°C is severely low. (GCD) % < 335°C is abnormally high.
10/11/18	System much better. Flash point still a little low, but 30 Degrees C higher than before. GCD points all looking better. Continue to use and resample in 60 days. COC Flash Point is severely low.
09/20/18	Viscosity is half of new oil, Flash point is extremely low, low boilers are very high at 17.8% 10% distillation point also very low at 261.8C. This heat transfer efficacy of this oil is going to suffer. Oil needs to be changed ASAP to improve safety of operation. (GCD) % < 335°C is severely high. (GCD) 10% Distillation Point is severely low. COC Flash Point is severely low. Visc @ 40°C is severely low.

Petro-Canada makes no representation or warranty of any kind, either express or implied, as to the accuracy or completeness of the analysis and assumes no responsibility and shall have no liability whatsoever with respect to such analysis, or a party's use of it. Petro-Canada is a division of HollyFrontier Corporation.