



SOUTH HEATER

Customer: PTRHTF10043

MALARKY ROOFING PRODUCTS 3131 N. COLUMBIA BLVD PORTLAND, OR 97217 USA Attn: SCOTT MCDANIEL

Tel: (503)283-1191

E-Mail: smcdaniel@malarkeyroofing.com

System Information

System Volume: 1200 gal

Bulk Operating Temp: 620F / 327C

Heating Source:

Blanket:

Fluid: PETRO CANADA CALFLO HTF

Make: AMERICAN HEATING

Sample Information


Lab No: 02356544 Analyst: Ron LeBlanc Sample Date: 03/15/20 Received Date: 05/29/20 Completed: 06/01/20


Ron LeBlanc


Ronald.LeBlancSr@petrocanadalsp.com


Recommendation: COC Flash Point is very low. A low flash point can indicate thermal degradation. Add new oil to bring up Flash Point. (GCD) % < 335°C is marginally high. Make sure the oil was purged before collection into the sample container to get the best sample.

Comments: COC Flash Point is severely low. (GCD) % < 335°C is marginally high.
















| Sample Date | Iron | Chromium | Nickel | Aluminum | Copper | Lead | Tin | Cadmium | Silver | Vanadium | Silicon | Sodium | Potassium | Titanium | Molybdenum | Antimony | Manganese | Lithium | Boron | Magnesium | Calcium | Barium | Phosphorus | Zinc |
|---------------|------|----------|--------|----------|--------|------|-----|---------|--------|----------|---------|--------|-----------|----------|------------|----------|-----------|---------|-------|-----------|---------|--------|------------|------|
| 03/15/20 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 13 | 0 |
| 08/09/19 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 16 | 0 |
| 05/09/19 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 17 | 0 |
| 02/04/19 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 18 | 0 |
| 07/26/18 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 25 | 0 |
| | | | | | | | | | | | | | | | | | | | | | | | | |
| Baseline Data | | | 0 | 0 | | | | | | 0 | | | 0 | 0 | | | | | 0 | | | | 280 | |

Elemental analysis results (above) in parts per million (ppm). [10,000 ppm = 1.0%]





| | Historical Comments |
|----------|--|
| 08/09/19 | COC Flash point came up from the previous sample. (GCD) 90% point is marginally low. Resample in 3 months. COC Flash Point is marginally low. (GCD) 90% Distillation Point is marginally low. |
| 05/09/19 | Flash point is lower than normal. If possible add new oil to bring flash point up. COC Flash Point is severely low. |
| 02/04/19 | COC Flash Point is elevated. Re-sample in 3 months to check results again. Purge 1/2 gallon of oil before sample is drawn. COC Flash Point is severely low. (GCD) 90% Distillation Point is marginally low. |
| 07/26/18 | Viscosity has dropped from ISO 32 to ISO 22. COC flash point has lowered significantly to a point that should be corrected. Determine what is affecting viscosity. Has there been a heater issue of late causing oil to overheat severely. New oil might need to be added to bring COC flash point up if no other issue is found. (GCD) 90% Distillation Point is severely low. COC Flash Point is severely low. |
| | |

Petro-Canada makes no representation or warranty of any kind, either express or implied, as to the accuracy or completeness of the analysis and assumes no responsibility and shall have no liability whatsoever with respect to such analysis, or a party's use of it. Petro-Canada is a division of HollyFrontier Corporation.