


Recommendation: The fluid is contaminated with excess water (6552 ppm and 1% emulsified water). If this sample is representative, there is risk of boil-over once put into service. High water content also is a catalyst for fluid oxidation and additive hydrolysis. It is advised to remove water from the fluid before use and before long-term storage. 5% low boiling vapor content, reduce flashpoint and fluid viscosity likely indicate mixing with process hydrocarbon if not from thermal degradation. This fluid would need to be vented once in service to remove low boiling vapors.


Clinton.Buhler@hollyfrontier.com

E-Mail: Iain Hamilton@keyera.com

Comments: Water contamination levels are severely high. Water contamination levels are severely high.. ppm Water contamination levels are severely high. COC Flash Point is abnormally low.

Sample Date	Received Date	Fluid Age	Sample Location	Flash Point (COC)	Water (KF)	Viscosity (40°C)	Acid Number	Solids	GCD 10%	GCD 50%	GCD 90%	GCD % < 335°C
	mm/dd/yy			°F/°C	ppm	cSt	mg/KOH/ g	%wt	°F/°C	°F/°C	°F/°C	%
05/18/21	06/08/21	0.0h	Truck 1 - delivery	352 / 178	6552.4	29.2	0.04	0.013	688 / 365	793 / 423	902 / 484	5.03





Petro-Canada makes no representation or warranty of any kind, either express or implied, as to the accuracy or completeness of the analysis and assumes no responsibility and shall have no liability whatsoever with respect to such analysis, or a party's use of it. Petro-Canada is a division of HollyFrontier Corporation.

Report ID: [02425930] (Generated: 06/14/2021 16:04:16) - Page 2 - Copyright 2021 Wearcheck Inc. All Rights Reserved.