


WANSON EPC 2500 ES

Customer: PTRHTF40020	System Information	Sample Information
LE DUC FINE FOOD BV	System Volume: 1500 ltr	Lab No: 02470762
MEESTER SNIJDERWEG 18	Bulk Operating Temp: 265F / 129C	Analyst: Luis Rodriguez
ZUID-HOLLAND	Heating Source:	Sample Date: 02/03/22
STELLENDAM, ZUI NETHERLANDS	Blanket:	Received Date: 02/08/22
Attn: Wilbert Snijers	Fluid: PETRO CANADA PURITY FG HEAT TRANSFER FLUID	Completed: 02/18/22
Tel:	Make: WANSON	Luis Rodriguez
E-Mail: w.snijers@klt.nl		luis.rodriguez@hollyfrontier.com


Recommendation: Flash point redone. Although the parameters of the HTF are very constant during the last year the flash point has dropped and is still abnormally low. Levels of low weight hydrocarbons recommend to monitor the low boilers and continue to perform venting, that may help to recover the flash point.

Comments: COC Flash Point is severely low.


Sample Date	Received Date	Fluid Age	Sample Location	Flash Point (COC)	Water (KF)	Viscosity (40°C)	Acid Number	Solids	GCD 10%	GCD 50%	GCD 90%	GCD % < 335°C
	mm/dd/yy			°F/°C	ppm	cSt	mg/KOH/ g	%wt	°F/°C	°F/°C	°F/°C	%
02/03/22	02/08/22	7.3y		309 / 154	14.2	28.9	0.38	0.186	679 / 360	804 / 429	903 / 484	6.46
06/15/21	06/18/21	6.8y		349 / 176	15.4	29.0	0.33	0.105	694 / 368	806 / 430	906 / 486	5.22
12/04/20	12/11/20	6.3y		345 / 174	11.3	29.3	0.39	0.162	692 / 367	805 / 430	903 / 484	5.28
06/02/20	06/09/20	5.8y		360 / 182	55.0	29.5	0.41	0.289	683 / 362	804 / 429	906 / 486	5.79
10/12/19	12/23/19	5.3y		351 / 177	40.4	30.0	0.494	0.304	698 / 370	789 / 421	884 / 473	2.29







Resp



Historical Comments

06/15/21	Although the parameters of the HTF are very constant during the last year the flash point continues to be severely low. Levels of low weight hydrocarbons recommend to monitor the low boilers and do some venting, that may help to recover the flash point. COC Flash Point is severely low.
12/04/20	Flash Point is severely low, but GCD % <335 is still on an acceptable level. Monitor trend and take action if number of low boilers further increase and flash point further decreases.
06/02/20	No action required. Send in next oil sample in 6-12 month. COC Flash Point is slightly low.
10/12/19	Going through the history of this sample it raises some concerns. In this current sample there has been a loss in viscosity of 10cSt from previous, and a significant drop in flash point to a level that is severely low. The curve shows a little evidence of cracking, but levels of low weight hydrocarbons look fairly low. SOme venting, if it can be done safely, may recover the flash point. I would attempt safe venting and re-sample. If it cannot be done a confirmation or another sample would be recommended as the step downwards in viscosity and flash point shows a worrying trend. COC Flash Point is severely low.

Petro-Canada makes no representation or warranty of any kind, either express or implied, as to the accuracy or completeness of the analysis and assumes no responsibility and shall have no liability whatsoever with respect to such analysis, or a party's use of it. Petro-Canada is a division of HollyFrontier Corporation.