## CONSTRUCTION EQUIPMENT

#### LIEBHERR L538P 063547-1754 - Diesel Engine

Sample No: LH0269550

Oil Type: NOT GIVEN

### **SAMPLE INFORMATION**

Sample Number	LH0269550	 	
Sample Date	31 Jul 2023	 	
Machine Hours	1175	 	
Oil Hours	0	 	
Oil Changed	N/A	 	
Sample Status	ABNORMAL	 	

OIL CONI	DITION		
Visc @ 100°C cSt	<b>O</b> 11.5	 	
Oxidation (PA) %	72	 	

Soot %	%	0				
Nitration (PA)	%	76				
Sulfation (PA)	%	57				
Glycol	%	NEG				
Fuel	%	<mark>)</mark> 2				
Silicon	ppm	06				
Sodium	ppm	0 5				
Potassium	ppm	01				

#### WEAR METALS

Iron	ppm	0 11	 	
Copper	ppm	<b>23</b>	 	
Lead	ppm	01	 	
Tin	ppm	<b>○</b> <1	 	
Aluminum	ppm	02	 	
Chromium	ppm	<b>○</b> <1	 	
Molybdenum	ppm	0 78	 	
Nickel	ppm	0 🔘	 	
Titanium	ppm	0	 	
Silver	ppm	0 🔘	 	
Manganese	ppm	<1	 	
Vanadium	ppm	0	 	

	VIIIVES			
Calcium	ppm	<b>911</b>	 	
Magnesium	ppm	0 1218	 	
Zinc	ppm	0 1260	 	
Phosphorus	ppm	0 1168	 	
Barium	ppm	0	 	
Boron	ppm	0 57	 	





HEFLER FOREST PRODUCTS - 4325842 NS LTD. 230 LUCASVILLE RD. LOWER SACKVILLE, NS CA B4B 1S1 Contact: Service Manager

#### T: F:

#### Diagnosis

Resample at the next service interval to monitor. Please specify the brand, type, and viscosity of the oil on your next sample.All component wear rates are normal. Light fuel dilution occurring. Fuel is present in the oil and is lowering the viscosity. The condition of the oil is acceptable for the time in service.

Depot: Unique No: Signed: Report Date: HEFLOW 5618423 Wes Davis 02 Aug 2023

Report Id: HEFLOW [WCAMIS] 02573372 (Generated: 08/29/2023 11:14:25) Rev: 1

# CONSTRUCTION EQUIPMENT



GRAPHS

 $\odot$ 

