CONSTRUCTION EQUIPMENT

[(347073)] LIEBHERR R966 048149-1535 - Diesel Engine

Sample No: LH0274609

Oil Type: NOT GIVEN

SAMPLE INFORMATION

Sample Number	LH0274609	LH	
Sample Date	14 Sep 2023	20 Jan 2022	
Machine Hours	1959	637	
Oil Hours	0	0	
Oil Changed	Changed	Changed	
Sample Status	NORMAL	ABNORMAL	

OILCO	NULLION			
Visc @ 100°C	cSt	11.0	0 11.5	
Oxidation (PA)	%	73	115	

CON'	TAMIN	ATION		
Soot %	%	0	00	
Nitration (PA)	%	69	57	
Sulfation (PA)	%	58	76	
Glycol	%	NEG	NEG	
Fuel	%	01	0.6	
Silicon	ppm	04	○ 20	
Sodium	ppm	02	3	
Potassium	ppm	3	0 4	

WEAR METALS

Iron	ppm	0 10	0 19	
Copper	ppm	0 217	○ 392	
Lead	ppm	06	0 13	
Tin	ppm	0 🔘	○ <1	
Aluminum	ppm	02	2	
Chromium	ppm	◯ <1	○ <1	
Molybdenum	ppm	0 45	0 45	
Nickel	ppm	0 🔘	0	
Titanium	ppm	0	<1	
Silver	ppm	◯ <1	<1	
Manganese	ppm	<1	3	
Vanadium	ppm	0	0	

ADDITIVES

Calcium	ppm	0 1346	0 1392	 	
Magnesium	ppm	○ 716	○ 900	 	
Zinc	ppm	0 1137	929	 	
Phosphorus	ppm	952	0 802	 	
Barium	ppm	0 2	29	 	
Boron	ppm	23	94	 	





Zancon Holdings Inc.

415 Warren Road King City, ON CA L7B 1C4 Contact: Frank Provenzano fprovenzano@zanconenv.com T: (416)990-4582 F:

Diagnosis

The oil change at the time of sampling has been noted. Resample at the next service interval to monitor. No other corrective action is recommended at this time. Please specify the brand, type, and viscosity of the oil on your next sample.All component wear rates are normal. Light fuel dilution occurring. No other contaminants were detected in the oil. The condition of the oil is acceptable for the time in service.

Depot: Unique No: Signed: Report Date: ZANKIN 5643751 Bill Quesnel 18 Sep 2023

CONSTRUCTION EQUIPMENT



GRAPHS

 \odot

