CONSTRUCTION EQUIPMENT

LIEBHERR LH50M 110456-1216 - Front Left Wheel Hub

Sample No: LH0278421

Oil Type:

PETRO CANADA TRAXON 75W90 SYNTHETIC

-					
	PLE INF	ORMATION			
Sample Number		LH0278421	LH0277111	LH0234607	LH0246691
Sample Date		29 Jan 2024	13 Oct 2023	01 Apr 2023	15 Dec 2022
Machine Hours		18585	17581	16012	0
Oil Hours		0	0	0	0
Oil Changed		Changed	Changed	Changed	N/A
Sample Status		ABNORMAL	NORMAL	NORMAL	NORMAL
OIL CO	ONDITI	ON			
Visc @ 40°C	cSt	96.9	94.4	0 101	0 100
	AMIN/	TION			

	ITAMIN/	ATION				
Water	%	0.493	NEG	NEG	NEG	
Silicon	ppm	0 2	0 2	03	2	
Sodium	ppm	0 2	2	◯ <1	◯ <1	
Potassium	ppm	01	0	◯ <1	0	

Ä					
WEA WEA	R METAL	.S			
Iron	ppm	3 0	64	23	24
Copper	ppm	03	○ 5	0 4	6
Lead	ppm	0 ()	◯ <1	0	0
Tin	ppm	0 ()	0	0 ()	0
Aluminum	ppm	○ <1	○ <1	◯ <1	◯ <1
Chromium	ppm	0 ()	0	0 ()	0
Molybdenum	ppm	0 ()	0	0	0
Nickel	ppm	◯ <1	0	0	0
Titanium	ppm	0	0	0	0
Silver	ppm	0 ()	○ <1	0	0
Manganese	ppm	0	0	◯ <1	◯ <1
Vanadium	ppm	0	0	0	0



ADDI	TIVES				
Calcium	ppm	0 14	22	62	0 12
Magnesium	ppm	01	2	2	01
Zinc	ppm	36	72	37	0 19
Phosphorus	ppm	914	0 1214	1328	0 1306
Barium	ppm	0	○ <1	0	0
Boron	ppm	0 214	286	313	317



J.D. Irving

Truro Sawmill, 529 Valley Dale Road Truro, NS CA B2N 5C5 Contact: Sheldon Richardson richardson.sheldon@jdirving.com T: (902)890-9419 F:

Diagnosis

We advise that you check for the source of water entry. The oil change at the time of sampling has been noted. We recommend an early resample to monitor this condition.All component wear rates are normal. There is a moderate concentration of water present in the oil. The oil is no longer serviceable due to the presence of contaminants.

J
61
Mar
20

23861 vin Marson Feb 2024





GRAPHS

0

