\mathbf{R} E **CONSTRUCTION EQUIPMENT**

[(355228) [50241076]] LIEBHERR LH60M 114198-1217 - Rear Left W

Sample No: LH0290542

Oil Type:

PETRO CANADA TRAXON 75W90 SYNTHETIC

Sample Inf	ormation			
Sample Number	LH0290542	LH0225128	LH0250389	
Sample Date	11 Jul 2024	07 Dec 2023	22 Sep 2023	
Machine Hours	10000	8004	7355	
Oil Hours	0	0	0	
Oil Changed	Changed	Changed	Changed	
Sample Status	SEVERE	NORMAL	NORMAL	
Oil Conditio	on			
Visc @ 40°C cSt	0 104	0 102	0 104	

Con	ntaminati	on			
Water	%	NEG	NEG	NEG	
Silicon	ppm	0 176	01	02	
Sodium	ppm	◯ <1	◯ <1	◯ <1	
Potassium	ppm	○ <1	○ <1	○ <1	

Ä					
Wea	r Metals	;			
Iron	ppm	0 10	6	0 12	
Copper	ppm	04	○ 5	0 14	
Lead	ppm	0 🔘	0	◯ <1	
Tin	ppm	0 🔘	0	0	
Aluminum	ppm	○ <1	◯ <1	0	
Chromium	ppm	0 🔘	0	0	
Molybdenum	ppm	0 🔘	0	0	
Nickel	ppm	◯ <1	○ <1	0	
Titanium	ppm	0 🔘	0	0	
Silver	ppm	0	0	<1	
Manganese	ppm	○ <1	0	0	
Vanadium	ppm	0	0	0	

Add Add	mves				
Calcium	ppm	0 10	36	6	
Magnesium	ppm	0 2	○ <1	0 1	
Zinc	ppm	0 10	25	0 14	
Phosphorus	ppm	0 1251	0 1233	0 1263	
Barium	ppm	○ <1	0	◯ <1	
Boron	ppm	0 308	◯ 306	315	



AltaSteel

9401 34 St NW Edmonton, AB CA T6B 2X6 Contact: Richard Bailey richard.bailey@altasteel.com T: F:

Diagnosis

We advise that you check all areas where dirt can enter the system. The oil change at the time of sampling has been noted. We recommend an early resample to monitor this condition.All component wear rates are normal. High concentration of dirt present in the oil. The oil is no longer serviceable due to the presence of contaminants.

Depot: Unique No: Signed: **Report Date:**

ALT940EDM 5814329 Kevin Marson 19 Jul 2024 Submitted By: ?





Ø

Graphs

