CONSTRUCTION EQUIPMENT

LIEBHERR A918 110890-1184 - Swing Drive

Changed

ABNORMAL

Sample No: LHMC130924

Oil Type:	NOT GIVEN			
Ō SAMI	PLE INFOR <i>N</i>	MATION		
Sample Number		LHMC130924	 	
Sample Date		16 Sep 2023	 	 ı
Machine Hours		3968	 	 •
Oil Hours		0	 	 (



UNITED SCRAP 1545 S CICERO AVE CHICAGO, IL US 60804 Contact:

Т	:	
F		

OIL CO	ONDITION			
40°C	cSt	157	 	

Visc @	40°C	cSt
44		

Oil Changed

Boron

Sample Status

CONT	AMINATIO	ON		
Water	%	0.427	 	
Silicon	ppm	3	 	
Sodium	ppm	0	 	
Potassium	ppm	○ <1	 	

WEA	R METALS	5		
Iron	ppm	277	 	
Copper	ppm	15	 	
Lead	ppm	0	 	
Tin	ppm	0 <1	 	
Aluminum	ppm	() <1	 	
Chromium	ppm	3	 	
Molybdenum	ppm	<1	 	
Nickel	ppm	○ <1	 	
Titanium	ppm	0	 	
Silver	ppm	0	 	
Manganese	ppm	2	 	
Vanadium	ppm	0	 	
-				

Molybdenum	ppm	<1	 	
Nickel	ppm	0 <1	 	
Titanium	ppm	0	 	
Silver	ppm	0	 	
Manganese	ppm	2	 	
Vanadium	ppm	0	 	
ADDI	TIVES			
Calcium	P pm	10	 	
		10 <1	 	
Calcium	ppm			
Calcium Magnesium	ppm ppm	<1	 	

Diagnosis

We advise that you check for the source of water entry. The oil change at the time of sampling has been noted. We advise that you inspect for the source(s) of metal. Resample at the next service interval to monitor. High concentration of visible metal present. All component wear rates are normal. There is a moderate concentration of water present in the oil. The condition of the oil is acceptable for the time in service.

Depot: UNICHILH Unique No: 10672334 Signed: Don Baldridge **Report Date:** 03 Oct 2023





GRAPHS

