CONSTRUCTION EQUIPMENT



LIEBHERR LR1250.1 LH35298 (S/N 135.298) - Rear Gearbox

Sample No: LH0258467

Oil Type: SAE 30W

Sample Information

Sample Number	LH0258467					
Sample Date	16 Apr 2024					
Machine Hours	3348					
Oil Hours	1311					
Oil Changed	Not Changd					
Sample Status	ABNORMAL					
Oil Condition						

UII Condition

Visc @ 40°C - 1

cSt

0 171

Cont	aminati	on		
Water	%	NEG	 	
Silicon	ppm	0 2	 	
Sodium	ppm	2	 	
Potassium	ppm	0 ()	 	

Ä				
Wea	r Metals			
Iron	ppm	274	 	
Copper	ppm	0 2	 	
Lead	ppm	0	 	
Tin	ppm	00	 	
Aluminum	ppm	0 <1	 	
Chromium	ppm	04	 	
Molybdenum	ppm	5	 	
Nickel	ppm	02	 	
Titanium	ppm	○ <1	 	
Silver	ppm	0	 	
Manganese	ppm	04	 	
Vanadium	ppm	0	 	

٥ **Additives** Calcium ppm 0 155 Magnesium ppm 0 22 Zinc 0 164 ppm **690** Phosphorus ppm Barium ◯ <1 ppm Boron ppm 0 17



KINDER MORGAN

4301 IVERSON TRINITY, AL US 35601 Contact: RICKY JOHNSON ricky_johnson@kindermorgan.com T: F: (256)355-5250

Diagnosis

Resample at the next service interval to monitor.Gear wear is indicated. There is no indication of any contamination in the oil. The oil viscosity is higher than normal. This plus the additive levels indicates the addition of a different brand, or type of oil. Confirm oil type.


Depot: KINTRI Unique No: 11031836 Signed: Don Baldridge **Report Date:** 17 May 2024 Contact/Location: RICKY JOHNSON - KINTRI

CONSTRUCTION EQUIPMENT



O

Graphs



Apr16/24

90

80. 70 Apr16/24.

Abnormal