

LIEBHERR

CONSTRUCTION EQUIPMENT



LIEBHERR L550 059181-1756 - Front Left Wheel Hub

Sample No: LH0245756

Oil Type: SHELL SPIRAX HD 80W90



INFORMATION SUR L'ÉCHANTILLON

Numéro d'échant.	LH0245756	LH0221710	---	---
Date d'échant.	27 Sep 2023	05 Oct 2022	---	---
Heures de la Machine	3336	1026	---	---
Heures de l'huile	0	0	---	---
Huile changée	Changed	Changed	---	---
Statut de l'échant.	ABNORMAL	NORMAL	---	---

AV Terrace Bay Inc.

21 Mill Rd.

Terrace Bay, ON

CA P0T 2W0

Contact: Naqshe Iqbal

naqshe.iqbal@adityabirla.com

T: (807)823-0761

F:



ÉTAT D'HUILE

Visc 40°C	cSt	176	53.6	---	---
-----------	-----	-----	------	-----	-----



CONTAMINATION

Silicium	ppm	8	13	---	---
Sodium	ppm	8	21	---	---
Potassium	ppm	<1	<1	---	---



MÉTAUX D'USURE

Fer	ppm	240	167	---	---
Cuivre	ppm	52	44	---	---
Plomb	ppm	1	2	---	---
Étain	ppm	2	2	---	---
Aluminium	ppm	2	3	---	---
Chrome	ppm	2	2	---	---
Molybdène	ppm	34	20	---	---
Nickel	ppm	2	2	---	---
Titane	ppm	0	<1	---	---
Argent	ppm	<1	0	---	---
Manganèse	ppm	26	56	---	---
Vanadium	ppm	0	0	---	---



ADDITIFS

Calcium	ppm	356	3739	---	---
Magnésium	ppm	6	10	---	---
Zinc	ppm	108	1414	---	---
Phosphore	ppm	2107	1271	---	---
Baryum	ppm	<1	1	---	---
Bore	ppm	8	107	---	---

Diagnostic

The oil change at the time of sampling has been noted. Confirm the source of the lubricant being utilized for top-up/fill. We recommend an early resample to monitor this condition. Copper ppm levels are abnormal. Bearing and/or bushing wear is indicated. There is no indication of any contamination in the oil. Additive levels indicate the addition of a different brand, or type of oil. The oil is no longer serviceable as a result of the abnormal and/or severe wear.

Depot: AVTTER

Unique No: 5658031

Signed: Kevin Marson

Report Date: 16 Oct 2023



GRAPHS

