

# LIEBHERR L550 059181-1756 - Rear Right Wheel Hub

Sample No: LH0245759

Oil Type: SHELL SPIRAX HD 80W90

## **INFORMATION SUR L'ÉCHANTILLON**

Numéro d'échant.
Date d'échant.
Heures de la Machine
Heures de l'huile
Huile changée
Statut de l'echant.

chant.	LH0245759
int.	27 Sep 2023
Machine	3336
'huile	0
lée	Changed
chant.	NORMAL

0 169



## ÉTAT D'HUILE

Visc 40°C

cSt

# CONTAMINATION

Silicium	ppm	04		 
Sodium	ppm	<b>3</b>		 
Potassium	ppm	<b>○</b> <1		 

\_\_\_\_

Mél Mél	raux d'u	JSURE		
Fer	ppm	90	 	
Cuivre	ppm	0 21	 	
Plomb	ppm	<b>○</b> <1	 	
Étain	ppm	<1	 	
Aluminium	ppm	◯ <1	 	
Chrome	ppm	<b>○</b> <1	 	
Molybdène	ppm	0 13	 	
Nickel	ppm	<b>○</b> <1	 	
Titane	ppm	0	 	
Argent	ppm	<1	 	
Manganèse	ppm	08	 	
Vanadium	maa	0	 	

#### 0 **ADDITIFS** Calcium 464 ppm Magnésium ppm 02 Zinc 187 ppm 0 750 Phosphore ppm Baryum ppm ◯ <1 Bore 13 ppm





## AV Terrace Bay Inc.

21 Mill Rd. Terrace Bay, ON CA P0T 2W0 Contact: Naqshe lqbal naqshe.iqbal@adityabirla.com T: (807)823-0761 F:

## Diagnostic

Confirm the source of the lubricant being utilized for top-up/fill. Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. Additive levels indicate the addition of a different brand, or type of oil. The condition of the oil is acceptable for the time in service.

Depot:AVUnique No:56Signed:KeReport Date:16


### AVTTER 5658053 Kevin Marson 16 Oct 2023





GRAPHS

 $\odot$ 



ID du rapport: AVTTER [WCAMIS] 02588987 (Generated: 10/16/2023 09:18:47) Rev: 1