## BHERR E **CONSTRUCTION EQUIPMENT**

### LIEBHERR LH50M 150728-1216 - Swing Drive

PETRO CANADA TRAXON SYNTHETIC 75W90

Sample No: LH0242068

**Oil Type:** 

| INFORM/ | <b>ATION SUR</b> | <b>L'éCHAN</b> | TILLON |
|---------|------------------|----------------|--------|

500

LH0242068

21 Nov 2023 500

Changed

NORMAL

179

| Numéro d'échant.     |  |  |
|----------------------|--|--|
| Date d'échant.       |  |  |
| Heures de la Machine |  |  |
| Heures de l'huile    |  |  |
| Huile changée        |  |  |

Statut de l'echant.

ÉTAT D'HUILE

Visc 40°C . .

# cSt

|           |               |             |      | _ |
|-----------|---------------|-------------|------|---|
| CON1      | <b>FAMINA</b> | TION        |      |   |
| Eau       | %             | NEG         | <br> |   |
| Silicium  | ppm           | 04          | <br> |   |
| Sodium    | ppm           | 03          | <br> |   |
| Potassium | ppm           | <b>○</b> <1 | <br> |   |

| Ä         |          |                  |      |  |
|-----------|----------|------------------|------|--|
| W Mét     | AUX D'US | URF              |      |  |
|           |          |                  |      |  |
| Fer       | ppm      | <b>0</b> 167     | <br> |  |
| Cuivre    | ppm      | 0 83             | <br> |  |
| Plomb     | ppm      | 02               | <br> |  |
| Étain     | ppm      | 0 5              | <br> |  |
| Aluminium | ppm      | <b>○</b> <1      | <br> |  |
| Chrome    | ppm      | <mark></mark> <1 | <br> |  |
| Molybdène | ppm      | 0 🔘              | <br> |  |
| Nickel    | ppm      | <mark></mark> <1 | <br> |  |
| Titane    | ppm      | 0                | <br> |  |
| Argent    | ppm      | <1               | <br> |  |
| Manganèse | ppm      | 02               | <br> |  |
| Vanadium  | ppm      | 0                | <br> |  |

0 **ADDITIFS** Calcium 0 22 ppm Magnésium 01 ppm Zinc 25 ppm Phosphore ppm 2021 Baryum 07 ppm Bore ppm 23





### ABC RECYCLING

750C JACKSON RD NANAIMO, BC CA V9X 1J2 Contact: Jordie Richmond jordie.richmond@abcrecycling.com T: (250)202-8235 F:

### Diagnostic

Confirm the source of the lubricant being utilized for top-up/fill. Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. Additive levels indicate the addition of a different brand, or type of oil. The condition of the oil is acceptable for the time in service.


| Depot:       | ABCNAN      |
|--------------|-------------|
| Unique No:   | 5684404     |
| Signed:      | Wes Davis   |
| Report Date: | 28 Nov 2023 |





GRAPHS

 $\overline{\mathbf{O}}$ 



ID du rapport: ABCNAN [WCAMIS] 02599324 (Generated: 12/07/2023 13:33:43) Rev: 1

Submitted By: Jordie Richmond